

# UST NOVs - 2014

Site Town(s)	Site Name(s)	Site Address(es)	Status	Action Date	Enf Action Comment	Number Violations	Affil Last Name	Open in SIMS
GUILFORD	DELI UNLIMITED	1099 BOSTON POST RD GUILFORD, CT 06437	Closed	6/2/2014	Site submitted notification form recd 12/19/14 stating tanks a-1, b-1. c-1 were removed on 10/1/14 by Michael Orsini DBA Enviro-Site, LLC 203-915-1286. Closure report attached, forwarded to sas on 1/13/14. Site also submitted A/B Operator training information dated 8/26/14 for Alexander Oranzo, Certificate of Liability Insurance from CPM Insurance Services, passing tank tightness testing results and passing line tightness testing for three tanks	9	1099 LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159752&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159752&amp;type=ENFORCEMENT_ACTION</a>
CENTERBROOK	Centerbrook Shell	23 MAIN ST CENTERBROOK, CT 06409	Active	8/6/2014	Equipment is not capable of one-eighth of an inch measurement.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. The UST system is in operation or is temporarily out-of-service without the requisit...	11	23 MAIN STREET, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164500&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164500&amp;type=ENFORCEMENT_ACTION</a>

GREENWICH	CARRIAGE HOUSE MOTOR CARS	25 RAILROAD AVE GREENWICH, CT 06830	Closed	4/23/2014	Daily measurements to the nearest one-eighth of an inch were not made for any water level in the bottom of the tank. . The date and measurements of oil and water level at the beginning and ending of at least a 36-hour idle period were not recorded. . The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. 4/28/14 Inspection by Mike Cosker passed. Site is SOC. Open NOV being closed.	5	25 RAILROAD AVENUE LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155696&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155696&amp;type=ENFORCEMENT_ACTION</a>
DANBURY	J&R Bussiness Group, LLC	282 WHITE ST DANBURY, CT 06810	Active	5/30/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. No Notice of Financial Responsibility on site.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The release detection documentation was not available.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	6	282 WHITE STREET LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164321&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164321&amp;type=ENFORCEMENT_ACTION</a>
WINSTED	WINSTED GULF	29 MAIN ST WINSTED, CT 06098	Closed	9/3/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. See email from Harold Zino dated 9/9/14. Cleaned sumps 9/4/14. Issued directive to gas haulers that they are to be notified at time of delivery if there is any water in their sumps. Operator re-training violation voided by Peter Zack.	3	29 MAIN - WINSTED, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166308&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166308&amp;type=ENFORCEMENT_ACTION</a>
WATERFORD	BAYVIEW HEALTH CARE CENTER	301 ROPE FERRY RD WATERFORD, CT 06385	Active	6/30/2014	Failure to have required financial responsibility in the required amount(s).. Spill containment device was not present.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	3	301 ROPE FERRY RD,C LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162296&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162296&amp;type=ENFORCEMENT_ACTION</a>

HARTFORD	Capital Shell Food Mart, Inc.	335 CAPITOL AVE HARTFORD, CT 06106	Active	3/18/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump..	6	335 CAPITOL AVENUE, L.L.C.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152331&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152331&amp;type=ENFORCEMENT_ACTION</a>
ORANGE	LAMPOST CONVIENCE INC	340 BOSTON POST RD ORANGE, CT 06477	Closed	3/25/2014	A review of DEP records indicates that we do not have a registration form with current information.. Failure to have required financial responsibility in the required amount(s).. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. Received notification form w/ A/b operator information and fiscal mechanisms on 4/28/14.	3	340 BOSTON POST ROAD, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152930&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152930&amp;type=ENFORCEMENT_ACTION</a>
WEST HARTFORD	DANS OF WEST HARTFORD	456 NEW PARK AVE WEST HARTFORD, CT 06110	Active	4/29/2014	Release or discharge from a UST system.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. UST system discharged regulated substances to the environment without a permit..	7	456 NEW PARK AVENUE, L.L.C.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156304&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156304&amp;type=ENFORCEMENT_ACTION</a>

UNIONVILLE	7-ELEVEN #32528	70 S MAIN ST UNIONVILLE, CT 06085	Closed	6/4/2014	No Notice of Financial Responsibility on site.. The annual test documentation was not available for the piping leak monitoring equipment and devices. . The annual tightness test documentation was not available for the piping. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who hav...	19	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160044&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160044&amp;type=ENFORCEMENT_ACTION</a>
MOODUS	7-ELEVEN #32526	4 FALLS RD MOODUS, CT 06469	Closed	5/29/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. Contractor hired. Spill containment devices cleaned/repared. Sleeve installed. Metallic piping in stp sump is no longer in contact with soil/ground water.	6	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159419&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159419&amp;type=ENFORCEMENT_ACTION</a>
Uncasville	7-ELEVEN # 32641	2178 Norwich New London Tpke Uncasville, CT 06382	Closed	5/5/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The passing annual line leak detector test documentation was not maintained.. Per CROMPCO Monitoring System Certification 3/2/14, There was no liquid found in any secondary system designed as a dry system, all sensors were installed at the lowest point of the secondary containment and all monitoring equipment was operational and passed. Recd passing CROMPCO LLD on 6/17/14 dated 6/3/14	4	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156889&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156889&amp;type=ENFORCEMENT_ACTION</a>

NEW LONDON	7-ELEVEN #32518	283 BROAD ST NEW LONDON, CT 06320	Active	4/3/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The annual tightness test documentation was not available for the piping. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	18	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154004&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154004&amp;type=ENFORCEMENT_ACTION</a>
HAMDEN	7-ELEVEN #33307	1795 DIXWELL AVE HAMDEN, CT 06514	Active	4/2/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	3	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153837&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153837&amp;type=ENFORCEMENT_ACTION</a>
MERIDEN	7-ELEVEN #33206	329 CHAMBERLAIN HWY MERIDEN, CT 06451	Active	4/2/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	3	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153838&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153838&amp;type=ENFORCEMENT_ACTION</a>
ANDOVER	7-ELEVEN #32523	380 ROUTE 6 ANDOVER, CT 06232	Active	12/12/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. A review of DEP records indicates that we do not have a registration form with current information.. The owner or operator failed to submit to the Commissioner a statement signed by the installation contractor, certifying that the installation has been carried out in accordance with the UST Regulations. .	5	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145465&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145465&amp;type=ENFORCEMENT_ACTION</a>

PLAINFIELD	7-ELEVEN # 32515	65 MAIN ST PLAINFIELD, CT 06374	Active	10/24/2013	A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. ATG is not checking portion of the tank that routinely contains product (for some models, the tank level can be 14%).. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. There is one or more underground storage tank piping system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location..	18	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143009&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143009&amp;type=ENFORCEMENT_ACTION</a>
VERNON	7- ELEVEN STORE #22399	180 UNION ST VERNON, CT 06066	Closed	10/18/2013	The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. CROMPCO passing line tightness test & LLD test results	6	7-ELEVEN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142568&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142568&amp;type=ENFORCEMENT_ACTION</a>
DANBURY	JOHN'S AUTOMOTIVE	85 MILL PLAIN RD DANBURY, CT 06811	Active	8/5/2014	No Notice of Financial Responsibility on site.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual test documentation was not available for the piping leak monitoring equipment and devices. . The passing annual line leak detector test documentation was not maintained.. The passing annual line leak detector test had not been performed.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	9	85 MILL PLAIN ROAD, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164429&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164429&amp;type=ENFORCEMENT_ACTION</a>
WEST HARTFORD	WEST HARTFORD SUNOCO	956 NEW BRITAIN AVE WEST HARTFORD, CT 06110	Closed	11/5/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was closed by Kelly McShea on 11/14/13 as part of the NOV followup project.	2	956 NEW BRITAIN AVENUE, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143565&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143565&amp;type=ENFORCEMENT_ACTION</a>

BRANFORD	A & M SERVICE STATION	117 N MAIN ST BRANFORD, CT 06405	Closed	9/8/2014	The monthly release detection test documentation from the automatic tank gauging device was not available. . The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Received passing 0.2 test results for DF, super, reg, plus dated 10/9/14	3	A & M SERVICE STATION, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166298&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166298&amp;type=ENFORCEMENT_ACTION</a>
BRANFORD	BRANFORD GULF	380 E MAIN ST BRANFORD, CT 06405	Active	7/23/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The dispenser sump contains liquid.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information..	7	ABID, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163659&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163659&amp;type=ENFORCEMENT_ACTION</a>
HIGGANUM	QUICK STOP PETROL PLUS	110 SAYBROOK RD HIGGANUM, CT 06441	Active	6/18/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The dispenser sump contains liquid.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	6	ABID, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161544&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161544&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	EXPRESS FOOD MART A10	1195 N COLONY RD WALLINGFORD, CT 06492	Active	4/21/2014	Fittings were not cathodically protected.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	7	ABID, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155375&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155375&amp;type=ENFORCEMENT_ACTION</a>
MYSTIC	COLONIAL TIRE	1892 GOLD STAR HWY MYSTIC, CT 06355	Active	10/23/2013	A review of DEP records indicates that we do not have a registration form with current information.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	2	ACKLEY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142878&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142878&amp;type=ENFORCEMENT_ACTION</a>



BLOOMFIELD	Advanced Gas Company, Inc. (Citgo)	925 BLUE HILLS AVE BLOOMFIELD, CT 06002	Closed	5/20/2014	Recd CCMI UST System Testing Report recd 8/12/14, Tank Monitor Inspection passed, sensor installed at lowest point, no liquid was found in any secondary containment system, Product line tightness testing passed, mechanical I9ine leak detector testing passed, dispenser shear valve inspection passed, all monitoring equipment functional, Site submitted monthly visual inspection checklist, class a& b operator retraining certificates, passing 0.2 and liquid status normal atg reports submitted,	6	ADVANCED GAS CO., INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158529&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158529&amp;type=ENFORCEMENT_ACTION</a>
BLOOMFIELD	ADVANCED GAS CO., INC.	129 W DUDLEY TOWN RD BLOOMFIELD, CT 06002	Closed	5/15/2014	Monthly records of interstitial monitoring records were not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly,Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Site submitted monthly ust checklist, class A/B Operator Certificate for re-training, monthly interstitial monitoring report sensors normal, passing 0.2 test results	5	ADVANCED GAS CO., INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158471&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158471&amp;type=ENFORCEMENT_ACTION</a>
Norwalk	128 CONNECTICUT AVENUE, LLC	128 Connecticut Ave Norwalk, CT 06854	Closed	3/5/2014	The dispenser sump contains liquid.. The tanks cathodic protection was not operational, therefore, corrosion protection must be repaired or system permanently closed.. Inspection on 10/29/2014 by inspector Gary Bellmar. The inspection status was failed. 4 violation(s) found. new NOV Id: NOVUST-GB14-0144	2	AFENTOULIDES	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151327&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151327&amp;type=ENFORCEMENT_ACTION</a>



WINSTED	Singh's Convenience Plus	60 S MAIN ST WINSTED, CT 06098	Active	9/3/2014	Annual Tightness Test for Pressurized Piping was not performed.. Documentation of an annual passing cathodic protection test for piping was not available.. Monthly records of interstitial monitoring records were not available.. No Notice of Financial Responsibility on site.. Piping was repaired and no report of the repair was maintained.. Repaired piping was not tested.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual test documentation was not available for the piping leak monitoring equipment and devices. . The annual tightness test documentation was not available for the piping. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has fail...	44	Akaal Management, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166309&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166309&amp;type=ENFORCEMENT_ACTION</a>
SIMSBURY	AMERIGAS	125 WEST ST SIMSBURY, CT 06070	Closed	6/11/2014	Site removed fluid from spill buckets, Federal Oil Services collected 2 gals water with trace oil, Wildco PES replaced the regular and super adaptors, all functions tested and working properly, Recd statement of training for ust operators, forwarded to steu on 9/30/14, Submitted copies of monthly visual checklists	5	Akhtar	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160942&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160942&amp;type=ENFORCEMENT_ACTION</a>
KILLINGWORTH	KILLINGWORTH GARAGE, INC.	319 ROUTE 81 KILLINGWORTH, CT 06419	Closed	5/28/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Site submitted daily/weekly inventory control records on 6/6/14	3	Albrecht	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159226&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159226&amp;type=ENFORCEMENT_ACTION</a>
Brooklyn	BROOKLYN SUNOCO	500 Providence Rd Brooklyn, CT 06234	Closed	5/15/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. Aldin Associates maintenance department on site 5/16/14, liquid removed from dispenser sumps. Filters on dispensers 5&6 replaced. Photos attached. Class A Operators Certificate included dated 5/8/14	3	ALDIN ASSOCIATES LIMITED PARTNERSHIP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158202&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158202&amp;type=ENFORCEMENT_ACTION</a>

NEW MILFORD	Murphy Road Recycling, LLC	182 DANBURY RD NEW MILFORD, CT 06776	Closed	4/24/2014	A review of DEP records indicates that we do not have a registration form with current information.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. Registration form recd 5/8/14, financial mechanism information included, ACE, Illinois Union Insurance Co, 10/1/13-10/1/14	3	ALL AMERICAN WASTE, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155908&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155908&amp;type=ENFORCEMENT_ACTION</a>
MERIDEN	MOBIL R/S 10750	954 E MAIN ST MERIDEN, CT 06450	Closed	7/24/2014	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. Registration had been submitted 11/6/13, registering the new tanks installed in 2013 and had not yet been entered into ICM at time of inspection	1	ALLIANCE RETAIL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163691&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163691&amp;type=ENFORCEMENT_ACTION</a>
DURHAM	DURHAM SUNOCO	24 MAIN ST DURHAM, CT 06422	Closed	4/29/2014	A review of DEP records indicates that we do not have a registration form with current information.. NOV nullified by Peter Zack and Lori Saliby. A notification form had been submitted to DEEP.	1	ALLIANCE RETAIL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156306&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156306&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	MOBIL S/S #01-QRB R/S# 12470	779 JOHN FITCH BLVD SOUTH WINDSOR, CT 06074	Active	4/15/2014	A review of DEP records indicates that we do not have a registration form with current information.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	10	ALLIANCE RETAIL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155013&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155013&amp;type=ENFORCEMENT_ACTION</a>
MONROE	MOBIL #949	405 MONROE TPKE MONROE, CT 06468	Closed	11/25/2013	recd registration form re WO ust removal 10/7/13, no lab data on form, sas stated 12/18/14, they have recd the 2013 WO closure report	3	ALLIANCE RETAIL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144770&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144770&amp;type=ENFORCEMENT_ACTION</a>
ELLINGTON	Sunoco Buckstop	194 WINDSORVILLE RD ELLINGTON, CT 06029	Active	11/18/2013	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.	3	ALLIANCE RETAIL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144180&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144180&amp;type=ENFORCEMENT_ACTION</a>
Canton	CANTON GULF	210 Albany Tpke Canton, CT 06019	Active	10/28/2013	The annual test documentation was not available for the piping leak monitoring equipment and devices. . The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. The release detection documentation was not available..	8	ALLIANCE RETAIL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143131&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143131&amp;type=ENFORCEMENT_ACTION</a>

STAMFORD	MOBIL #976	920 HIGH RIDGE RD STAMFORD, CT 06905	Active	10/16/2013	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Equipment is not capable of one-eighth of an inch measurement.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The passing annual line leak detector test documentation was not main...	68	ALLIANCE RETAIL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142431&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142431&amp;type=ENFORCEMENT_ACTION</a>
MERIDEN	Aldin Associates LP/ Meriden Sunoco	363 W MAIN ST MERIDEN, CT 06451	Closed	11/6/2013	A closure report has not been maintained for this system permanently closed at this facility.. A review of DEP records indicates that we do not have a registration form with current information.. Failure to notify the implementing agency at least 30 days prior to beginning permanent closure of UST system components.. Rec notification stating three tanks removed, 12/18/14 SASU has two versions of a closure report for this site.	7	ALSA ASSOCIATES	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143603&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143603&amp;type=ENFORCEMENT_ACTION</a>

Winsted	Winsted Grocery	161 Main St Winsted, CT 06098	Active	8/27/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has...	18	Amana Trade LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165630&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165630&amp;type=ENFORCEMENT_ACTION</a>
NEWTOWN	AMARAL MOTORS, INC.	40 S MAIN ST NEWTOWN, CT 06470	Active	8/20/2014	Daily measurements to the nearest one-eighth of an inch were not made for any water level in the bottom of the tank. . Failure to have required financial responsibility in the required amount(s).. Proof of corrosion protection installation on tank was not available.. Proof of installation was not available; provide the piping corrosion protection testing results to prove installation or system must be permanently closed.. The date and measurements of oil and water level at the beginning and ending of at least a 36-hour idle period were not recorded. . The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facili...	16	AMARAL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165348&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165348&amp;type=ENFORCEMENT_ACTION</a>
EAST WINDSOR	AMERICAN FOOD MART	148 NORTH RD EAST WINDSOR, CT 06088	Closed	10/22/2013	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. This NOV was clsd by Kelly McShea on 10/30/13 as part of the NOV followup project.	3	AMERICAN FOOD MART	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142817&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142817&amp;type=ENFORCEMENT_ACTION</a>

FARMINGTON	AMERICAN RED CROSS	209 FARMINGTON AVE FARMINGTON, CT 06032	Closed	8/4/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. Inspection on 11/26/2014 by inspector John Hirschfeld shows usts were removed from the ground on 11/25/14. Site still needs to submit registration form but not a NOV requirement. Violations on NOV have been met.	2	AMERICAN RED CROSS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164292&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164292&amp;type=ENFORCEMENT_ACTION</a>
WEST HARTFORD	THE AMERICAN SCHOOL FOR THE DEAF	139 N MAIN ST WEST HARTFORD, CT 06107	Active	3/21/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. Water is not being monitored daily..	5	AMERICAN SCHOOL FOR THE DEAF	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152669&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152669&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	ANDREWS OIL COMPANY	136 RYE ST SOUTH WINDSOR, CT 06074	Active	12/5/2013	A review of DEP records indicates that we do not have a registration form with current information.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. The fill cover was broken or missing and must be repaired or replaced.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	7	ANDREWS OIL COMPANY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145114&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145114&amp;type=ENFORCEMENT_ACTION</a>
BRANFORD	TREMONTE AUTO GROUP INC.	490 E MAIN ST BRANFORD, CT 06405	Closed	3/4/2014	Enviroshield: Removal of one 2000 gal ust on 5/27/14, closure report forwarded to sas on 9/23/14	4	ANGELA FARRICIELLI MARITAL TRUST	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151212&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151212&amp;type=ENFORCEMENT_ACTION</a>

QUAKER HILL	GETTY S/S #611	40 NORWICH RD QUAKER HILL, CT 06375	Closed	3/21/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. . The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. recd closure report 9/26/14, tanks removed 5/30/14 by Tyree Environmental Corp. Closure report forwarded to sas on 9/26/14	17	AOC TRANSPORT, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152642&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152642&amp;type=ENFORCEMENT_ACTION</a>
NEW BRITAIN	GETTY S/S #6870	1500 CORBIN AVE NEW BRITAIN, CT 06053	Closed	11/20/2013	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. Recd notification on 10/15/14 stating site ownership has changed, closing nov as issued to Getty and new owners is J&S Enterprises, Inspector Cosker notified 11/21/14	12	AOC TRANSPORT, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144332&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144332&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	GETTY S/S #602	561 SULLIVAN AVE SOUTH WINDSOR, CT 06074	Closed	11/6/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Recd passing cathodic protection test results from Crompco dated 11/13/13	3	AOC TRANSPORT, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143640&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143640&amp;type=ENFORCEMENT_ACTION</a>

SIMSBURY	GETTY STATION #6725	850 HOPMEADOW ST SIMSBURY, CT 06070	Active	10/24/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. Annual Tightness Test for Pressurized Piping was not performed.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual tightness test documentation was not available for the piping. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or o...	33	AOC TRANSPORT, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151149&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151149&amp;type=ENFORCEMENT_ACTION</a>
CHESHIRE	GETTY #6779	197 MAIN ST CHESHIRE, CT 06410	Closed	10/17/2013	Site submitted notice of financial responsibility as self insurance, updated registration form showing tanks TOS & fee received, CP tested and passed on 12/17/13, tanks were pumped out to less than 1" on 11/20/13, sumps were pumped out & cleaned on 11/20/13, site submitted weekly inventory including water readings	16	AOC TRANSPORT, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142572&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142572&amp;type=ENFORCEMENT_ACTION</a>
MADISON	MADISON MOBIL	1336 BOSTON POST RD MADISON, CT 06443	Active	8/12/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	3	APACHE OIL COMAPNY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164778&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164778&amp;type=ENFORCEMENT_ACTION</a>
NEW LONDON	SUNOCO FOOD MART	407 WILLIAMS ST NEW LONDON, CT 06320	Active	4/4/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	7	APACHE OIL COMAPNY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154149&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154149&amp;type=ENFORCEMENT_ACTION</a>



NEW LONDON	HONEY BEE FARMS CONVENIENCE STORE	915 BANK ST NEW LONDON, CT 06320	Closed	3/31/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Recd monthly checklist email 6/11/14	1	APACHE OIL COMAPNY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153577&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153577&amp;type=ENFORCEMENT_ACTION</a>
WOODBURY	DOMS LYNNS CORNER	1633 MAIN ST N WOODBURY, CT 06798	Active	11/12/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. Monthly records of interstitial monitoring records were not available.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	6	Ariola	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143964&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143964&amp;type=ENFORCEMENT_ACTION</a>
MIDDLETOWN	DAINTY RUBBISH SERVICE, INC.	90 INDUSTRIAL PARK RD MIDDLETOWN, CT 06457	Closed	4/29/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The annual tightness test documentation was not available for the piping. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The passing annual line leak detector test documentation was not maintained.. NOV being closed as ownership of site has changed. Information forwarded to Mr. Wilde 6/24/14 as new NOV should be issued	9	ARMETTA	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156307&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156307&amp;type=ENFORCEMENT_ACTION</a>
Unionville	UNIONVILLE C.O. (5241)	82 Lovely St Unionville, 06085	Closed	1/29/2014	A review of DEP records indicates that we do not have a registration form with current information.. Piping was repaired and no report of the repair was maintained.. Repaired piping was not tested.. registration form recd, fiscal responsibility form unsigned, piping repair report recd 4/2/14, Superior Environmental Corp, replaced existing piping and installed new OPW double wall non-metallic flex piping, all tests passed.	3	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2148899&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2148899&amp;type=ENFORCEMENT_ACTION</a>
Farmington	FARMINGTON CO (5231)	18 Main St Farmington, CT 06032	Closed	1/29/2014	A review of DEP records indicates that we do not have a registration form with current information.. registration form entered into ICM on 1/16/14	1	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2148900&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2148900&amp;type=ENFORCEMENT_ACTION</a>

BRIDGEPORT	NORTH BRIDGEPORT CENTRAL OFFICE (3721)	3668 MAIN ST BRIDGEPORT, 06606	Active	12/11/2013	A review of DEP records indicates that we do not have a registration form with current information.. Piping was repaired and no report of the repair was maintained.. The owner or operator of an UST system has failed to designate Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training	3	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145445&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145445&amp;type=ENFORCEMENT_ACTION</a>
Bridgeport	Bridgeport Tower (3111)	430 John St Bridgeport, CT 06604	Closed	12/11/2013	A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. The owner or operator of an UST system has failed to designate Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. Registration form in ICM dated 2/7/14 contains operator training and financial responsibility information.	3	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145442&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145442&amp;type=ENFORCEMENT_ACTION</a>
BRIDGEPORT	BRIDGEPORT CO #1 (3101)	365 JOHN ST BRIDGEPORT, 06604	Closed	12/11/2013	A review of DEP records indicates that we do not have a registration form with current information.. The owner or operator of an UST system has failed to designate Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. 2/7/14 registration includes a/b operator information	2	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145443&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145443&amp;type=ENFORCEMENT_ACTION</a>
STRATFORD	STRATFORD CENTRAL OFFICE (3731)	2672 MAIN ST STRATFORD, 06615	Closed	12/11/2013	The owner or operator of an UST system has failed to designate Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. ESRUST database shows registration date as 10/6/14, with Rayshell Wamsley listed as the a/b operator	1	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145444&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145444&amp;type=ENFORCEMENT_ACTION</a>
COLUMBIA	COLUMBIA C.O. (7431)	246 ROUTE 66 COLUMBIA, 06237	Active	11/6/2013	A review of DEP records indicates that we do not have a registration form with current information.. Piping was repaired and no report of the repair was maintained.. Repaired piping was not tested.. The Department's inspector has determined that the leak monitor for piping was in alarm condition.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The overflow audible alarm was not visible or clearly marked..	6	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143842&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143842&amp;type=ENFORCEMENT_ACTION</a>

THOMASTON	THOMASTON C.O. #1561	37 HIGH ST THOMASTON, 06787	Closed	10/31/2013	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. 11/8/13 letter from Jabbar Thomas states that AT&T removed debris & liquid from spill bucket and site is ready to be inspected again	1	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143542&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143542&amp;type=ENFORCEMENT_ACTION</a>
SEYMOUR	SEYMOUR C.O. (1421)	6 FIRST ST SEYMOUR, 06483	Closed	10/30/2013	A review of DEP records indicates that we do not have a registration form with current information.. Piping was repaired and no report of the repair was maintained.. Repaired piping was not tested.. This NOV was clsd by Kelly McShea on 11/7/13 as part of the NOV followup project.	3	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143540&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143540&amp;type=ENFORCEMENT_ACTION</a>
MADISON	MADISON C.O. #2 (REC 1351)	1272 DURHAM RD MADISON, 06443	Closed	10/23/2013	A review of DEP records indicates that we do not have a registration form with current information.. This NOV was clsd by Kelly McShea on 11/7/13 as part of the NOV followup project	1	AT&T CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142966&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142966&amp;type=ENFORCEMENT_ACTION</a>
WINDSOR LOCKS	AVIS RENT A CAR	4 SCHOEPHOESTER RD WINDSOR LOCKS, CT 06096	Closed	9/18/2014	Could not verify that the overfill protection device was installed at the required 90% alert or 95% shut off level. . Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly,Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. T...	18	AVIS RENT A CAR SYSTEM, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167028&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167028&amp;type=ENFORCEMENT_ACTION</a>

DANBURY	AVIS RENT-A-CAR	58 MILL PLAIN RD DANBURY, CT 06811	Active	8/5/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily...	8	AVIS RENT A CAR SYSTEM, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164430&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164430&amp;type=ENFORCEMENT_ACTION</a>
LITCHFIELD	Bantam Fuel Mart	199 WEST STREET RTE 202 LITCHFIELD, CT 06759	Closed	11/7/2013	Inspection on 10/20/2014 by inspector George Purple. The inspection status was failed. 14 violation(s) found. NOV Id: NOVUST-GP14-0021 issued on this NOV is void	33	AZIZ	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143843&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143843&amp;type=ENFORCEMENT_ACTION</a>
DANIELSON	S-N-S Inc. dba Danielson's Gulf	869 N MAIN ST DANIELSON, CT 06239	Active	11/8/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. Fittings were not cathodically protected.. No Notice of Financial Responsibility on site.. The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The passing annual line leak detector test documentation was not maintained.. The Release Detection Method was not maintained in accord...	35	BADAT, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143833&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143833&amp;type=ENFORCEMENT_ACTION</a>

MIDDLEFIELD	LAKESIDE DELI	275 BAILEYVILLE RD MIDDLEFIELD, CT 06455	Closed	10/30/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. Suction piping without continuous monitoring with a check valve at the tank is required to be tightness tested every three years. Safe suction piping is required to be tested annually the last three (3) years of its life expectancy.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. UST owners or operators have failed to demonstrate that financial responsibil...	10	BAILEYVILLE HOLDING CO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143303&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143303&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	BRAINARD ROAD SHELL	131 BRAINARD RD HARTFORD, CT 06114	Active	2/26/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The fill cover was broken or missing and must be repaired or replaced.. The owner or operator failed to immediately respond to a sump sensor alarm..	10	BAKRI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150661&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150661&amp;type=ENFORCEMENT_ACTION</a>

LITCHFIELD	IRVING TWIN STOP	250 WEST ST LITCHFIELD, CT 06759	Active	10/16/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. Annual Tightness Test for Pressurized Piping was not performed.. Monthly records of interstitial monitoring records were not available.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The annual test documentation was not available for the piping leak monitoring equipment and devices. . The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. The passing annual line leak detector test had not been performed.. The release detection documentation was not available..	27	Bamtam Fuel Supply	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142453&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142453&amp;type=ENFORCEMENT_ACTION</a>
MONROE	WHITNEY FARMS (GOLF COURSE)/ STONE BARN	175 SHELTON RD MONROE, CT 06468	Active	3/3/2014	A review of DEP records indicates that we do not have a registration form with current information.. Piping was repaired and no report of the repair was maintained.. Repaired piping was not tested.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	10	BARGAS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151147&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151147&amp;type=ENFORCEMENT_ACTION</a>
FAIRFIELD	BENNETT'S SERVICE STATION	550 COMMERCE DR FAIRFIELD, CT 06825	Closed	5/9/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. The Franklin Co. changed EMC console setup from static tank test to CSLD, all tests ok.	3	BENNETT	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157302&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157302&amp;type=ENFORCEMENT_ACTION</a>

STRATFORD	FORMER OLD COACH AUTO & TRUCK REPAIR, INC.	100 HATHAWAY DR STRATFORD, CT 06615	Closed	6/12/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.. Registration form recd 11/7/14 states tank A-1 was removed 10/15/14, closure report & registration forwarded to sasu 12/22/14	5	BENZIEN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160953&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160953&amp;type=ENFORCEMENT_ACTION</a>
PUTNAM	Bestway (Citgo) Putnam	146 CHURCH ST PUTNAM, CT 06260	Active	12/13/2013	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	9	BEST WAY CITGO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145514&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145514&amp;type=ENFORCEMENT_ACTION</a>
NORTH FRANKLIN	BEST WAY EXPRESS LANE FOODS	96 ROUTE 32 NORTH FRANKLIN, CT 06254	Active	10/3/2013	No Notice of Financial Responsibility on site.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The dispenser sump contains liquid.. The passing annual line leak detector test documentation was not maintained.. The release detection documentation was not available.. The three (3) year test documentation was not available for the suction piping..	16	BEST WAY/EXPRESS LANE FOOD	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141914&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141914&amp;type=ENFORCEMENT_ACTION</a>
BETHEL	R.M.T. JOHNSON SCHOOL	500 WHITTLESEY DR BETHEL, CT 06801	Active	8/6/2014	A review of DEP records indicates that we do not have a registration form with current information..	1	BETHEL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164478&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164478&amp;type=ENFORCEMENT_ACTION</a>
BETHEL	BETHEL HEALTH CARE	13 PARK LAWN DR BETHEL, CT 06801	Active	11/13/2013	A review of DEP records indicates that we do not have a registration form with current information.. Could not verify that the overflow protection device was installed at the required 90% alert or 95% shut off level. . UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	3	BETHEL HEALTH & REHABILITATION CENTER, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143963&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143963&amp;type=ENFORCEMENT_ACTION</a>



Old Saybrook	BETWEEN THE BRIDGES, LLC.	142 Ferry Rd Old Saybrook, CT 06475	Closed	7/28/2014	Enviroshield performed passing line tightness testing and LLD testing on 8/6/14, Monthly form submitted. Form acceptable per Inspector Bellmar on 8/28/14, Wildco Petroleum cleaned and repaired spill devices. Clamp replacement, SCM5 pump purchase. Mike Pendelton has completed A/B Operator training on 7/29/14	6	BETWEEN-THE-BRIDGES LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163934&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163934&amp;type=ENFORCEMENT_ACTION</a>
PRESTON	PRESTON FOOD MART	363 ROUTE 165 PRESTON, CT 06365	Active	3/18/2014	Fittings were not cathodically protected.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The monthly release detection test documentation from the automatic tank gauging device was not available. .	10	BHAI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152465&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152465&amp;type=ENFORCEMENT_ACTION</a>
BLOOMFIELD	BIRKEN MANUFACTURING COMPANY, INC.	3 OLD WINDSOR RD BLOOMFIELD, CT 06002	Active	7/10/2014	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	3	BIRKEN MANUFACTURING COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163070&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163070&amp;type=ENFORCEMENT_ACTION</a>
EAST HAVEN	MAIN STREET GAS	439 MAIN ST EAST HAVEN, CT 06512	Closed	11/14/2013	Inspection on 12/29/2014 by inspector Gary Bellmar. The inspection status was failed. 24 violation(s) found. NOV Id: NOVUST-GB14-0169 issued, note: site had submitted NE Tank Services 1/17/14 invoice for passing CP for tanks & lines	8	BISHOP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144794&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144794&amp;type=ENFORCEMENT_ACTION</a>
GUILFORD	GUILFORD ON THE RUN	1164 BOSTON POST RD GUILFORD, CT 06437	Closed	9/23/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. 9/25/14 ECS Eclipse responded to NOV: TMC Environmental was dispatched to check the status of all tanks, sumps, fills and pans and remove any accumulated liquid.	2	BLACKROCK HOLDINGS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167182&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167182&amp;type=ENFORCEMENT_ACTION</a>
BRANFORD	BLAKESLEE ARPAIA CHAPMAN, INC.	200 N BRANFORD RD BRANFORD, CT 06405	Active	9/15/2014	A closure report has not been maintained for this system permanently closed at this facility.. A review of DEP records indicates that we do not have a registration form with current information..	7	BLAKESLEE ARPAIA CHAPMAN, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166711&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166711&amp;type=ENFORCEMENT_ACTION</a>

WINDSOR LOCKS	BOBBY G'S OLD FASHIONED SERVICE, INC.	61 S MAIN ST WINDSOR LOCKS, CT 06096	Active	11/26/2013	A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The release detection documentation was not available..	4	BOBBY G'S OLD FASHIONED SERVICE, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144767&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144767&amp;type=ENFORCEMENT_ACTION</a>
Unionville	BOLAN LLC	1795 Farmington Ave Unionville, CT 06085	Closed	7/18/2014	Site created a monthly inspection checklist and submitted a few months of inspections. Site submitted four months of interstitial monitoring reports and alarm history reports. Created procedure where they will print liquid status reports each month and attach them to the monthly inspection checklist. Retraining 8/7/14 Mohammad Ishaq A/B Operator.	6	BOLAN LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163275&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163275&amp;type=ENFORCEMENT_ACTION</a>
WETHERSFIELD	JDS GASWAY LLC	1785 BERLIN TPKE WETHERSFIELD, CT 06109	Active	4/2/2014	Proof of installation was not available; provide the piping corrosion protection testing results to prove installation or system must be permanently closed.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	9	BORDIEN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153815&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153815&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	BORLA'S SERVICE STATION LLC	826 NEW HARWINTON RD TORRINGTON, CT 06790	Active	6/23/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. The piping cathodic protection was not tested within six (6) months of installation or within the last year.	6	Borla	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161871&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161871&amp;type=ENFORCEMENT_ACTION</a>
BEACON FALLS	BOTTI & LENNERS	215 S MAIN ST BEACON FALLS, CT 06403	Active	12/5/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	2	BOTTI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145107&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145107&amp;type=ENFORCEMENT_ACTION</a>
NEW HAVEN	BOUSQUET'S SERVICE CENTER	115 MAIN ST NEW HAVEN, CT 06513	Closed	5/14/2014	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Site submitted passing CP tank test results on 6/3/14	2	BOUSQUET'S SERVICE CENTER	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157950&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157950&amp;type=ENFORCEMENT_ACTION</a>
Branford	BRANHAVEN SERVICES LLC	501 Main St Branford, CT 06405	Closed	9/17/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained.. The monthly inspection checklist was approved by Supervisor Saliby on 9/25/14, Passing tightness testing and passing LLD testing results from NE Tank Service	3	BRANHAVEN SERVICES LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166850&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166850&amp;type=ENFORCEMENT_ACTION</a>
CHESHIRE	CHESHIRE AUTO CARE	831 S MAIN ST CHESHIRE, CT 06410	Closed	10/17/2013	The passing annual line leak detector test documentation was not maintained.. Original report (NOVUST-GB13-0098) lost upon syncing and GB13-0100 issued. Passing LLD test results recd 11/11/13. tanks manifolded	3	BRICKEL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142571&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142571&amp;type=ENFORCEMENT_ACTION</a>

CHESHIRE	CHESHIRE AUTO CARE	831 S MAIN ST CHESHIRE, CT 06410	Closed	10/17/2013	The passing annual line leak detector test documentation was not maintained.. This NOV was clsd by Kelly McShea on 12/2/13 as part of the NOV followup project	3	BRICKEL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142580&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142580&amp;type=ENFORCEMENT_ACTION</a>
TOLLAND	DBM #559	206 MERROW RD TOLLAND, CT 06084	Closed	12/6/2013	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project	1	BROTHER	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145188&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145188&amp;type=ENFORCEMENT_ACTION</a>
BETHLEHEM	SUNNY SUPERMARKET LLC	82 MAIN ST S BETHLEHEM, CT 06751	Closed	10/22/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. This NOV was clsd by Kelly McShea on	1	BROTHERS LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142768&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142768&amp;type=ENFORCEMENT_ACTION</a>
SHELTON	SHELL SERVICE STATION	99 BRIDGEPORT AVE SHELTON, CT 06484	Closed	6/9/2014	UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. NOV being closed per Lori Saliby on 6/23/14. Site submitted signed contract with Liberty Auto & Electric for UST replacement in	6	BRUCE C. BUTLER, L.L.C.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160465&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160465&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	JOHN & SONS AUTOMOTIVE	125 NEW BRITAIN AVE HARTFORD, CT 06106	Closed	2/27/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The annual tightness test documentation was not available for the piping. . The division inspector has determined that a piping sump sensor was not installed at the tank sump.. The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Clsd per inspection 3/28/14. Inspector Cosker stated issues addressed and NOV can be clsd.	15	BSKRASA LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150770&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150770&amp;type=ENFORCEMENT_ACTION</a>
SHELTON	KENNYNICK LLC	198 LEAVENWORTH RD SHELTON, CT 06484	Closed	10/28/2013	The dispenser sump contains liquid.. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Per Inspector Purple re-vist on 7/24/14 the site NOV was all set with the exception of CP testing which was to be held later that day and results faxed to DEEP. Passing CP testing recd 8/29/14	7	BUCKHORN CROSSING LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143098&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143098&amp;type=ENFORCEMENT_ACTION</a>

WINDSOR LOCKS	BUDGET RENT A CAR	85-317 SCHOEPHOESTER ROAD WINDSOR LOCKS, CT 06096	Active	9/18/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). .	8	BUDGET RENT A CAR SYSTEM INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167030&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167030&amp;type=ENFORCEMENT_ACTION</a>
NEWTOWN	BUZZ'S ENTERPRISES, INC.	286 S MAIN ST NEWTOWN, CT 06470	Active	8/19/2014	Annual Tightness Test for Pressurized Piping was not performed.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or...	32	BUZZ'S ENTERPRISES, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165350&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165350&amp;type=ENFORCEMENT_ACTION</a>
WATERTOWN	WESTBURY CORNER STORE	24 FERN HILL RD WATERTOWN, CT 06795	Closed	11/12/2013	A review of DEP records indicates that we do not have a registration form with current information.. 6/9/2014 NOV archived by Lori Salihv	1	BYRNES	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143965&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143965&amp;type=ENFORCEMENT_ACTION</a>

SUFFIELD	C & S Wholesale Grocers	1120 HARVEY LN SUFFIELD, CT 06078	Closed	4/17/2014	A review of DEP records indicates that we do not have a registration form with current information.. Registration form received 4/21/14	1	C&S WHOLESALE GROCERS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155382&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155382&amp;type=ENFORCEMENT_ACTION</a>
SHELTON	CAMMISA'S GARAGE INC	344 RIVER RD SHELTON, CT 06484	Closed	6/9/2014	Failure to have required financial responsibility in the required amount(s).. Site removed two 8000 gal gasoline USTs, Phoenix lab report submitted, per SASU soils below GA PMC & RES DEC, need GW data for RSRs, site is considered "lust complete"	1	CAMMISA'S GARAGE, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160466&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160466&amp;type=ENFORCEMENT_ACTION</a>
MERIDEN	HARBOR TOWERS LIM.PART.	60 HANOVER ST MERIDEN, CT 06451	Active	8/19/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. No Notice of Financial Responsibility on site.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	4	CARABETTA MANAGEMENT COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165132&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165132&amp;type=ENFORCEMENT_ACTION</a>
MERIDEN	HANOVER TOWERS REALTY	76 BUTLER ST MERIDEN, CT 06451	Active	8/19/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. No Notice of Financial Responsibility on site.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	4	CARABETTA MANAGEMENT COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165131&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165131&amp;type=ENFORCEMENT_ACTION</a>

BLOOMFIELD	CARUSO'S AUTO BODY SERVICE, INC.	36 TUNXIS AVE BLOOMFIELD, CT 06002	Active	5/14/2014	Documentation of an annual passing cathodic protection test for piping was not available.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The tanks cathodic protection was not tested within six (6) months of installation or ...	18	Caruso's Auto Body Service, Inc	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158050&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158050&amp;type=ENFORCEMENT_ACTION</a>
VERNON	SAM'S FOOD STORE #1085	41 WINDSOR AVE VERNON, CT 06066	Active	9/17/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion	3	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166843&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166843&amp;type=ENFORCEMENT_ACTION</a>
MANCHESTER	SAMS FOOD STORE #1046	653 CENTER ST MANCHESTER, CT 06040	Closed	8/26/2014	Inspection on 10/14/2014 by inspector Mike Cosker . The inspection status was failed. 2 violation(s) found. new NOV Id: NOVUST-MC214-0084 issued	12	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165571&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165571&amp;type=ENFORCEMENT_ACTION</a>
PUTNAM	SAM'S FOOD STORE	303 KENNEDY DR PUTNAM, CT 06260	Active	8/6/2014	The Department's inspector has determined that the leak monitor for piping was in alarm condition.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. UST owners and/or operators are required to report to the implementing agency, at (860) 424-3338 and within twenty-four (24)hours, actual or suspected releases from UST systems..	4	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164479&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164479&amp;type=ENFORCEMENT_ACTION</a>



BETHEL	BETHEL SUNOCO #011	295 GREENWOOD AVE BETHEL, CT 06801	Closed	6/25/2014	Monthly records of interstitial monitoring records were not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Site submitted renewed a/b operator training information, monthly inspection checklist and monthly records of interstitial monitoring.	4	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162098&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162098&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	SAM'S FOOD STORE	1001 N COLONY RD WALLINGFORD, CT 06492	Active	4/21/2014	The Department's inspector has determined that the leak monitor for piping was in alarm condition.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator failed to immediately respond to a sump sensor alarm.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	4	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155374&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155374&amp;type=ENFORCEMENT_ACTION</a>
NORWICH	SAM'S FOOD STORE	275 WASHINGTON ST NORWICH, CT 06360	Closed	4/14/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. Liquid pumped out of sumps. Both STP sumps have metallic piping in contact with the soil. 9/30/14 passing Cathodic protection test recd done at STP / line flex connectors. Soil cant be taken out of contact since flex connector coming out of STP line connection goes beyond entrenchment.	3	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154930&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154930&amp;type=ENFORCEMENT_ACTION</a>
PLAINFIELD	SAM'S FOOD STORE	518 NORWICH RD PLAINFIELD, CT 06374	Closed	3/31/2014	A pump out of the liquid was performed on 4/3/14, manifest included. CCO has approved for Service Station Equipment to go on site and repair all spill containment devices to make them liquid tight. They are to remove existing spill buckets and provide and install new slip on spill bucket, cap and adapters.	3	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153536&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153536&amp;type=ENFORCEMENT_ACTION</a>



NEW HARTFORD	Stop-N- Save	513 MAIN ST NEW HARTFORD, CT 06057	Closed	3/28/2014	Site submitted passing monthly inventory, registration form listing piping material as flexible plastic, CP for piping violation voided, passing CP recd for tanks, passing CSLD report recd, reconciliation logs, and information re pump out of spill containment.	19	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153503&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153503&amp;type=ENFORCEMENT_ACTION</a>
TRUMBULL	SUNOCO	6335 MAIN ST TRUMBULL, CT 06611	Active	3/27/2014	Monthly records of interstitial monitoring records were not available.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.	3	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153230&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153230&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	SAM'S FOOD STORE	145 NEW BRITAIN AVE HARTFORD, CT 06106	Closed	2/27/2014	The fill cover was broken or missing and must be repaired or replaced.. Fill cover was replaced	2	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150769&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150769&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	SAM'S FOOD STORE # 1036	106 SISSON AVE HARTFORD, CT 06106	Closed	2/26/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Service Station Environmental performed a pump out on 3/4/14	6	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150662&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150662&amp;type=ENFORCEMENT_ACTION</a>
SUFFIELD	SAMS FOOD STORE	1520 MAPLETON AVE SUFFIELD, CT 06078	Active	12/17/2013	A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. The annual tightness test documentation was not available for the piping. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The passing annual line leak detector test documentation was not maintained.. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	33	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144768&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144768&amp;type=ENFORCEMENT_ACTION</a>

NEW HAVEN	RAVI PETRO	14 KIMBERLY AVE NEW HAVEN, CT 06519	Closed	11/14/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. Registration received 2/10/14. A/B operators listed in database.	1	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144033&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144033&amp;type=ENFORCEMENT_ACTION</a>
MANSFIELD CENTER	SAM'S MANSFIELD	9 STAFFORD RD MANSFIELD CENTER, CT 06250	Active	10/29/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	11	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143193&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143193&amp;type=ENFORCEMENT_ACTION</a>
CROMWELL	SAM'S FOOD STORE	265 MAIN ST CROMWELL, CT 06416	Closed	10/29/2013	Site submitted passing line tightness testing and passing LLD test. Site submitted Service station Environmental manifest re sump water removal and photos of sumps	13	CCO, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143238&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143238&amp;type=ENFORCEMENT_ACTION</a>
CLINTON	Cedar Island Marina	34 RIVERSIDE DR CLINTON, CT 06413	Closed	5/21/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. 5/26/14 site removed liquid from sump, mopped out sump, repaired the sumps water tight seal and removed sediment around the outside of the rim, which had been deflecting water into the sump rather than allowing the water to drain around the outside of the rim. Before & after Photos submitted	4	CEDAR ISLAND MARINA, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158692&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158692&amp;type=ENFORCEMENT_ACTION</a>

LEDYARD	LED-CENTER GAS-CARWASH LLC	735 COLONEL LEDYARD HWY LEDYARD, CT 06339	Active	7/8/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. Annual Tightness Test for Pressurized Piping was not performed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The owner or operator has failed to perform, or has performed inadequ...	16	CENTER LEDYARD SHELL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162763&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162763&amp;type=ENFORCEMENT_ACTION</a>
NEW HAVEN	Chapel Venture, LLC	61 CHAPEL ST NEW HAVEN, CT 06513	Closed	3/3/2014	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. Site submitted registration form 3/25/14.	1	CHAPEL VENTURES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151104&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151104&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	CHARLOTTE HUNGERFORD HOSPITAL	540 LITCHFIELD ST TORRINGTON, CT 06790	Active	7/28/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	3	CHARLOTTE HUNGERFORD HOSPITAL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163961&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163961&amp;type=ENFORCEMENT_ACTION</a>
BRANFORD	Leetes Island Fuel	49 LEETES ISLAND RD BRANFORD, CT 06405	Closed	9/10/2014	Inspection on 09/12/2014 by inspector George Purple. The inspection status was passed.	23	Chaudry	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166527&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166527&amp;type=ENFORCEMENT_ACTION</a>
MONROE	MONROE FOOD MART / SHELL SERVICE STATION	133 MAIN ST MONROE, CT 06468	Closed	11/18/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. ESRUST states last registration recd 1/16/14	1	Chestnut Petroleum Distributors	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144409&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144409&amp;type=ENFORCEMENT_ACTION</a>

WALLINGFORD	CHOATE SCHOOL PONDS	35 N ELM ST WALLINGFORD, CT 06492	Closed	11/7/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project.	2	CHOATE ROSEMARY HALL FOUNDATION, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143728&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143728&amp;type=ENFORCEMENT_ACTION</a>
OLD LYME	CITGO GASOLINE SERVICE STATION	281 SHORE RD OLD LYME, CT 06371	Active	8/7/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	2	CHOUDHRY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164577&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164577&amp;type=ENFORCEMENT_ACTION</a>
BOZRAH	IBRAHIM ALI LLC (FORMERLY MIMMO'S SERVICE CENTER)	421 SALEM TPKE BOZRAH, CT 06334	Active	10/23/2013			CHOUDHRY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143109&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143109&amp;type=ENFORCEMENT_ACTION</a>
BLOOMFIELD	SEABURY RETIREMENT COMMUNITIES	200 SEABURY DR BLOOMFIELD, CT 06002	Closed	5/14/2014	A closure report has not been maintained for this system permanently closed at this facility.. A review of DEP records indicates that we do not have a registration form with current information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. On 6/3/14 site submitted updated registration form, operator training information, monthly inspection checklist, and a closure report for DF tank A.	4	Church Home of Hartford, Inc; dbaSEABURY RETIREMENT	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158049&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158049&amp;type=ENFORCEMENT_ACTION</a>
Windsor Locks	CIGNA FLIGHT OPERATIONS	85 Insurance Rd Windsor Locks, CT 06096	Closed	9/22/2014	Monthly records of interstitial monitoring records were not available.. The annual test documentation was not available for the piping leak monitoring equipment and devices. 10/2/14 Lakes Region Environmental onsite to test all probes & veeder root monitor, all found functional. Site submitted passing Annual leak Monitor & Overfill Protection Test Form with Secondary Containment and probe tests, liquid status normal reports	4	CIGNA FLIGHT OPERATIONS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167118&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167118&amp;type=ENFORCEMENT_ACTION</a>
CLINTON	FORMER TEXACO/ SHELL STATION/ CLINTON MARKET	56 W MAIN ST CLINTON, CT 06413	Closed	3/27/2014	The dispenser sump contains liquid.. TMC Environmental on site 4/8/14. Removed liquid from dispenser pan, checked all fills, spill buckets and pans. Ran V-root slip, all functions normal	1	CLINTON REALTY INVESTMENT, INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153239&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153239&amp;type=ENFORCEMENT_ACTION</a>

BRANFORD	COLBURN'S	87 S MONTOWESE ST BRANFORD, CT 06405	Active	7/29/2014	Failure to have required financial responsibility in the required amount(s).. Fittings were not cathodically protected.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	15	COLBURN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163999&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163999&amp;type=ENFORCEMENT_ACTION</a>
HAMDEN	FAMILY AUTO CENTER	293 GOODRICH ST HAMDEN, CT 06517	Active	8/25/2014	An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. . Failure to have required financial responsibility in the required amount(s).. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location..	14	COLLINS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165600&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165600&amp;type=ENFORCEMENT_ACTION</a>
NEW HAVEN	COLLINS TIRES	4 ORCHARD ST NEW HAVEN, CT 06519	Active	5/27/2014	A review of DEP records indicates that we do not have a registration form with current information.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location..	5	COLLINS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158932&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158932&amp;type=ENFORCEMENT_ACTION</a>

MERIDEN	COMPUTER SCIENCES CORPORATION	71 DEERFIELD LN MERIDEN, CT 06450	Closed	11/5/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Passing cathodic test results received 12/16/13.	2	COMPUTER SCIENCES CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143570&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143570&amp;type=ENFORCEMENT_ACTION</a>
BROOKFIELD	UNITED PARCEL SERVICE, INC.	82 POCONO RD BROOKFIELD, CT 06804	Closed	8/6/2014	Per Assistant Director Peter Zack who reviewed the inspection report and correspondence, the inspection was closed early, the records were available, therefore the NOV is being voided. Note operator training held 7/15/14	11	CONDELL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164509&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164509&amp;type=ENFORCEMENT_ACTION</a>
NEWTOWN	FRIENDLY SERVICE #52	47 CHURCH HILL RD NEWTOWN, CT 06470	Closed	8/14/2014	Site updated their excel spreadsheets used for weekly reconciliation to show the volumetric size of the tank as well as the gallons pumped, store will sign & print them & store in compliance binder; fiscal mechanism: Peoples United Bank, SB-1810, 9/10/14-9/10/15, forwarded to steu on 10/21/14	5	CONSUMERS PETROLEUM OF CONNECTICUT, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164943&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164943&amp;type=ENFORCEMENT_ACTION</a>
NEW MILFORD	FRIENDLY SERVICE STATIONS, INC. #30	61 DANBURY RD NEW MILFORD, 06776	Closed	4/22/2014	The annual test documentation was not available for the piping leak monitoring equipment and devices. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Advanced Tank Testing Services onsite 10/23/13, line tightness testing and LLD testing passed. Site created & submitted new monthly inspection checklist	4	CONSUMERS PETROLEUM OF CONNECTICUT, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155566&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155566&amp;type=ENFORCEMENT_ACTION</a>
MONROE	Friendly Service Station #53	396 MONROE TPKE MONROE, CT 06468	Closed	11/25/2013	No Notice of Financial Responsibility on site.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project.	2	CONSUMERS PETROLEUM OF CONNECTICUT, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144769&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144769&amp;type=ENFORCEMENT_ACTION</a>
EAST HARTFORD	SILVER LANE SHELL	1475 SILVER LN EAST HARTFORD, CT 06118	Closed	9/15/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. Inspection on 09/16/2014 by inspector George Purple to remove red tags. The inspection status was passed for both red tag and NOV violations. Site is SOC	3	CPD PARENT PROPERTIES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166705&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166705&amp;type=ENFORCEMENT_ACTION</a>



Danbury	Chestnut Mart	445 N Main St Danbury, CT 06811	Active	7/30/2014	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual test documentation was not available for the piping leak monitoring equipment and devices. . The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). .	10	CPD PARENT PROPERTIES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164293&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164293&amp;type=ENFORCEMENT_ACTION</a>
FARMINGTON	SHELL SERVICE STATION	342 COLT HWY FARMINGTON, CT 06032	Active	7/16/2014	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). .	3	CPD PARENT PROPERTIES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163245&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163245&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	Albany Avenue Shell	949 ALBANY AVE HARTFORD, CT 06112	Active	5/16/2014	A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. Monthly records of interstitial monitoring records were not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements..	10	CPD PARENT PROPERTIES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158313&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158313&amp;type=ENFORCEMENT_ACTION</a>



Hartford	FORMER SHELL FACILITY NO. 100040	195 Prospect Ave Hartford, CT 06106	Active	4/17/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release or discharge from a UST system.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The fill cover was broken or missing and must be repaired or replaced..	10	CPD PARENT PROPERTIES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155223&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155223&amp;type=ENFORCEMENT_ACTION</a>
GLASTONBURY	TEXACO SERVICE STATION	556 HEBRON AVE GLASTONBURY, CT 06033	Active	2/28/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	12	CPD PARENT PROPERTIES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150926&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150926&amp;type=ENFORCEMENT_ACTION</a>
VERNON	Hartford Turnpike Shell	448 HARTFORD TPKE VERNON, CT 06066	Closed	12/4/2013	The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. 6/10/14 Alarm fixed. Site submitted liquid status report showing all sensors working normally and passing 0.2 test results	1	CPD PROPERTIES- 24 HIGH STREET LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144976&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144976&amp;type=ENFORCEMENT_ACTION</a>
EAST WINDSOR	SHELL SERVICE STATION	172 BRIDGE ST EAST WINDSOR, CT 06088	Closed	10/22/2013	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. This NOV was clsd by Kelly McShea on 11/4/13 as part of the NOV followup project.	1	CPD PROPERTIES- 24 HIGH STREET LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142818&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142818&amp;type=ENFORCEMENT_ACTION</a>
SOUTHURY	Southbury Shell	121 MAIN ST N SOUTHURY, CT 06488	Closed	10/10/2013	No Notice of Financial Responsibility on site.. Ace American Insurance Company, G24729308 002 expires 10/1/2014	1	CPD PROPERTIES- 24 HIGH STREET LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142373&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142373&amp;type=ENFORCEMENT_ACTION</a>
NEW HAVEN	CROSBY REALTY	454 QUINNIPIAC AVE NEW HAVEN, CT 06513	Closed	11/14/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. USTs have been removed, CTR Closure report dated 5/28/14 given to Inspector Keating onsite 9/30/14, NOV can be closed per Inspector Keating	2	CROSBY REALTY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144035&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144035&amp;type=ENFORCEMENT_ACTION</a>

Monroe	Cross Hill Service	515 Monroe Tpke Monroe, CT 06468	Active	10/28/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	16	Cross Hill Service LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144410&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144410&amp;type=ENFORCEMENT_ACTION</a>
Essex	CUMBERLAND FARMS GULF #0673	82 Main St PO BOX 237 Essex, CT 06426	Closed	8/5/2014	The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. USTs at site continuously monitored by Veeder-root system... reasoning for over limit inventory report believed to be due to temperature variance. Site was remotely polled and periodic leak test history included. History shows each of the usts has passing leak tests for previous 12 months. Cumberland Farms also included the most recent annual compliance tank test report 5/14/14 including passing line tightness test results, LLD test results, impact valves, lead detection monitoring system, stage 1 documentation , documentation of the requested meter calibration found all meters within regulated limits. Also attached were four weeks of inventory within tolerance.	1	CUMBERLAND FARMS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164390&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164390&amp;type=ENFORCEMENT_ACTION</a>
SHELTON	CUMBERLAND FARMS	464 RIVER RD SHELTON, CT 06484	Active	6/9/2014	UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. .	3	CUMBERLAND FARMS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160464&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160464&amp;type=ENFORCEMENT_ACTION</a>
MOODUS	CUMBERLAND FARMS #660	416 E HADDAM MOODUS RD MOODUS, CT 06469	Closed	5/30/2014	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. recd notification form dated 12/11/13	1	CUMBERLAND FARMS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159588&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159588&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	Cumberland Farms #803	868 N COLONY RD WALLINGFORD, CT 06492	Active	4/22/2014	The dispenser sump contains liquid.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping)	2	CUMBERLAND FARMS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155586&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155586&amp;type=ENFORCEMENT_ACTION</a>

GLASTONBURY	CUMBERLAND FARMS GULF #694	2875 MAIN ST GLASTONBURY, CT 06033	Closed	2/26/2014	OCSR #2014-00778 2/26/14 assigned Brian Emanuelson, unweathered gasoline in sump, TMC Environmental pumped out sump. ECS gauged sniffer wells & found no gasoline impact, La Mountain Brothers inc on site to make repairs & test lines, hydrostatic testing of sump, sump determined to be tight and OCSR case closed 2/27/14	2	CUMBERLAND FARMS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150663&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150663&amp;type=ENFORCEMENT_ACTION</a>
ELLINGTON	CUMBERLAND FARMS #0643	5 WAPPING WOOD RD ELLINGTON, CT 06029	Closed	11/18/2013	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Per Tanknology report (testing date 7/21/14) Sumps sensors replaced. There was no liquid found in any secondary containment system designed as a dry system, sensors were at lowest point of secondary containment, and sensors were inspected/tested and confirmed operational. Monitoring system was operational and set up was reviewed.	1	CUMBERLAND FARMS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144179&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144179&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	CUMBERLAND FARMS GULF #60944	1125 E MAIN ST STAMFORD, CT 06902	Closed	10/16/2013	The Department's inspector has determined that the leak monitor for piping was in alarm condition.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. Tanknology onsite 7/29/14, Product line tightness test passed, line leak detector test passed, impact valve test passed, monitoring system certification passed, wire replaced on tank 2 probe, all sensors at lowest point of secondary containment and all sensors tested operational, no liquid found in any secondary containment designed as a dry system	4	CUMBERLAND FARMS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142430&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142430&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	SAM'S GULF	315 N COLONY ST WALLINGFORD, CT 06492	Active	4/24/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump..	6	CURRY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155907&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155907&amp;type=ENFORCEMENT_ACTION</a>

Monroe	D M Service Center	505 Monroe Tpke Monroe, CT 06468	Active	3/3/2014	Annual Tightness Test for Pressurized Piping was not performed.. Release detection had not been performed.. The passing annual line leak detector test documentation was not maintained.. The passing annual line leak detector test had not been performed.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	16	D & M SERVICE CENTER, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151148&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151148&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	Dalene Hardwood Flooring, Inc.	45 NUTMEG RD S SOUTH WINDSOR, CT 06074	Closed	4/15/2014	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. Inspector Cosker onsite 5/2/14, tank has been removed	1	Dalene	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155011&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155011&amp;type=ENFORCEMENT_ACTION</a>
Windsor	Windor Shell	160 Windsor Ave Windsor, CT 06095	Active	5/9/2014	A closure report has not been maintained for this system permanently closed at this facility.. A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. A review of DEP records indicates that we do not have a registration form with current information.. A tank and/or integral piping installed on or after October 1, 2003 is not double-walled, or, the tank is double-walled but is not monitored interstitially.. Annual Tightness Test for Pressurized Piping was not performed.. Monthly records of interstitial monitoring records were not available.. Piping was repaired and no report of the repair was maintained.. Release detection had not been performed.. Repaired piping was not tested.. Sensor is not properly placed.. Significant operational compliance (SOC) violat...	47	Danby's Gasoline Marketers, Inc	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157693&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157693&amp;type=ENFORCEMENT_ACTION</a>

VERNON	Dania Food Mart 3	24 WEST ST VERNON, CT 06066	Active	10/18/2013	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Could not verify that the overfill protection device was installed at the required 90% alert or 95% shut off level. . Failure to cease discharge and remove and mitigate all contamination and impacted media and/or restore the environment and/or repair damage caused by the release and/or properly dispose of the discharged material and any contaminated substances.. Failure to conduct free product removal as specified in 106(f).. Failure to report a confirmed release to the implementing agency.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Release or discharge from a UST system.. The annual tightness test documentation was not available for the piping. . The monthly release detection test documentation from the automatic tank gauging device was not a...	37	Dania Foodmart, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142570&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142570&amp;type=ENFORCEMENT_ACTION</a>
Darien	DARIEN PLAZA LLC	85 Old Kings Hwy N Darien, CT 06820	Closed	3/25/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. . Per Inspector Bellmar USTs have been removed & NOV can be closed	3	DARIEN PLAZA LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152919&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152919&amp;type=ENFORCEMENT_ACTION</a>

Unionville	DEPOT PLACE TERMINAL, INC.	17 Depot Pl Unionville, CT 06085	Active	7/18/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Documentation of an annual passing cathodic protection test for piping was not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual tightness test documentation was not available for the piping. . The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not operational, therefore, corrosion protect...	10	DEPOT PLACE TERMINAL, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163276&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163276&amp;type=ENFORCEMENT_ACTION</a>
WATERFORD	MAGO POINT MARINA, LLC	20 1ST ST WATERFORD, CT 06385	Closed	7/1/2014	Failure to have required financial responsibility in the required amount(s).. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. Site re-visited by Inspector Bellmar on 8/7/14, site is SOC, per Inspector Bellmar NOV can be closed	3	DEW ENTERPRISES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162396&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162396&amp;type=ENFORCEMENT_ACTION</a>

TRUMBULL	DIGITAL 60 & 80 MERRITT LLC	80 MERRITT BLVD TRUMBULL, CT 06611	Active	3/19/2014	No Notice of Financial Responsibility on site.. Spill containment device was not present.. The owner or operator failed to immediately respond to a sump sensor alarm.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	7	DIGITAL 60 & 80 MERRITT, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152521&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152521&amp;type=ENFORCEMENT_ACTION</a>
PROSPECT	SHORT STOP CONVENIENCE STORE	20 UNION CITY RD PROSPECT, CT 06712	Active	5/12/2014	Documentation of an annual passing cathodic protection test for piping was not available.. Documentation showing that the monitors for tanks impressed current systems have been inspected every 30 days was not available.. Documentation showing that the monitors for the piping impressed current systems have been inspected every 30 days was not available.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	10	DILONETO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157610&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157610&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	WESTOVER SERVICE INC.	10 WEST AVE STAMFORD, CT 06902	Active	6/4/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required..	4	DIPIETRO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160066&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160066&amp;type=ENFORCEMENT_ACTION</a>
NORWICH	TAFTVILLE XTRAMART	186 NORWICH AVE NORWICH, 06360	Closed	5/15/2014	The dispenser sump contains liquid.. 6/9/14 nov archived per Lori saliby	1	DRAKE PETROLEUM COMPANY. INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158207&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158207&amp;type=ENFORCEMENT_ACTION</a>
THOMASTON	THOMASTON XTRA MART	196 PINE HILL RD THOMASTON, 06787	Closed	4/25/2014	A review of DEP records indicates that we do not have a registration form with current information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Recd registration form 5/27/14, Effective immediately, ECS Eclipse of Agawam Mass has been hired to complete monthly inspections at this station	2	DRAKE PETROLEUM COMPANY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156194&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156194&amp;type=ENFORCEMENT_ACTION</a>



NORWALK	AMOCO SERVICE STATION 516	452 WESTPORT AVE NORWALK, CT 06851	Active	3/17/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. The annual tightness test documentation was not available for the piping. . The owner or operator failed to submit to the Commissioner a statement signed by the installation contractor, certifying that the installation has been carried out in accordance with the UST Regulations. . The owner or operator has failed to pay the requisite UST system installation fee.. The passing annual line leak detector test documentation was not maintained..	12	DRAKE PETROLEUM COMPANY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152201&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152201&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	RICS	822 MAPLE AVE HARTFORD, CT 06114	Active	6/16/2014	A review of DEP records indicates that we do not have a registration form with current information.. Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Documentation of an annual passing cathodic protection test for piping was not available.. Failure to have required financial responsibility in the required amount(s).. No Notice of Financial Responsibility on site.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.....	13	DRJ., INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161214&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161214&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	RICS	822 MAPLE AVE HARTFORD, CT 06114	Closed	10/1/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Inspection on 06/16/2014 by inspector Mike Cosker . The inspection status was failed. 13 violation(s) found. New NOV Id: NOVUST-MC214-0057 issued, previous NOV being closed	2	DRJ., INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141786&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141786&amp;type=ENFORCEMENT_ACTION</a>

SOUTH WINDSOR	DZEN FARMS, INC.	244 BARBER HILL RD SOUTH WINDSOR, CT 06074	Active	4/15/2014	A review of DEP records indicates that we do not have a registration form with current information.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. There was no weekly reconciliation of inventory control figures to determine whether or not an abnormal loss or gain occurred..	5	DZEN PROPERTIES LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155012&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155012&amp;type=ENFORCEMENT_ACTION</a>
NORWALK	SHELL STATION #100044	216 EAST AVE NORWALK, CT 06855	Closed	12/16/2013	The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. Recd passing line tightness test results and passing LLD test results from CCMI on 2/3/14, CCMI tested on 1/9/14, ACE American Insurance, G21861388 006	7	EAST AVENUE SHELL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145564&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145564&amp;type=ENFORCEMENT_ACTION</a>
East Windsor	Warehouse Point Station 1	89 Bridge St East Windsor, CT 06088	Active	7/1/2014	A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The primary overfill device was not identified.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	4	EAST WINDSOR	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162353&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162353&amp;type=ENFORCEMENT_ACTION</a>
MONROE	EDGERTON INC.	786 MAIN ST MONROE, CT 06468	Closed	5/6/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Site submitted one month of daily/weekly inventory control records on 5/29/14	1	EDGERTON	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157086&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157086&amp;type=ENFORCEMENT_ACTION</a>
MANCHESTER	HOWELL CHENEY R.V.T. SCHOOL	791 MIDDLE TPKE W MANCHESTER, CT 06040	Active	6/11/2014	A closure report has not been maintained for this system permanently closed at this facility.. A review of DEP records indicates that we do not have a registration form with current information..	3	EDUCATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160848&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160848&amp;type=ENFORCEMENT_ACTION</a>

FAIRFIELD	SCHRIER BROTHERS, INC.	81 BLACK ROCK TPKE FAIRFIELD, CT 06825	Active	5/9/2014	A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. A review of DEP records indicates that we do not have a registration form with current information.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location..	3	EDWARD S. REINER TRUSTEE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157300&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157300&amp;type=ENFORCEMENT_ACTION</a>
Litchfield	DPS/DSP-TROOP "L"	452A Bantam Rd Litchfield, CT 06759	Active	7/16/2014	The fill cap comes in contact with the spill bucket cover..	1	Emergency Services and Public Protection	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163248&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163248&amp;type=ENFORCEMENT_ACTION</a>
Meriden	ESPOSITO'S AUTOMOTIVE LLC	652 W Main St Meriden, CT 06451	Active	10/1/2013	A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The release detection documentation was not available.. UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. .	8	ESPOSITO'S AUTOMOTIVE, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141787&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141787&amp;type=ENFORCEMENT_ACTION</a>
MIDDLEFIELD	MIDDLEFIELD SERVICE CENTER	165 JACKSON HILL RD MIDDLEFIELD, CT 06455	Closed	6/19/2014	A closure report has not been maintained for this system permanently closed at this facility.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. Recd notification form and closure report 9/18/14. Forwarded closure report to sas and registration form to steu	4	ESTATE OF LEOPOLD KOKOSZKA, SR.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161690&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161690&amp;type=ENFORCEMENT_ACTION</a>

NORWALK	FRED'S CAR WASH	498 WESTPORT AVE NORWALK, CT 06851	Active	7/15/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. The annual tightness test documentation was not available for the piping. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The passing annual line leak detector test documentation was not maintained.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program	10	EXXONMOBIL OIL CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163139&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163139&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	Tony's Turtle Gas, LLC	84 JOHN FITCH BLVD SOUTH WINDSOR, CT 06074	Closed	4/16/2014	VOID LLD & Line tightness test per Lori Saliby as site has continuous electronic interstitial monitoring and electronic automatic LLD, 0.2 & 0.1 test results passed, water intrusion is due to sumps missing gaskets, observation plugs broken & removed & no fasteners securing sump covers to lids. Bierman Services pumped out sumps, removed debris, repaired, installed new drop tube, installed sensor, mounting kit bracket. performed atg certification & lld functionality tests, all liquid sensors and probes passed.	16	EXXONMOBIL OIL CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155094&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155094&amp;type=ENFORCEMENT_ACTION</a>
HARWINTON	GRJH, INC.	207 BIRGE PARK RD HARWINTON, CT 06791	Closed	9/4/2014	Recd closure report removing three usts, report forwarded to sasu	23	FALCON PETROLEUM, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166307&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166307&amp;type=ENFORCEMENT_ACTION</a>
Niantic	GULF SERVICE STATION	326 Main St Niantic, CT 06357	Closed	4/8/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Recd email with monthly checklist on 6/23/14	1	FBAA LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154616&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154616&amp;type=ENFORCEMENT_ACTION</a>
GUILFORD	FOUR CORNERS SERVICE STATION	1500 BRANFORD RD. (ROUTE #80) GUILFORD, CT 06437	Closed	9/23/2014	The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. Per Inspector Bellmar's email on 12/1/14, the site had a/b operator information on revist and the nov can be closed	1	FESTA	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167577&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167577&amp;type=ENFORCEMENT_ACTION</a>

NEW FAIRFIELD	The Marina at Cottonwood Cove	6 CANDLEWOOD ISLE CAUSEWAY NEW FAIRFIELD, CT 06812	Active	7/17/2014	An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. . Failure to notify the implementing agency at least 30 days prior to beginning permanent closure of UST system components.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The release detection documentation was not available.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	7	First Black Ink, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163242&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163242&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	FIRST STUDENT, INC. #20684	124 SELLECK ST STAMFORD, CT 06902	Closed	3/13/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The dispenser sump contains liquid.. UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. 8/28/14 per Inspector Cosker NOV can be closed UST has been removed	4	FIRST STUDENT, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151912&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151912&amp;type=ENFORCEMENT_ACTION</a>
WATERTOWN	APPLE REHAB WATERTOWN	35 BUNKER HILL RD WATERTOWN, CT 06795	Closed	10/3/2013	Site submitted plan of correction 11/1/13, site removed tank 6/25/14, site assessment completed, one soil sample collected, report forwarded to sas on 1/5/15	5	FOLEY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142145&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142145&amp;type=ENFORCEMENT_ACTION</a>

LITCHFIELD	THE FORMAN SCHOOL, INC.	12 NORFOLK RD LITCHFIELD, CT 06759	Active	5/27/2014	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	4	FORMAN SCHOOL, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159274&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159274&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	SHELL SERVICE STATION	1059 N COLONY RD WALLINGFORD, CT 06492	Active	4/22/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The fill cover was broken or missing and must be repaired or replaced.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained..	13	FOUR STARS PLUS LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155584&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155584&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	FIRST STUDENT INC. #20605	11 BROWN HOUSE RD STAMFORD, CT 06902	Closed	6/4/2014	No Notice of Financial Responsibility on site.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. TXE-NY-100314-114 Liberty Surplus Insurance Group, 4/26/14-4/26/15; Liberty Auto & Electric cleaned & evaluated containment sumps on 6/10/14. Passing CP test results dated 7/18/13	3	FOWLER-HARTMAN LP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160067&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160067&amp;type=ENFORCEMENT_ACTION</a>
MIDDLETOWN	FRANK'S SERVICE CTR	159 MAIN STREET EXT MIDDLETOWN, CT 06457	Active	10/21/2013	Fittings were not cathodically protected.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	9	FRANK'S SERVICE CTR	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142792&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142792&amp;type=ENFORCEMENT_ACTION</a>

Deep River	FREMUT SERVICE	373 Main St Deep River, CT 06417	Closed	3/12/2014	The monthly release detection test documentation from the automatic tank gauging device was not available. . The piping cathodic protection was not tested within six (6) months of installation or within the last year.. Submitted passing cathodic test results for tanks & lines. N.E. Tank Services installed CSLD chip for ATG. Received passing test results for Reg. & Super tank.	3	FREMUT SERVICE, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151847&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151847&amp;type=ENFORCEMENT_ACTION</a>
Suffield	HILLTOP FARM	MAPLETON AVE Suffield, CT 06078	Closed	8/25/2014	(d)-1 tank beyond life expectancy. A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. Operation of substandard non-compliant UST system components beyond December 22, 1998.. UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. NOV being closed as issued to incorrect owner. Inspector and Supervisor Saliby notified.	5	Friends of the Farm at Hilltop, Inc	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165579&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165579&amp;type=ENFORCEMENT_ACTION</a>
WINDSOR	FUSCO BROS. INC.	866 MARSHALL PHELPS RD WINDSOR, CT 06095	Active	5/7/2014	A review of DEP records indicates that we do not have a registration form with current information.. Documentation of an annual passing cathodic protection test for piping was not available.. No Notice of Financial Responsibility on site.. The annual tightness test documentation was not available for the piping. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The passing annual line leak detector test documentation was not maintained.. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The three (3) year test documentation was not available for the suction piping..	24	FUSCO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157173&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157173&amp;type=ENFORCEMENT_ACTION</a>
WEST CORNWALL	Berkshire Store	103 CEMETERY HILL RD WEST CORNWALL, CT 06796	Closed	10/9/2013	BDL Environmental Consultants removed one 1000 gal DF ust, and two 4,000 gal gasoline usts on 12/30/13, case no. 2014-00764 assigned	25	GAGS Inc	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142376&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142376&amp;type=ENFORCEMENT_ACTION</a>



WALLINGFORD	GAYLORD HOSPITAL	50 GAYLORD FARM RD WALLINGFORD, CT 06492	Closed	11/18/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. Inventory control with tank tightness is not a sufficient release detection method for tanks greater than 10 years old.. Release detection had not been performed.. 6/13/14 Registration form & Operator Training information listed in ESRUST database	3	GAYLORD HOSPITAL, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144191&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144191&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	Gello Bros Inc.	477 N COLONY ST WALLINGFORD, CT 06492	Closed	4/23/2014	Fittings were not cathodically protected.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. EGC Enviro. Services pumped out all submersibles & fills. NE Tank Services cathodically protected eight flex hoses in three dispensers and submersibles and upgraded existing Petrosonic ATG unit with a Veeder Root 250. Passing 0.2 test results from ATG submitted. Monthly visual inspection checklist attached. OK'd by Inspector Bellmar.	11	GELLO BROTHERS, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155728&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155728&amp;type=ENFORCEMENT_ACTION</a>
OLD SAYBROOK	FOOD BAG #509	1652 BOSTON POST RD OLD SAYBROOK, CT 06475	Closed	6/3/2014	The dispenser sump contains liquid.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Contracted with Quality Compliance LLC to be their a/b operator (Matt Bassett certified a/b operator with Quality Compliance LLC) recertified the location employees at the C level. Site contracted with Quality Compliance LLC to perform their monthly inspections	2	GENERAL EQUITIES, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159880&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159880&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	FOOD BAG #521	326 S COLONY RD WALLINGFORD, CT 06492	Closed	4/24/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Site submitted monthly UST checklist on 4/29/14	1	GENERAL EQUITIES, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155906&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155906&amp;type=ENFORCEMENT_ACTION</a>
SUFFIELD	FOOD BAG #519	98 MOUNTAIN RD SUFFIELD, CT 06078	Closed	12/5/2013	No Notice of Financial Responsibility on site.. Read financial responsibility information 10/13/13. Nautilus Ins. CST200634700.	1	GENERAL EQUITIES, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145265&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145265&amp;type=ENFORCEMENT_ACTION</a>

TRUMBULL	GENE'S AUTOMOTIVE LLC	6567 MAIN ST TRUMBULL, CT 06611	Active	4/8/2014	A review of DEP records indicates that we do not have a registration form with current information.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s)	9	GENE'S AUTOMOTIVE LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154408&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154408&amp;type=ENFORCEMENT_ACTION</a>
South Windsor	Geisslers Shopping Center	965 Sullivan Ave South Windsor, CT 06074	Active	1/17/2014			GERSTEN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2148455&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2148455&amp;type=ENFORCEMENT_ACTION</a>
VERNON	Vernon Food Mart/Citgo	229 TALCOTTVILLE RD VERNON, CT 06066	Active	9/11/2014	Monthly records of interstitial monitoring records were not available.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	4	GETTY PROPERTIES CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166518&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166518&amp;type=ENFORCEMENT_ACTION</a>

NORWALK	GETTY STATION #00597	497 MAIN AVE NORWALK, CT 06851	Active	12/17/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The release detection documentation was not available.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accord...	13	GETTY REALTY CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145644&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145644&amp;type=ENFORCEMENT_ACTION</a>
EAST HARTFORD	GIBBS OIL	302 MAIN ST EAST HARTFORD, CT 06118	Closed	6/13/2014	The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. Compliance Testing Services Inc determined that surface water had entered the tank interstitial space through a damaged cap causing the interstitial space fluid to rise and activate the alarm. The cap to the interstitial riser was replaced, the interstitial fluid returned to the proper level and the interstitial sensor replaced.	1	GIBBS OIL COMPANY LIMITED PARTNERSHIP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161156&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161156&amp;type=ENFORCEMENT_ACTION</a>
EAST GRANBY	GIBBS OIL COMPANY	150 RAINBOW RD EAST GRANBY, CT 06026	Closed	9/17/2014	The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. 10/9/14 received 2014 notification form and a 2013 notification form which was never entered into ICM, American International Specialty Lines Insurance Co. ST 8087996 6/30/14-6/30/15	2	GIBBS OIL COMPANY, L.P.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167029&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167029&amp;type=ENFORCEMENT_ACTION</a>

STAMFORD	SUNNY MART (GLENBROOK)	527 GLENBROOK RD STAMFORD, CT 06906	Closed	8/14/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. Per email dated 12/31/14 from Inspector Cosker, the site forwarded him passing 0.2 gal test results and nov can be closed	5	GLEN LAKES ASSOCIATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164901&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164901&amp;type=ENFORCEMENT_ACTION</a>
VERNON	MOBIL S/S #13030	1292 HARTFORD TPKE VERNON, CT 06066	Active	9/11/2014	The fill cover was broken or missing and must be repaired or replaced..	1	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166517&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166517&amp;type=ENFORCEMENT_ACTION</a>
BRANFORD	MOBIL R/S #10750	48 LEETES ISLAND RD BRANFORD, CT 06405	Active	9/10/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The division inspector has determined that a piping sump sensor was not installed at the tank sump.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	13	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166640&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166640&amp;type=ENFORCEMENT_ACTION</a>
FARMINGTON	MOBIL S/S #01-PNG	244 FARMINGTON AVE FARMINGTON, CT 06032	Closed	8/15/2014	Recd notification form on 9/16/14 stating site has continuous electronic interstitial monitoring, site submitted passing sensor results, forwarded notification form to steu on 9/18/14, Recd notification form 9/16/14, updated fiscal mechanism (ACE American Insurance Co. 10/1/13-10/1/14), but operator training has expired, David Went called an LMM re: expired training	11	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165001&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165001&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	TORRINGTON MOBIL	332 E MAIN ST TORRINGTON, CT 06790	Closed	7/24/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. ECS Eclipse Agawam is a third party environmental consultant hired by Alliance to conduct the sites monthly inspections. Site submitted April, May & June 2014 monthly inspections	1	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163842&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163842&amp;type=ENFORCEMENT_ACTION</a>

FARMINGTON	MOBIL #933	843 FARMINGTON AVE FARMINGTON, CT 06032	Closed	7/24/2014	Alliance contracted with ECS Eclipse Agawam to perform monthly inspections. Submitted April, May, June 2014 copies will be kept on site. Alliance contracted with Gilbarco Veeder Root (Greensboro NC) to continuously monitor the sites tanks, including the used oil tank, using CSLD. CSLD ran continuously for last 41 months. Site had a/b operators retrained valid 8/13/14-8/13/15	3	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163843&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163843&amp;type=ENFORCEMENT_ACTION</a>
NORWALK	GLOBAL MONTELLO GROUP #	93 MAIN ST NORWALK, CT 06851	Active	7/16/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The owner or operator has rendered inoperable a sensor in a new under-dispenser containment sump and/or a new piping containment sump. .	5	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163202&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163202&amp;type=ENFORCEMENT_ACTION</a>
BROOKFIELD	MOBIL SERVICE STATION #01-HMO	818 FEDERAL RD BROOKFIELD, CT 06804	Active	6/19/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities	1	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161693&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161693&amp;type=ENFORCEMENT_ACTION</a>
NEW FAIRFIELD	NEW FAIRFIELD S/C	94 STATE ROUTE 37 NEW FAIRFIELD, CT 06812	Active	5/28/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities	1	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159275&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159275&amp;type=ENFORCEMENT_ACTION</a>
MANCHESTER	Manchester Sunoco	330 TOLLAND TPKE MANCHESTER, CT 06042	Closed	5/27/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The fill cover was broken or missing and must be repaired or replaced.. TMC ENvironmental removed liquid from sumps. A. Govoni Backhoe Service installed a new fill cover on 5/24/14. Liberty Auto & Electric installed a new manhole cover on 6/24/14	4	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158948&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158948&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	GLOBAL	570 CENTER ST WALLINGFORD, CT 06492	Closed	5/16/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). Alliance dispatched Jones & Frank Inc. to calibrate each dispensers meters. Work was completed on 6/12/14, the adjustments should bring reconciliation into compliance state. Site submitted inventory reconciliation forms from before calibration and week of calibration. Further investigation will be conducted if the calibration does not explain the overages. Approved by Phil Wilde 9/30/14	2	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158364&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158364&amp;type=ENFORCEMENT_ACTION</a>

PROSPECT	EXXON MOBIL #13850	2 NEW HAVEN RD PROSPECT, CT 06712	Closed	4/30/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. TMC Environmental pumped out and tested sumps. Photos of cleaned sump and passing sump test results enclosed.	2	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156509&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156509&amp;type=ENFORCEMENT_ACTION</a>
VERNON	CARPENTER'S MOBIL (MOBIL #980)	447 HARTFORD TPKE VERNON, CT 06066	Closed	4/29/2014	The annual tightness test documentation was not available for the piping. . The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The passing annual line leak detector test documentation was not maintained.. Inspection on 05/06/2014 by inspector Mike Cosker .The inspection status was passed.	7	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156305&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156305&amp;type=ENFORCEMENT_ACTION</a>
AVON	MOBIL	411 W MAIN ST AVON, CT 06001	Closed	4/17/2014	The Release Detection Method was not maintained in accordance with the Manufacturer's Instructions.. 3/24/14 PES on site to service & test the sites release detection method. The tech re-set sensors, installed pull strings, upon completion of adjustments all tests concluded normal	1	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155381&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155381&amp;type=ENFORCEMENT_ACTION</a>
TRUMBULL	GLOBAL MONTELLO GROUP	111 MONROE TPKE TRUMBULL, CT 06611	Closed	4/10/2014	Liberty Auto & Electric investigated release. It was determined to be the result of a faulty nozzle which was replaced. All liquid was removed from the sump by TMC Environmental on 4/18/14. Upon removing liquid Liberty was dispatched to further investigated the liquid accumulation. It was determined water infiltration doesn't come from any pipe entries but from the top, building up over sump cover. Alliance to evaluate and determine necessary corrective action. Eclipse hired to perform sites monthly inspections, 4 months of monthly inspections submitted. OK to close per Lori Saliby 1/30/14	3	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154848&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154848&amp;type=ENFORCEMENT_ACTION</a>
TRUMBULL	MOBIL OIL CORPORATION	2775 NICHOLS AVE TRUMBULL, CT 06611	Closed	4/10/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Lori Saliby Ok'd Eclipse monthly checklist on 5/15/14. Site included four months of Eclipse monthly visual inspections. Will keep forms on site.	1	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154850&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154850&amp;type=ENFORCEMENT_ACTION</a>

NEW LONDON	NEW LONDON CITGO	447 WILLIAMS ST NEW LONDON, CT 06320	Active	4/4/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	6	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154150&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154150&amp;type=ENFORCEMENT_ACTION</a>
TRUMBULL	MOBIL S/S# 01-LG2	950 WHITE PLAINS RD TRUMBULL, CT 06611	Closed	3/27/2014	The release detection documentation was not available.. TMC Environmental pumped the tank to less than 1", locked fill cap and registered the ust as temporarily out of service	1	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153229&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153229&amp;type=ENFORCEMENT_ACTION</a>
PLAINFIELD	PLAINFIELD GULF	721 NORWICH RD PLAINFIELD, CT 06374	Active	3/17/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Liquid has accumulated in a sump and hydrosttic testing is required to determine whether or not the sump is liquid tight.This procedure has prior written approval by this agency.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump..	5	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152212&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152212&amp;type=ENFORCEMENT_ACTION</a>
BLOOMFIELD	BLOOMFIELD SHELL	47 JEROME AVE BLOOMFIELD, CT 06002	Closed	3/17/2014	The annual test documentation was not available for the piping leak monitoring equipment and devices. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The passing annual line leak detector test documentation was not maintained.. The passing annual line leak detector test had not been performed.. The release detection documentation was not available..	15	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152194&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152194&amp;type=ENFORCEMENT_ACTION</a>



GLASTONBURY	GLASTONBURY GLOBAL	2997 MAIN ST GLASTONBURY, CT 06033	Closed	2/28/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. TMC Environmentatl pumped out sumps. Fuller installations confirmed each of the sump sensors were correctly positioned and functional. They conducted a .2 test which passed. Upon completeion the AT6 read "all functions normal". Crompco performed petro tight line testing all passed.	8	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150925&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150925&amp;type=ENFORCEMENT_ACTION</a>
SIMSBURY	MOBIL SERVICE STATION #01-QQC	955 HOPMEADOW ST SIMSBURY, CT 06070	Closed	2/27/2014	The annual test documentation was not available for the piping leak monitoring equipment and devices. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. Essam brought required documents to DEEP on 3/13/14	13	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150972&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150972&amp;type=ENFORCEMENT_ACTION</a>
SIMSBURY	MOBIL	404 HOPMEADOW STREET SIMSBURY, CT 06070	Closed	2/27/2014	The owner or operator failed to immediately respond to a sump sensor alarm.. Diesel fuel sump sensor (s6) in alarm since 2-22-14 when call went in for service request (per onsite file). At time of inspection the presumed diesel sump (s6) was opened and found to be free of liquids. NOV to be closed per Lori Saliby 6/9/2014	1	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150975&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150975&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	WESTON STREET SUNOCO	125 WESTON ST HARTFORD, CT 06120	Active	2/26/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.	2	GLOBAL MONTELLO GROUP CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150660&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150660&amp;type=ENFORCEMENT_ACTION</a>

EAST HAMPTON	G & S SERVICE INC.	100 MAIN ST EAST HAMPTON, CT 06424	Active	3/10/2014	Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Documentation showing that the monitors for tanks impressed current systems have been inspected every 30 days was not available.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The tanks cathodic protection documentation not maintained.. The tanks cathodic protection was not operational, therefore, corrosion protection must be repaired or system permanently closed.. The tanks cathodic protection was not tested within six (6) months of in...	20	GOFF	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151678&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151678&amp;type=ENFORCEMENT_ACTION</a>
ORANGE	CITGO ORANGE LLC	347 BOSTON POST RD ORANGE, CT 06477	Active	3/25/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required..	4	GOMOSTA	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152931&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152931&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	COUNTY DISTRIBUTORS INC	1510 JOHN FITCH BLVD SOUTH WINDSOR, CT 06074	Active	10/21/2013	Documentation of an annual passing cathodic protection test for piping was not available.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Suction piping without continuous monitoring with a check valve at the tank is required to be tightness tested every three years. Safe suction piping is required to be tested annually the last three (3) years of its life expectancy.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	7	Gordon	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142639&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142639&amp;type=ENFORCEMENT_ACTION</a>

WINDSOR LOCKS	FAS MART 306	269 MAIN ST WINDSOR LOCKS, CT 06096	Closed	9/10/2014	Compliance Statement states 9/26/14 new flapper overflow device installed, attached work order, site submitted monthly inspection checklist, 10/30/14 Richard Negrete & Joseph Swazey are the a/b operators, date of class 7/27/14 & 8/8/14 date of nov 9/10/14, ok to close per Lori Saliby	3	GPM INVESTMENTS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166450&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166450&amp;type=ENFORCEMENT_ACTION</a>
DURHAM	FAS MART 313	384 MAIN ST DURHAM, CT 06422	Active	8/18/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The tanks cathodic pr...	16	GPM INVESTMENTS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165040&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165040&amp;type=ENFORCEMENT_ACTION</a>
WESTBROOK	FAS MART 317	1309 BOSTON POST RD WESTBROOK, CT 06498	Active	8/11/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	7	GPM INVESTMENTS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164691&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164691&amp;type=ENFORCEMENT_ACTION</a>

FARMINGTON	Fas Mart 330	1387 FARMINGTON AVE FARMINGTON, CT 06032	Active	7/16/2014	A closure report has not been maintained for this system permanently closed at this facility.. Failure to maintain records of the excavation zone assessment performed at the time of UST system permanent closure for at least 5 years.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has performed inadequately, the requisite m...	11	GPM INVESTMENTS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163244&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163244&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	FAS MART 320	720 N COLONY RD WALLINGFORD, CT 06492	Closed	4/22/2014	Service Station Equipment onsite 5/12/14 pumped out RUL & DSL spill buckets, Site submitted daily, weekly & monthly checklists for April, may thru 5/12/14, Certificate of Insurance: American International Specialty Lines Insurance, PLS 14264967, forwarded to steu on 9/30/14,	4	GPM INVESTMENTS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155585&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155585&amp;type=ENFORCEMENT_ACTION</a>
VERNON	FAS MART 308	506 TALCOTTVILLE RD VERNON, CT 06066	Active	4/16/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid..	5	GPM INVESTMENTS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155093&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155093&amp;type=ENFORCEMENT_ACTION</a>
SUFFIELD	FAS MART 310 (VELERO)	801 THOMPSONVILLE RD SUFFIELD, CT 06078	Active	12/5/2013	Release detection had not been performed.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105..	6	GPM INVESTMENTS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145266&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145266&amp;type=ENFORCEMENT_ACTION</a>

MERIDEN	FAS MART 314	1101 E MAIN ST MERIDEN, CT 06450	Closed	11/6/2013	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Service Station Equipment on site 11/22/13, containment lids were cracked, hydro tested gas/df sumps	2	GPM INVESTMENTS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143638&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143638&amp;type=ENFORCEMENT_ACTION</a>
Branford	GVO / EZ SHOP	30 Main St Branford, CT 06405	Closed	9/18/2014	Site submitted registration form, including a/b operator information (Laila Gilani), and completed monthly checklists	3	GREEN VALLEY OIL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166933&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166933&amp;type=ENFORCEMENT_ACTION</a>
WEST HARTFORD	GVO #6850	210 SOUTH ST WEST HARTFORD, CT 06110	Active	4/8/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Failure to have required financial responsibility in the required amount(s).. No Notice of Financial Responsibility on site.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visua...	13	GREEN VALLEY OIL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154390&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154390&amp;type=ENFORCEMENT_ACTION</a>
NORWALK	GETTY STATION #00597	497 MAIN AVE NORWALK, CT 06851	Closed	12/12/2013	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator of an UST system has failed to designate Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. The release detection documentation was not available.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. NOV is being closed and re-issued to the correct owner as novust-gb13-0136	12	GREEN VALLEY OIL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145472&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145472&amp;type=ENFORCEMENT_ACTION</a>

STAMFORD	GVO #91224	250 HOPE ST STAMFORD, CT 06906	Closed	11/15/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. 12/18/13 recd passing CP test results dated 12/10/13	3	GREEN VALLEY OIL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144076&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144076&amp;type=ENFORCEMENT_ACTION</a>
MIDDLETOWN	GVO #06852	578 S MAIN ST MIDDLETOWN, CT 06457	Active	10/30/2013	The monthly release detection test documentation from the automatic tank gauging device was not available.	3	GREEN VALLEY OIL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143305&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143305&amp;type=ENFORCEMENT_ACTION</a>
NORTH FRANKLIN	7-ELEVEN, INC. # 32517	15 ROUTE 32 NORTH FRANKLIN, CT 06254	Closed	10/3/2013	Documentation showing that the monitors for tanks impressed current systems have been inspected every 30 days was not available.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. No Notice of Financial Responsibility on site.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd by Kelly McShea on 10/31/13 as part of the NOV followup project.	17	GREEN VALLEY OIL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141915&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141915&amp;type=ENFORCEMENT_ACTION</a>
NORTH FRANKLIN	Franklin BP	62 ROUTE 32 NORTH FRANKLIN, CT 06254	Closed	10/3/2013	The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. This NOV was clsd by Kelly McShea on 10/10/13 as part of the NOV followup project.	6	GREEN VALLEY OIL, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141916&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141916&amp;type=ENFORCEMENT_ACTION</a>
EAST HARTFORD	Founder's Plaza Sunoco	131 DARLIN ST EAST HARTFORD, CT 06108	Active	4/30/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid..	11	Gregary, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156512&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156512&amp;type=ENFORCEMENT_ACTION</a>

DURHAM	GRIPPO'S LLC	349 MAIN ST DURHAM, CT 06422	Closed	11/18/2013	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project.	9	GRIPPO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144192&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144192&amp;type=ENFORCEMENT_ACTION</a>
GRISWOLD	GRISWOLD SUNOCO	659 VOLUNTOWN RD GRISWOLD, CT 06351	Active	10/29/2013	Could not verify that the overfill protection device was installed at the required 90% alert or 95% shut off level. . The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The passing annual line leak detector test documentation was not maintained..	7	GRISWOLD S & P, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143240&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143240&amp;type=ENFORCEMENT_ACTION</a>
MERIDEN	Meriden Service Center	1801 N BROAD ST MERIDEN, CT 06450	Active	11/5/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. No Notice of Financial Responsibility on site.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The passing annual line leak detector test documentation was not maintained..	10	GRJH, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143571&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143571&amp;type=ENFORCEMENT_ACTION</a>



GROTON	GROTON CITGO	1004 POQUONNOCK RD GROTON, CT 06340	Active	12/3/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. UST owners or operators have failed to demonstrate that financial respon...	18	Gronin	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144872&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144872&amp;type=ENFORCEMENT_ACTION</a>
DURHAM	DICK'S SUNOCO	22 NEW HAVEN RD DURHAM, CT 06422	Active	8/18/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly,Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual tightness test documentation was not available for the piping. . The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained.. The tanks cathodic pr...	15	GURCZYNSKI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165039&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165039&amp;type=ENFORCEMENT_ACTION</a>
NIANTIC	GUY'S, INC.	90 W MAIN ST NIANTIC, CT 06357	Active	4/7/2014	The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	4	GUY'S INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154340&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154340&amp;type=ENFORCEMENT_ACTION</a>

NEW BRITAIN	HAJAN LLC	788 W MAIN ST NEW BRITAIN, CT 06053	Active	12/2/2013	No Notice of Financial Responsibility on site.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	11	HAJAN LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144790&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144790&amp;type=ENFORCEMENT_ACTION</a>
MADISON	HAMMONASSET SERVICE STATION INC.	905 BOSTON POST RD MADISON, CT 06443	Closed	3/11/2014	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Passing CP test results received	3	HAMMONASSET SERVICE STATION, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151731&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151731&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	On the Go	180 SULLIVAN AVE SOUTH WINDSOR, CT 06074	Closed	11/6/2013	No Notice of Financial Responsibility on site.. Submitted certification of Financial Responsibility on 3/14/14.	1	Hannah Enterprises	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143641&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143641&amp;type=ENFORCEMENT_ACTION</a>
WINDSOR	HARRIS PETROLEUM, LLC.	314 WINDSOR AVE WINDSOR, CT 06095	Active	5/7/2014	A review of DEP records indicates that we do not have a registration form with current information.. Annual Tightness Test for Pressurized Piping was not performed.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual tightness test documentation was not available for the piping. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The passing annual line leak detector test documentation was not maintained.. The passing annual line leak detector test had not been performed.. The release detection documentation was not availab...	20	Harris Petroleum, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157174&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157174&amp;type=ENFORCEMENT_ACTION</a>

BLOOMFIELD	SHELL FACILITY #136283	991 BLUE HILLS AVE BLOOMFIELD, CT 06002	Active	3/25/2014	A review of DEP records indicates that we do not have a registration form with current information.. Monthly records of interstitial monitoring records were not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The overfill protection device was not maintained in good working order.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an app..	12	HENDEL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152928&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152928&amp;type=ENFORCEMENT_ACTION</a>
STONINGTON	Stonington Village Shell	522 STONINGTON RD CORNER OF WATER ST. STONINGTON, CT 06378	Closed	3/19/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. On 3/20/14 a Hendel's service technician pumped out the STP sump and changed the function element on top of the sump. The sump is now dry.	1	HENDEL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152410&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152410&amp;type=ENFORCEMENT_ACTION</a>
Old Saybrook	Old Saybrook Henny Penny Shell	1090 OLD BOSTON POST ROAD Old Saybrook, CT 06745	Closed	4/8/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. NOV has been archived per Lori Saliby ; 6/13/14 NOV closed. On 4/10/14 Hendels servicemen removed all the silt from the STP sumps (A1R1 & B1R1)	2	HENDEL FAMILY TRUST LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154381&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154381&amp;type=ENFORCEMENT_ACTION</a>

SOUTHURY	HERITAGE VILLAGE MASTER ASSOC. INC.	719 E HILL RD SOUTHURY, CT 06488	Closed	10/22/2013	Monthly records of interstitial monitoring records were not available.. Release detection had not been performed.. The release detection documentation was not available.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. The 10,000 gal. gas tank was removed by BDL Consultants on 11/22/13. There was evidence of a release. Results were below CTDEP RSRs for a GA area. Report forwarded to SASU. Registration form recd 3/6/14	4	HERITAGE VILLAGE MASTER ASSOCIATION, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142767&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142767&amp;type=ENFORCEMENT_ACTION</a>
WINDSOR LOCKS	THE HERTZ RENT A CAR	2 SCHOEPHOESTER RD WINDSOR LOCKS, CT 06096	Active	4/9/2014	A review of DEP records indicates that we do not have a registration form with current information.. Monthly records of interstitial monitoring records were not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s)..	6	HERTZ CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154467&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154467&amp;type=ENFORCEMENT_ACTION</a>
EAST HARTFORD	HESS STATION #07216	530 MAIN ST EAST HARTFORD, CT 06108	Closed	5/19/2014	Rec notification form 10/29/14 stating site ownership has changed, new owner marathon Petroleum Co., NOV being closed, Inspector Cosker notified 12/18/14	12	HESS CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158450&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158450&amp;type=ENFORCEMENT_ACTION</a>
NORWICH	HESS STATION, #07211	720 BOSWELL AVE NORWICH, CT 06360	Closed	4/14/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Liquid removed from sump on 4/15/14	1	HESS CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154929&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154929&amp;type=ENFORCEMENT_ACTION</a>
EAST HAVEN	HESS 07502	24 FRONTAGE RD EAST HAVEN, CT 06512	Closed	11/14/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project.	5	HESS CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144787&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144787&amp;type=ENFORCEMENT_ACTION</a>

TRUMBULL	LAKE & MAIN SERVICE CENTER	6149 MAIN ST TRUMBULL, CT 06611	Active	4/2/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	5	HIBYAN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153929&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153929&amp;type=ENFORCEMENT_ACTION</a>
NEW FAIRFIELD	GIL'S GULF	#7 ROUTE 37 & ROUTE 39 NEW FAIRFIELD, CT 06812	Active	7/17/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). .	17	HICKS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163243&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163243&amp;type=ENFORCEMENT_ACTION</a>
WESTBROOK	WESTBROOK EXXON	198 ESSEX RD WESTBROOK, 06498	Closed	8/11/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. 8/12/14 TMC Environmental onsite, water pumped out of dispensers/sumps/fills as needed, alarm cleared	2	HIGH MART, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164690&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164690&amp;type=ENFORCEMENT_ACTION</a>

KENSINGTON	HOGUE REPAIR	1406 CHAMBERLAIN HWY KENSINGTON, CT 06037	Active	3/24/2014	A review of DEP records indicates that we do not have a registration form with current information.. Failure to have required financial responsibility in the required amount(s).. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.	9	HOGUE REPAIRS LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152710&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152710&amp;type=ENFORCEMENT_ACTION</a>
MANCHESTER	HOLLYWOOD Service & Sales, LLC	342 E CENTER ST MANCHESTER, CT 06040	Closed	4/21/2014	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. NOV archived by Lori Saliby on 6/9/2014	1	Hollywood Service & Sales, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155362&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155362&amp;type=ENFORCEMENT_ACTION</a>
SOUTHURY	LAKESIDE MARINA LLC	216 LEE FARM DR SOUTHURY, CT 06488	Active	5/21/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). .	5	HORNBECKER	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158734&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158734&amp;type=ENFORCEMENT_ACTION</a>

New London	Huntington Towers	147-149 Huntington Street New London, CT 06320	Active	7/2/2014	Failure to have required financial responsibility in the required amount(s).. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). .	6	HUNTINGTON TOWERS PRESERVATION ASSOCIATES LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162485&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162485&amp;type=ENFORCEMENT_ACTION</a>
WATERBURY	VALLEY AUTO BODY SHOP LLC.	990 HUNTINGDON AVE WATERBURY, CT 06704	Active	11/8/2013	A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The passing annual line leak detector test had not been performed.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. UST owners and/or operators are required to report to the implementing agency, at (860) 424-3338 and within twenty-four (24)hours, actual or suspected releases from UST systems..	15	HYCHKO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143803&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143803&amp;type=ENFORCEMENT_ACTION</a>



TORRINGTON	GIBBS OIL COMPANY, LP	882 E MAIN ST TORRINGTON, CT 06790	Active	6/23/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). .	10	HZM PETROLEUM CORP.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161872&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161872&amp;type=ENFORCEMENT_ACTION</a>
GRANBY	IMPERIAL NURSERIES	85 FLOYDVILLE RD GRANBY, CT 06035	Closed	10/25/2013	Release detection had not been performed.. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project.	2	IMPERIAL NURSERIES, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143070&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143070&amp;type=ENFORCEMENT_ACTION</a>
ELLINGTON	DANIA FOODMART LLC	83 WEST RD ELLINGTON, CT 06029	Closed	10/18/2013	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. This NOV was clsd by Kelly McShea on 12/3/13 as part of the NOV followup project.	10	INA PETROLEUM COMPANY INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142569&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142569&amp;type=ENFORCEMENT_ACTION</a>
OLD SAYBROOK	CLASSIC CARRIAGE AUTO WASH	351 BOSTON POST RD OLD SAYBROOK, CT 06475	Closed	6/4/2014	site submitted 6/24/14 CCMI passing LLD test results and passing CP test results for tanks	7	INJUN LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160224&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160224&amp;type=ENFORCEMENT_ACTION</a>

DERBY	BORRELLI'S FUEL	190 SEYMOUR AVE DERBY, CT 06418	Active	8/19/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. A review of DEP records indicates that we do not have a registration form with current information.. The owner or operator failed to submit to the Commissioner a statement signed by the installation contractor, certifying that the installation has been carried out in accordance with the UST Regulations. . The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to pay the requisite UST system installation fee.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s)..	8	JAB, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165042&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165042&amp;type=ENFORCEMENT_ACTION</a>
BLOOMFIELD	THE JACK FARRELLY CO.	97 OLD POQUONOCK RD BLOOMFIELD, CT 06002	Active	5/15/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. ATG is not checking portion of the tank that routinely contains product (for some models, the tank level can be 14%).. Documentation of an annual passing cathodic protection test for piping was not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owne...	15	JACK FARRELLY CO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158472&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158472&amp;type=ENFORCEMENT_ACTION</a>

GUILFORD	GUILFORD SHELL	490 BOSTON POST RD GUILFORD, CT 06437	Active	9/22/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery..	8	JAMES L. MCNEIL REVOCABLE TRUST	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167101&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167101&amp;type=ENFORCEMENT_ACTION</a>
NORTH GROSVENORDALE	JDS GASWAY	440 RIVERSIDE DR NORTH GROSVENORDALE, CT 06255	Active	8/15/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	13	JDS GASWAY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164970&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164970&amp;type=ENFORCEMENT_ACTION</a>
MIDDLETOWN	J & S Enterprise, LLC	1075 NEWFIELD ST MIDDLETOWN, CT 06457	Active	8/8/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	12	JDS GASWAY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164605&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164605&amp;type=ENFORCEMENT_ACTION</a>
HADDAM	JD Food Mart LLC/JDS Gasway LLC	1618 SAYBROOK RD HADDAM, CT 06438	Closed	7/7/2014	A review of DEP records indicates that we do not have a registration form with current information.. Registration form recd 7/11/14, forwarded to sasu & steu on 9/8/14	1	JDS GASWAY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162728&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162728&amp;type=ENFORCEMENT_ACTION</a>

WALLINGFORD	ZOZ 1ST LLC	68 N TURNPIKE RD WALLINGFORD, CT 06492	Active	5/20/2014	A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Fittings were not cathodically protected.. Release detection had not been performed.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to pay the requisite UST system installation fee.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	17	JOHNSON	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159028&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159028&amp;type=ENFORCEMENT_ACTION</a>
CLINTON	JON'S MALS GAS LLC	212 E MAIN ST CLINTON, CT 06413	Closed	5/6/2014	The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. Recd passing LLD, line tightness testing and cathodic protection testing on 7/8/14 from NE Tank Services	6	JON'S MAL'S GAS LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157065&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157065&amp;type=ENFORCEMENT_ACTION</a>
Ledyard	JOSHUA'S LIMOSINE SERVICE	172 STODDARDS WHARF ROAD Ledyard, CT 06339	Active	7/9/2014	A review of DEP records indicates that we do not have a registration form with current information.. Failure to have required financial responsibility in the required amount(s).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is ...	11	JOSHUA'S LIMOSINE SERVICE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162839&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162839&amp;type=ENFORCEMENT_ACTION</a>

WATERBURY	CITGO FOOD MART	235 W MAIN ST WATERBURY, CT 06702	Active	7/17/2014	A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. There is one or more underground storage tank piping system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location..	12	JOT LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163225&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163225&amp;type=ENFORCEMENT_ACTION</a>
NORWICH	TRADING COVE SUNOCO	688 W THAMES ST NORWICH, CT 06360	Closed	5/8/2014	Failure to have required financial responsibility in the required amount(s).. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator ... Recd notification form 9/2/14 including fiscal mechanism (Ace Insurance Co), recd passing CP test results dated 1/9/14, site has less than 1" of product in tanks and submitted the monthly readings posted for our inspectors	6	K BROTHERS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157278&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157278&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	EAST SIDE SERVICE	66 WOODHOUSE AVE WALLINGFORD, CT 06492	Closed	10/1/2013	The annual tightness test documentation was not available for the piping. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The passing annual line leak detector test documentation was not maintained.. This NOV was clsd by Kelly McShea on 190/31/13 as part of the NOV followup project.	7	KELSEYS PROPERTY MANAGEMENT LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141788&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141788&amp;type=ENFORCEMENT_ACTION</a>
MIDDLETOWN	In and Out	237 S MAIN ST MIDDLETOWN, CT 06457	Closed	5/12/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Site removed water and debris from spill containment manhole and sumps. Disposed of material, tightened boots inside sump, and cleaned around seals.	2	Khalifa	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157684&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157684&amp;type=ENFORCEMENT_ACTION</a>

DAYVILLE	Twin Stop (Formerly Dayville Fuels)	1094 N MAIN ST DAYVILLE, CT 06241	Closed	6/3/2014	Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Site submitted passing cathodic protection results, a/b operator training information.,	2	KING	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159862&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159862&amp;type=ENFORCEMENT_ACTION</a>
WATERFORD	KOBYLUCK READY-MIX, INC.	24 INDUSTRIAL DR WATERFORD, CT 06385	Closed	6/25/2014	06/27/2014 Inspector: Gary Bellmar - Did partial inspection of site. Site had been red tagged on 6/25/2014. Pursuant to agreement reached at hearing on 6/27/2014 - 10 AM, 79 Elm St., Hartford - inspector Bellmar removed red tags to allow owner to continue to progress towards compliance. Per Inspector Bellmar on 10/2/14 site has come into compliance and nov can be closed	9	KOBYLUCK READY-MIX, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162107&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162107&amp;type=ENFORCEMENT_ACTION</a>
SUFFIELD	KRUPA OIL COMPANY	827 THOMPSONVILLE RD SUFFIELD, CT 06078	Active	8/25/2014	No Notice of Financial Responsibility on site.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The piping corrosion (cathodic) protection system was not operational, therefore, must be repaired or system permanently closed.. The tanks cathodic protection was not operational, therefore, corrosion protection must be repaired or system permanently closed.. The UST system is in operation ...	18	KRUPA OIL COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165578&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165578&amp;type=ENFORCEMENT_ACTION</a>
GREENWICH	GLENVILLE SHELL	222 GLENVILLE RD GREENWICH, CT 06831	Closed	5/1/2014	Site removed water from sumps, cleaned and sealed sumps. Site had company snake new wire from probe to building, tightened flanges, bolts, replaced gasket and tested. 5/13/14 Inspector Cosker met with Tony at his request. Addressed the water issue and NOV concerns. his reconciliation, is above & beyond, looks good. No violations found.	8	LACOFF CAPITAL PARTNERS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156606&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156606&amp;type=ENFORCEMENT_ACTION</a>

CANTON	CANTON CITGO #84635	232 ALBANY TURNPIKERT 44 CANTON, CT 06019	Active	10/28/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. Annual Tightness Test for Pressurized Piping was not performed.. Could not verify that the overfill protection device was installed at the required 90% alert or 95% shut off level. . Monthly records of interstitial monitoring records were not available.. Release detection had not been performed.. The annual test documentation was not available for the piping leak monitoring equipment and devices. . The annual tightness test documentation was not available for the piping. . The release detection documentation was not available.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the ...	22	Ladd Management, Inc	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143130&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143130&amp;type=ENFORCEMENT_ACTION</a>
Thomaston	CLOCKWORK COUNTRY STORE	9 N Main St Thomaston, CT 06787	Closed	9/12/2014	Registration form filed lists a/b operators and financial mechanism, Recd passing 0.2 test results T1, T2 & T3, dated 9/21/14, Environshield 7/22/14: passing cathodic protection test tank results, passing line test results	8	LAFAYETTE REALTY, INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166720&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166720&amp;type=ENFORCEMENT_ACTION</a>
PROSPECT	PROSPECT SUNOCO	68 WATERBURY RD PROSPECT, CT 06712	Closed	4/30/2014	The monthly release detection test documentation from the automatic tank gauging device was not available. . Recd passing 0.2 test results for tanks A1R1 & D4R1 on 5/14/14	2	LAFAYETTE REALTY, INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156510&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156510&amp;type=ENFORCEMENT_ACTION</a>
WETHERSFIELD	LAMORE'S GULF STATION	475 SILAS DEANE HWY WETHERSFIELD, CT 06109	Active	10/17/2013	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	6	LAMORE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142514&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142514&amp;type=ENFORCEMENT_ACTION</a>



WINDSOR	SHELL SERVICE STATION	1010 KENNEDY RD WINDSOR, CT 06095	Active	5/8/2014	A review of DEP records indicates that we do not have a registration form with current information.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The release detection documentation was not available.. The UST system is in operation or is temporarily out-of-service ...	23	Lara Market, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157297&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157297&amp;type=ENFORCEMENT_ACTION</a>
MANCHESTER	MANCHESTER IRVING	318 - 330 ADAMS ST MANCHESTER, CT 06040	Active	9/22/2014	Annual Tightness Test for Pressurized Piping was not performed.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The passing annual line leak detector test had not been performed..	9	LEONARD E. BELCHER, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167067&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167067&amp;type=ENFORCEMENT_ACTION</a>
New Milford	EAST STREET (NEW MILFORD) CITGO	4 East St New Milford, CT 06776	Closed	4/11/2014	Site submitted monthly checklists, individual store managers will now receive monthly inspection reminders by email and monthly management summaries will be distributed to managers to confirm inspections and any follow up activities. Water pumped out, spill buckets wiped clean, new fill cover gaskets installed.	3	LEONARD E. BELCHER, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154849&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154849&amp;type=ENFORCEMENT_ACTION</a>

LAKEVILLE	Lime Rock Park	497 LIME ROCK RD LAKEVILLE, CT 06039	Active	10/9/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form with current information.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The release detection documentation was not available..	10	Lime Rock Park LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142372&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142372&amp;type=ENFORCEMENT_ACTION</a>
WOLCOTT	NORTHEND LIQOUR	1496-1500 WOLCOTT RD WOLCOTT, CT 06716	Closed	10/1/2013	(d)-1 tank beyond life expectancy. A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. . Failure to cease discharge and remove and mitigate all contamination and impacted media and/or restore the environment and/or repair damage caused by the release and/or properly dispose of the discharged material and any contaminated substances.. Failure to have required financial responsibility in the required amount(s).. Failure to maintain records of the excavation zone assessment performed at the time of UST system permanent closure for at least 5 years.. Failure to notify the implementing agency at least 30 days prior to beginning permanent ...	20	LOFGREEN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141767&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141767&amp;type=ENFORCEMENT_ACTION</a>

GROTON	Jo's Convenient Store	528 GOLD STAR HWY GROTON, CT 06340	Active	3/24/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump..	4	LORENZ	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152786&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152786&amp;type=ENFORCEMENT_ACTION</a>
LEDYARD	LOU'S ENTERPRISES, INC.	748 COLONEL LEDYARD HWY LEDYARD, CT 06339	Active	5/5/2014	Failure to have required financial responsibility in the required amount(s).. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	14	LOU'S ENTERPRISES, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156890&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156890&amp;type=ENFORCEMENT_ACTION</a>
STRATFORD	MAS GAS & CONVENIENCE STORE	2000 BARNUM AVE STRATFORD, CT 06615	Closed	9/11/2014	The passing annual line leak detector test documentation was not maintained.. The passing annual line leak detector test had not been performed.. CCMI 9/29/14 Passing line tightness & LLD test results, passing tank monitor inspection	4	M&M GAS AND CONVENIENCE, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166528&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166528&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	LONE STAR REPAIR SERVICE INC.	780 PACIFIC ST STAMFORD, CT 06902	Closed	8/18/2014	The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. Notification form and fee submitted to CPPU on 9/5/14	1	MACCHIO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165018&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165018&amp;type=ENFORCEMENT_ACTION</a>

DANBURY	ONE STOP MOBIL	276 WHITE ST DANBURY, CT 06810	Active	7/30/2014	Annual Tightness Test for Pressurized Piping was not performed.. Monthly records of interstitial monitoring records were not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual test documentation was not available for the piping leak monitoring equipment and devices. . The annual tightness test documentation was not available for the piping. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or...	22	MACHOTRA	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164291&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164291&amp;type=ENFORCEMENT_ACTION</a>
MADISON	MADISON SERVICE CENTER	608 BOSTON POST RD MADISON, CT 06443	Active	8/4/2014	Documentation of an annual passing cathodic protection test for piping was not available.. Documentation showing that the monitors for tanks impressed current systems have been inspected every 30 days was not available.. Documentation showing that the monitors for the piping impressed current systems have been inspected every 30 days was not available.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	18	MADISON SERVICE CENTER, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164350&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164350&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	REY-JEFF	136 MYRTLE AVE STAMFORD, CT 06902	Active	8/14/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion	2	MALINDA PROPERTIES LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164902&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164902&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	M & J Automotive LLC	2661 LONG RIDGE RD STAMFORD, CT 06903	Closed	5/29/2014	Inspection on 07/29/2014 by inspector Mike Cosker .The inspection status was passed.	10	MALLOZZI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159378&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159378&amp;type=ENFORCEMENT_ACTION</a>

BLOOMFIELD	BLUE HILLS SERVICE INC..	919 BLUE HILLS AVE BLOOMFIELD, CT 06002	Closed	3/14/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. . The tank has not been properly abandoned in-place in accordance with NFPA 30. Oil remains in the tank and it has not been filled with a solid inert material.. NOV was issued to previous owner. New nov to be issued to current owner (Blue Hills Associates LLC)	12	MANCINI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152068&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152068&amp;type=ENFORCEMENT_ACTION</a>
NORTHFORD	HARRY CUSCIO SALES & SERVICE INC.	1872 MIDDLETOWN AVE NORTHFORD, CT 06472	Closed	5/2/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The release detection documentation was not available.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. NOV closed as site has new owner. New NOV issued to current owner as NOVUST-GB14-0061	12	MANSFIELD	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156742&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156742&amp;type=ENFORCEMENT_ACTION</a>
STORRS MANSFIELD	MANSFIELD TOWN GARAGE	230 CLOVER MILL RD STORRS MANSFIELD, CT 06268	Active	11/6/2013	Product dispensing is not being metered and recorded within local standards for meter calibration to required accuracy.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product	5	MANSFIELD	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143666&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143666&amp;type=ENFORCEMENT_ACTION</a>

STORRS MANSFIELD	DURHAM SCHOOL SERVICES	1725 STAFFORD RD STORRS MANSFIELD, CT 06268	Active	10/23/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. The piping corrosion (cathodic) protection system was not operational, therefore, must be repaired or system permanently closed.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The three (3) year test documentation was not available for the suction piping..	7	MANSFIELD	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142916&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142916&amp;type=ENFORCEMENT_ACTION</a>
CHESHIRE	CHESHIRE DETAILING LLC	1125 HIGHLAND AVE CHESHIRE, CT 06410	Active	11/4/2013	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.	3	MARSHALL ENTERPRISES LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143520&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143520&amp;type=ENFORCEMENT_ACTION</a>
NEW FAIRFIELD	NEW FAIRFIELD AUTO SERVICE, INC.	104 STATE ROUTE 39 NEW FAIRFIELD, CT 06812	Active	5/28/2014	Annual Tightness Test for Pressurized Piping was not performed.. Documentation of an annual passing cathodic protection test for piping was not available.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual tightness test documentation was not available for the piping. . The overflow audible alarm was not visible or clearly marked.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or fac...	35	MARTINS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159273&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159273&amp;type=ENFORCEMENT_ACTION</a>

BLOOMFIELD	THE MATHER CORPORATION	21 W DUDLEY TOWN RD BLOOMFIELD, CT 06002	Active	5/15/2014	A review of DEP records indicates that we do not have a registration form with current information.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. ATG is not checking portion of the tank that routinely contains product (for some models, the tank level can be 14%).. Release detection had not been performed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed maintain the requisite testing records and has failed to provide t...	21	MATHER CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158473&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158473&amp;type=ENFORCEMENT_ACTION</a>
BOZRAH	FITCHVILLE AUTO CENTER INC.	188 FITCHVILLE RD P.O. BOX 269 BOZRAH, CT 06334	Active	11/8/2013	UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	1	McGEOWAN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143800&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143800&amp;type=ENFORCEMENT_ACTION</a>
FARMINGTON	MCPHEE LTD	505 MAIN ST FARMINGTON, CT 06032	Active	3/20/2014	Monthly records of interstitial monitoring records were not available.. Release detection had not been performed.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. Suction piping without continuous monitoring with a check valve at the tank is required to be tightness tested every three years. Safe suction piping is required to be tested annually the last three (3) years of its life expectancy.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite ann...	14	MCPHEE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152520&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152520&amp;type=ENFORCEMENT_ACTION</a>



SALEM	Mekamu, LLC d/b/a Maple Shade	428 HARTFORD RD SALEM, CT 06420	Closed	5/30/2014	Documentation of an annual passing cathodic protection test for piping was not available.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. Recd passing CP test documentation. PTS Corrosion Engineering Inc. dated 7/31/2013, site submitted photos of cleaned spill containment device approved by Inspector Bellmar	4	MEKAMU, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159589&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159589&amp;type=ENFORCEMENT_ACTION</a>
CHAPLIN	E-Z MART STORE #024	17 WILLIMANTIC RD CHAPLIN, CT 06235	Active	10/23/2013	The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The passing annual line leak detector test documentation was not maintained..	8	MICKEY PANKAJ, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142908&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142908&amp;type=ENFORCEMENT_ACTION</a>
Marlborough	MAXUM FUEL	2 E Hampton Rd Marlborough, CT 06447	Active	8/7/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated sub...	7	MID VALLEY OIL COMPANY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164519&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164519&amp;type=ENFORCEMENT_ACTION</a>
FAIRFIELD	MILLER NISSAN INC.	930-970 KINGS HIGHWAY FAIRFIELD, CT 06430	Active	5/9/2014	Failure to have required financial responsibility in the required amount(s).. No Notice of Financial Responsibility on site.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	3	MILLER FORD, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157301&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157301&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	MITCHELL FUEL CO., INC	PO BOX 1163 SOUTH WINDSOR, CT 06074	Active	10/21/2013	The overfill alarm could not be manually activated..	2	MITCHELL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142638&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142638&amp;type=ENFORCEMENT_ACTION</a>

PORTLAND	PORTLAND AUTOMOTIVE, INC.	131 MARLBOROUGH ST PORTLAND, CT 06480	Active	11/8/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	2	MJT ENTERPRISES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143802&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143802&amp;type=ENFORCEMENT_ACTION</a>
West Cornwall	MOHAWK MT SKI AREA	46 Great Hollow Rd West Cornwall, CT 06796	Active	3/18/2014	The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	5	MOHAWK MOUNTAIN SKI AREA, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152333&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152333&amp;type=ENFORCEMENT_ACTION</a>
EAST HAVEN	ERNIE & SONS	925 FOXON RD EAST HAVEN, CT 06513	Closed	5/13/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The monthly release detection test documentation from the automatic tank gauging device was not available. . Veterans Petroleum Services installed CSLD module at veeder root console (TLS-350) RAM cleared & reprogrammed, replaced broken grade select button on #2 regular, submitted passing 0.2 test results, . Tradebe pumped out 20 gals of water from sumps, tightened all penetration boots.	3	MONGILLO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157871&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157871&amp;type=ENFORCEMENT_ACTION</a>
MONROE	SHELL SERVICE STATION	604 MAIN ST MONROE, CT 06468	Active	11/18/2013			MONROE FOOD MART 123, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145591&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145591&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	SOUTH WINDSOR GARAGE INC	1179 JOHN FITCH BLVD SOUTH WINDSOR, CT 06074	Closed	12/5/2013	No Notice of Financial Responsibility on site.. Site submitted Storage tank Vertificate of Insurance to demonstrate Financial resposibility Form on 6/6/14. ACE American Insurance Co. G2477692A 001 (12/10/13-12/10/14)	1	MONTANO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145115&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145115&amp;type=ENFORCEMENT_ACTION</a>
MONTVILLE	CORNELIUS P. LEARY TRANSPORTATION CTR.	162 CHESTERFIELD RD MONTVILLE, CT 06353	Closed	10/22/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. Site submitted maine certificate of training: General Operator.	1	MONTVILLE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142914&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142914&amp;type=ENFORCEMENT_ACTION</a>

WETHERSFIELD	Winding Brook Turf Farm, Inc	240 GRISWOLD RD WETHERSFIELD, CT 06109	Closed	3/25/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Equipment is not capable of one-eighth of an inch measurement.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. Release or discharge from a UST system.. The division inspector has determined that release detection was not installed at this facility.. The monthly release detection test documentation from the automatic tank gauging device was not available. . There was no release detection provided for tanks.. UST system discharged regulated substances to the environment without a permit.. Water is not being monitored daily.. 4/9/14 Inspector Cosker met w/ Brett Burdess too follow up on NOV and post red tag hearing. All requirements have been met.	10	MORGAN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152940&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152940&amp;type=ENFORCEMENT_ACTION</a>
FARMINGTON	SUNOCO	46 FARMINGTON AVE FARMINGTON, CT 06032	Closed	8/15/2014	Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator failed to immediately respond to a sump sensor alarm.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. Received notification form (entered 9/9/14) including Operator Training information. Operator training done recently before inspection OK'd by Peter Zack. Does not need to re-train again. Sump sensor alarm fixed on 8/29/14. Sensor was faulty and sensor was replaced.	3	MYSTIC OIL COMPANY, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165000&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165000&amp;type=ENFORCEMENT_ACTION</a>
MYSTIC	MYSTIC VALERO	530 NEW LONDON RD MYSTIC, CT 06355	Closed	9/24/2014	Site submitted a/b 7 C operator information, monthly inspection checklists, passing LLD test results, General Repair Services 10/2/14 removed liquid from sump and fixed sump sensor in place by bolting it to the wall.	8	MYSTIC ON THE GO LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167258&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167258&amp;type=ENFORCEMENT_ACTION</a>
CHESHIRE	K & J AUTOMOTIVE INC.	2125 MERIDEN RD CHESHIRE, CT 06410	Closed	10/18/2013	A review of DEP records indicates that we do not have a registration form with current information.. This NOV was clsd by Kelly McShea on 11/21/13 as part of the NOV followup project	1	NARDELLI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142565&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142565&amp;type=ENFORCEMENT_ACTION</a>

Winsted	Mad River Grocery LLC	787 Main St Winsted, CT 06098	Active	8/28/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Annual Tightness Test for Pressurized Piping was not performed.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Failure to have required financial responsibility in the required amount(s).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual tightness test documentation was not available for the piping. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The ...	21	Nassari	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165802&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165802&amp;type=ENFORCEMENT_ACTION</a>
MANSFIELD CENTER	NATCHAUG HOSPITAL	189 STORRS RD MANSFIELD CENTER, CT 06250	Closed	11/6/2013	A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. 6/9/14 nov archived per Lori calibv	1	NATCHAUG HOSPITAL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143665&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143665&amp;type=ENFORCEMENT_ACTION</a>
BETHEL	BETHEL SAND & GRAVEL CO.	2 MAPLE AVENUE EXT BETHEL, CT 06801	Closed	6/25/2014	The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). . UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. Per the UST database, all usts at this site have been removed	12	NAZZARO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162099&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162099&amp;type=ENFORCEMENT_ACTION</a>

WESTPORT	NECG #6764	271 POST RD E WESTPORT, CT 06880	Active	8/26/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator failed to submit to the Commissioner a statement signed by the installation contractor, certifying that the installation has been carried out in accordance with the UST Regulations. . The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has f...	12	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165552&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165552&amp;type=ENFORCEMENT_ACTION</a>
NORWICH	NECG #598	170 TAFTVILLE OCCUM RD NORWICH, CT 06360	Closed	7/25/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. CCMI on site 9/9/14, liquid was not found in any secondary containment system designed as a dry system, sensors tested & confirmed functional, note: DF annular sensor operational but may not be at lowest point of secondary containment, Inspector Bellmar notified on 11/25/14. A/B Operator training held 7/15/14 ten days before inspection. Ok per Lori Saliby to close	6	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163813&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163813&amp;type=ENFORCEMENT_ACTION</a>

NAUGATUCK	NECG #607	531 N MAIN ST NAUGATUCK, CT 06770	Active	7/7/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. There is one or more underground storage tank piping system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location..	9	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162679&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162679&amp;type=ENFORCEMENT_ACTION</a>
BROOKFIELD	NECG #6813	813 FEDERAL RD BROOKFIELD, CT 06804	Closed	6/19/2014	ICM lists last registration date as 1/27/14, lists Ace American Insurance Co, 11/30/13-11/30/14, and shows A/B training date as 7/28/12 (note: training is NOT good for 5 years, must be retaken every two years) ICM lists last registration as 11/10/14 Philadelphia Insurance Co PHPK1147480 Commercial Insurance 2000000.00 3/13/2014 - 3/13/2015, Site submitted CCMi passing test results dated 11/22/13 for product line tightness testing , mechanical LLD testing , tank monitor inspection, and cathodic protection tank testing, ok to close per Lori Saliby 1/30/15	8	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161692&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161692&amp;type=ENFORCEMENT_ACTION</a>
Manchester	BP	176 Tolland Tpke Manchester, CT 06042	Closed	5/27/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Submitted bill of lading from TMC Environmental for the water removal from the stp sumps	2	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158950&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158950&amp;type=ENFORCEMENT_ACTION</a>
EAST HARTFORD	NECG #06864	1022 BURNSIDE AVE EAST HARTFORD, CT 06108	Active	5/19/2014	The Department's inspector has determined that the leak monitor for piping was in alarm condition.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The leak monitor for piping was in alarm condition and the piping system was not temporarily closed. . The owner or operator failed to immediately respond to a sump sensor alarm..	6	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158449&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158449&amp;type=ENFORCEMENT_ACTION</a>

FAIRFIELD	NECG #06782	721 KINGS HWY E FAIRFIELD, 06825	Active	4/30/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator failed to submit to the Commissioner a statement signed by the installation contractor, certifying that the installation has been carried out in accordance with the UST Regulations. . The owner or operator has failed to pay the requisite UST system installation fee.. The owner or operator has failed to submit the requisite annual UST faci...	19	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156507&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156507&amp;type=ENFORCEMENT_ACTION</a>
MILFORD	NECG #6781	231 CHERRY ST MILFORD, CT 06460	Closed	4/7/2014	Site is not choosing to temporarily close tanks, instead tanks are listed & tested as currently in use. OK per Supervisor Saliby. Temp Closed violations voided as they relate to temporarily closed tanks and these are not being temporarily closed. Recd notification form 6/1/14 including fiscal mechanism. Ace Insurance Co. G24734316 002 expires 11/30/14. Forwarded registration form to STEU on 9/9/14	15	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154276&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154276&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	NECG #6765	224 MAGEE AVE STAMFORD, CT 06902	Closed	4/7/2014	Notification form recd 1/16/14. WILD CO PES passing test results dated 4/28/14: LLD, line tightness, tank cathodic protection testing; 4/21/14 WILD CO PES onsite 4/28/14, passing ATG Certification, all the components passed with the exception of the super sump sensor which did not respond to a simulated alarm, the sensor was replaced and verified operational; Log documenting that the monitors for the tanks impressed current system have been inspected every 30 days submitted	16	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154295&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154295&amp;type=ENFORCEMENT_ACTION</a>
BLOOMFIELD	NECG #6722	1030 BLUE HILLS AVE BLOOMFIELD, CT 06002	Active	3/17/2014	A review of DEP records indicates that we do not have a registration form with current information.. An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. .	4	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152193&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152193&amp;type=ENFORCEMENT_ACTION</a>



DARIEN	NECG #6762	179 NOROTON AVE DARIEN, CT 06820	Active	3/6/2014	The Department's inspector has determined that the leak monitor for piping was in alarm condition.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The division inspector has determined that a piping sump sensor was not installed at the tank sump.. The overfill alarm could not be manually activated..	8	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151422&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151422&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	NECG #6768	59 W BROAD ST STAMFORD, CT 06902	Active	12/11/2013	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%)..	1	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145415&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145415&amp;type=ENFORCEMENT_ACTION</a>
NORWALK	NECG #6819	206 MAIN ST NORWALK, CT 06851	Closed	12/9/2013	Annual Tightness Test for Pressurized Piping was not performed.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The passing annual line leak detector test had not been performed.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	10	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145252&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145252&amp;type=ENFORCEMENT_ACTION</a>
WILTON	NECG #6837	210 DANBURY RD WILTON, CT 06897	Closed	12/5/2013	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Site submitted documentation on 1/14/14 documenting water removal from STP sumps, two new containment lids installed, adjusted sensors, replaced veeder root battery and printer.	4	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145116&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145116&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	NECG #6748	16 LONG RIDGE RD STAMFORD, 06905	Active	11/15/2013	The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	6	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144077&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144077&amp;type=ENFORCEMENT_ACTION</a>
NEW HAVEN	NECG #6759	241 KIMBERLY AVE NEW HAVEN, CT 06519	Closed	11/14/2013	The passing annual line leak detector test had not been performed.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project.	8	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144034&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144034&amp;type=ENFORCEMENT_ACTION</a>
Wauregan	NECG #600	309 PUTNAM ROAD Wauregan, CT 06387	Closed	11/8/2013	The Department's inspector has determined that the leak monitor for piping was in alarm condition.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. This NOV was clsd by Kelly McShea on 12/2/2013 as part of the NOV followup project.	6	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143761&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143761&amp;type=ENFORCEMENT_ACTION</a>

NORTH BRANFORD	NECG #680	208 FOXON RD NORTH BRANFORD, CT 06471	Active	10/4/2013	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. No Notice of Financial Responsibility on site.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	10	NECG HOLDINGS CORP	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141942&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141942&amp;type=ENFORCEMENT_ACTION</a>
New Canaan	NEW CANAAN COUNTRY SCHOOL	PO Box 997 635 Frogtown Road New Canaan, CT 06840	Closed	9/4/2014	The Release Detection Method was not maintained in accordance with the Manufacturer's Instructions.. Inspector stated that the ATG is overdue for recertification, there is no manufacturer recertification of ATG, VOIDING VIOLATION	1	NEW CANAAN COUNTRY SCHOOL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166006&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166006&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	New England Silica, Inc.	1370 JOHN FITCH BLVD SOUTH WINDSOR, CT 06074	Closed	6/18/2014	6/25/14 inspection by Inspector Cosker states he met with Brian Bellody, 'C' Operator. (The 'A/B' Operator is William Haun, from Hugh's Mechanical Services, Inc.) Proposal in place for annual registration & monthly inspections. Per Inspector Cosker site has a a/b operator, Recd passing CP test results for tanks and lines	3	NEW ENGLAND SILICA, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161515&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161515&amp;type=ENFORCEMENT_ACTION</a>
NEW MILFORD	NEW MILFORD HOSPITAL, INC.	21 ELM ST NEW MILFORD, CT 06776	Closed	4/23/2014	A review of DEP records indicates that we do not have a registration form with current information.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s)..6/10/14 site archived by Lori Saliby	2	NEW MILFORD HOSPITAL, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155725&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155725&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	THE NEW VICTORY CORP	406 W MAIN ST STAMFORD, CT 06902	Active	7/22/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required..	6	NEW VICTORY CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163473&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163473&amp;type=ENFORCEMENT_ACTION</a>

BROOKFIELD	C.M. Newman Inc.	820 FEDERAL RD BROOKFIELD, CT 06804	Active	6/19/2014	Annual Tightness Test for Pressurized Piping was not performed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual tightness test documentation was not available for the piping. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained.. The passing annual line leak detector test had not been performed..	10	Newman	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161691&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161691&amp;type=ENFORCEMENT_ACTION</a>
Newtown	NEWTOWN COUNTRY CLUB	COUNTRY CLUB RD. Newtown, CT 06470	Closed	10/21/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. The division inspector has identified that the tanks overfill device is not adequate for preventing overfills.. Site removed tanl A1R1 on 11/15/13. Reg form received 12/9/13.	4	NEWTOWN COUNTRY CLUB INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142620&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142620&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	NIDEC AMERICA CORPORATION	100 FRANKLIN DR TORRINGTON, CT 06790	Active	7/25/2014			NIDEC AMERICA CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163853&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163853&amp;type=ENFORCEMENT_ACTION</a>
Newtown	NJ K Automotive LLC	75 S Main St Newtown, CT 06470	Active	8/20/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s)..	3	NJK Automotive LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165349&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165349&amp;type=ENFORCEMENT_ACTION</a>
NEW MILFORD	PARK LANE SUNOCO	44 PARK LANE RD NEW MILFORD, CT 06776	Closed	4/11/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Recd copy of monthly checklist on 6/9/14	1	NORBERT E. MITCHELL CO., INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154847&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154847&amp;type=ENFORCEMENT_ACTION</a>
NORTH BRANFORD	NORTH BRANFORD GULF	1645 FOXON RD NORTH BRANFORD, CT 06471	Closed	11/15/2013	Site submitted A/B Operator information, and EGC Environmental checked all sumps /dispensers and removed all liquid. Site submitted system status report, invoice and photographs	7	NORTH BRANFORD GAS ASSOCIATES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144083&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144083&amp;type=ENFORCEMENT_ACTION</a>

WOLCOTT	NORTHEND LIQOUR	1496-1500 WOLCOTT RD WOLCOTT, CT 06716	Active	4/15/2014			NORTH END REALTY, L.L.C.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155144&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155144&amp;type=ENFORCEMENT_ACTION</a>
GROTON	Harings Marina	15 RIVERVIEW AVE GROTON, CT 06340	Active	6/9/2014	Failure to have required financial responsibility in the required amount(s).. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	3	Nyman	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160558&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160558&amp;type=ENFORCEMENT_ACTION</a>
KENT	BULLS BRIDGE COUNTRY STORE, LLC	337 KENT RD KENT, CT 06757	Active	10/29/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form with current information.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The division inspector has determined that release detection was not installed at this facility.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The release detect...	30	O'HARA	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143541&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143541&amp;type=ENFORCEMENT_ACTION</a>
OLD SAYBROOK	K.E. GOODWIN ELEMENTARY SCHOOL	80 OLD BOSTON POST RD OLD SAYBROOK, CT 06475	Closed	6/20/2014	Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Site submitted passing CP test results from PTS Corrosion Engineering Inc on 7/14/14	1	OLD SAYBROOK BOARD OF EDUCATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161732&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161732&amp;type=ENFORCEMENT_ACTION</a>
OLD SAYBROOK	MEINEKE	820 BOSTON POST RD OLD SAYBROOK, CT 06475	Closed	6/3/2014	A closure report has not been maintained for this system permanently closed at this facility.. A review of DEP records indicates that we do not have a registration form with current information.. NOV being closed, three 8,000 gal gasoline usts, one 4000 gal df ust, one 1000 gal hf ust removed 8/16/13, closure report forwarded to sas	5	P. A. ASSOCIATES, INC. OF OLD SAYBROOK	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159879&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159879&amp;type=ENFORCEMENT_ACTION</a>

NORTH BRANFORD	PASCALE'S GARAGE, INC.	1143 FOXON RD NORTH BRANFORD, CT 06471	Closed	5/2/2014	The monthly release detection test documentation from the automatic tank gauging device was not available. . NE Tank installed CSLD chip for Veeder Root system on 5/7/14. Site submitted passing 0.2 test results on 5/22/14	1	PASCALE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156743&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156743&amp;type=ENFORCEMENT_ACTION</a>
NORTH HAVEN	SHELL SERVICE STATION	77 WASHINGTON AVE NORTH HAVEN, CT 06473	Closed	8/27/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Site submitted monthly inspection checklist and submitted photos showing all liquid has been removed from sumps	3	PATEL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165646&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165646&amp;type=ENFORCEMENT_ACTION</a>
STERLING	D & K LLC. DBA ONECO MARKET	1107 PLAINFIELD PIKE STERLING, CT 06377	Active	12/12/2013	A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	8	PATEL	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145474&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145474&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	WEST TORRINGTON SHELL	2 NORFOLK RD TORRINGTON, CT 06790	Active	7/30/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid..	7	PATTERSON OIL COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164103&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164103&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	WINSTED ROAD PATCO HANDY SHOP	610 WINSTED RD TORRINGTON, CT 06790	Active	6/17/2014	Fittings were not cathodically protected..	2	PATTERSON OIL COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161392&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161392&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	NORTH MAIN PATCO	857 MAIN ST TORRINGTON, CT 06790	Closed	6/17/2014	The monthly release detection test documentation from the automatic tank gauging device was not available. . Received passing 0.2 test results dated 1/3/15	1	PATTERSON OIL COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161393&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161393&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	PINERIDGE PATCO HANDY SHOP	1036 E MAIN ST TORRINGTON, CT 06790	Active	6/16/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required..	5	PATTERSON OIL COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161260&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161260&amp;type=ENFORCEMENT_ACTION</a>

TORRINGTON	EAST & WALL PATCO	189 E MAIN ST TORRINGTON, CT 06790	Active	6/16/2014	Fittings were not cathodically protected.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion..	15	PATTERSON OIL COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161261&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161261&amp;type=ENFORCEMENT_ACTION</a>
NEW HARTFORD	NEW HARTFORD PATCO HANDY SHOP	443 MAIN ST NEW HARTFORD, CT 06057	Active	3/28/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Documentation of an annual passing cathodic protection test for piping was not available.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	22	PATTERSON OIL COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153502&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153502&amp;type=ENFORCEMENT_ACTION</a>
East Windsor	PENSKE TRUCK LEASING CO.,L.P.	10 SHOHAM ROAD East Windsor, CT 06088	Closed	10/25/2013	The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd by Kelly McShea on 10/13/13 as part of the NOV followup project.	6	PENSKE TRUCK LEASING CO.,L.P.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143066&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143066&amp;type=ENFORCEMENT_ACTION</a>

GRISWOLD	PETRO MAX	136 PRESTON RD GRISWOLD, CT 06351	Active	5/27/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The dispenser sump contains liquid.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained.. The release detection documentation was not available..	13	PETROMAX CONNECTICUT, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158949&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158949&amp;type=ENFORCEMENT_ACTION</a>
Hartford	Recycle King	240 Walnut St Hartford, CT 06120	Active	5/7/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. . Failure to have required financial responsibility in the required amount(s).. Failure to notify the implementing agency at least 30 days prior to beginning permanent closure of UST system components.. No Notice of Financial Responsibility on site.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual ...	19	PHOENIX TAX INVESTORS, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157130&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157130&amp;type=ENFORCEMENT_ACTION</a>



BRANFORD	Pine Orchard Yacht & Country Club	2 CLUB PKWY BRANFORD, CT 06405	Active	9/16/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	7	PINE ORCHARD YACHT AND COUNTRY CLUB, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166851&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166851&amp;type=ENFORCEMENT_ACTION</a>
NEW BRITAIN	STOP & SAVE	860 STANLEY ST NEW BRITAIN, CT 06051	Closed	12/2/2013	The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The passing annual line leak detector test documentation was not maintained.. Amor Pump Services LLC 4/3/14 passing line tightness & line leak detector test results. liquid removed from sumps and photos submitted	12	PINTO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144789&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144789&amp;type=ENFORCEMENT_ACTION</a>
THOMASTON	VILLAGE SERVICE CENTER	268 WATERTOWN RD THOMASTON, CT 06787	Closed	9/12/2014	NOV can be closed per Inspector Keating. He has received all documentation and has visually inspected the sumps.	12	PIZZANO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166721&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166721&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	PORTOS CITGO	480 N COLONY ST WALLINGFORD, CT 06492	Closed	4/23/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Site submitted reconciliation records on 5/20/14, OK per Inspector Purple	3	PORTO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155727&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155727&amp;type=ENFORCEMENT_ACTION</a>
MANCHESTER	SHELL SERVICE STATION	288 MIDDLE TPKE W MANCHESTER, CT 06040	Closed	9/22/2014	The fill cover was broken or missing and must be repaired or replaced.. The passing annual line leak detector test had not been performed.. Submitted Compliance Statement with service & repair report 10/16/14 from The Franklin Co. stating replaced DF, premium & regular FBW spill bucket covers and installed two new hand pumps (DR & reg) NE Tank Service 10/6/14 passing line tightness testing & passing LLD test results	6	PPP, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167066&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167066&amp;type=ENFORCEMENT_ACTION</a>

Preston	PUBLIC WORKS GARAGE	423 Route 2 Preston, CT 06365	Active	5/5/2014	The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The primary overfill device was not identified..	5	PRESTON	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156870&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156870&amp;type=ENFORCEMENT_ACTION</a>
PRESTON	TOWN BUS GARAGE	327 SHETUCKET TURNPIKE PRESTON, CT 06365	Closed	12/5/2013	The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. This NOV was clsd by Kelly McShea on 12/9/13 as part of the NOV followup	1	PRESTON BOARD OF EDUCATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145119&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145119&amp;type=ENFORCEMENT_ACTION</a>
YALESVILLE	IN AND OUT MART (CITGO)	305 MAIN ST YALESVILLE, CT 06492	Closed	5/20/2014	Annual Tightness Test for Pressurized Piping was not performed.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test had not been performed.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. Inspection on 05/29/2014 by inspector Gary Bellmar.The inspection status was passed.	8	PRIAL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158691&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158691&amp;type=ENFORCEMENT_ACTION</a>
WINDSOR LOCKS	Pride	77 ELLA GRASSO TPKE WINDSOR LOCKS, CT 06096	Active	5/8/2014	A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. Annual Tightness Test for Pressurized Piping was not performed.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly,Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The annual tightness test documentation was not available for the piping. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records t...	34	Pride Convenience	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157298&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157298&amp;type=ENFORCEMENT_ACTION</a>

SIMSBURY	PRIDE SIMSBURY	518 HOPMEADOW ST SIMSBURY, CT 06070	Closed	2/28/2014	Inspection on 07/02/2014 by inspector John Hirschfeld. The inspection status was passed. USTs removed	18	Pride Convenience	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150971&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150971&amp;type=ENFORCEMENT_ACTION</a>
SIMSBURY	Pride	1340 HOPMEADOW ST SIMSBURY, CT 06070	Closed	2/28/2014	Inspection on 05/09/2014 by inspector John Hirschfeld. The inspection status was passed. Tanks have been removed. Closure report recd 8/19/14	18	Pride Convenience LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150974&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150974&amp;type=ENFORCEMENT_ACTION</a>
WATERFORD	QUICK-EZE-	239 BOSTON POST RD WATERFORD, CT 06385	Active	5/14/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six ...	26	Qamar	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158046&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158046&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	R & D Service Center	550 ALBANY AVE HARTFORD, CT 06112	Active	4/1/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The division inspector has determined that release detection was not installed at this facility.. Water is not being monitored daily..	4	R & D SERVICE CENTER, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153677&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153677&amp;type=ENFORCEMENT_ACTION</a>
EAST HAVEN	EAST SHORE GARAGE d/b/a R.A. D'Urso's & Sons	667 COE AVE EAST HAVEN, CT 06512	Active	8/27/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	10	R.A. DURSO AND SONS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165647&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165647&amp;type=ENFORCEMENT_ACTION</a>

NORTHFORD	HARRY CUSCIO SALES & SERVICE INC.	1872 MIDDLETOWN AVE NORTHFORD, CT 06472	Active	5/2/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	15	RABBI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159027&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159027&amp;type=ENFORCEMENT_ACTION</a>
BARKHAMSTED	On The Go Country Store	128 NEW HARTFORD RD BARKHAMSTED, CT 06063	Active	3/28/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank and/or integral piping installed on or after October 1, 2003 is not double-walled, or, the tank is double-walled but is not monitored interstitially.. Annual Tightness Test for Pressurized Piping was not performed.. Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Monthly records of interstitial monitoring records were not available.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . Spill containment device was not maintained in good working order. The spill containment devic...	39	Rabbie	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153504&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153504&amp;type=ENFORCEMENT_ACTION</a>

MIDDLETOWN	ON THE GO	619 SAYBROOK RD MIDDLETOWN, CT 06457	Closed	11/26/2013	Annual Tightness Test for Pressurized Piping was not performed.. The passing annual line leak detector test had not been performed.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. Registration form received 12/10/13. Passing Line Tightness testing results and passing LLD test results rec. 12/3/13.	7	Rabbie	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144597&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144597&amp;type=ENFORCEMENT_ACTION</a>
WATERFORD	M & J BUS INC.	30 FARGO RD WATERFORD, CT 06385	Active	6/25/2014	The annual tightness test documentation was not available for the piping. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	5	RAMY, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162114&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162114&amp;type=ENFORCEMENT_ACTION</a>
NEW MILFORD	Raos Citgo	520 DANBURY RD NEW MILFORD, CT 06776	Active	4/23/2014	A closure report has not been maintained for this system permanently closed at this facility.. A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. . Failure to have required financial responsibility in the required amount(s).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner...	18	Rao, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155726&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155726&amp;type=ENFORCEMENT_ACTION</a>

Torrington	RAPID DAIRY TRANSPORT INC	1745 Tarringford West St Torrington, CT 06790	Active	11/7/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	6	RAPID DAIRY TRANSPORT	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143841&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143841&amp;type=ENFORCEMENT_ACTION</a>
Norwalk	EXXON SERVICE STATION (formerly amoco)	104 Connecticut Ave Norwalk, CT 06854	Closed	7/14/2014	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Removed soil from all three STP and added new quikrete so that piping is not in contact with the ground or water	3	REALTY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163045&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163045&amp;type=ENFORCEMENT_ACTION</a>
Higganum	SR. HIGH SCHOOL & BUS FACILITY	LITTLE CITY ROAD Higganum, CT 06441	Closed	10/21/2013	A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd by Kelly McShea on 12/2/13 as part of the NOV followup project.	3	REGIONAL SCHOOL DISTRICT #17	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142629&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142629&amp;type=ENFORCEMENT_ACTION</a>
NORTHFORD	NORTHFORD PATCO HANDY STOP	1371 MIDDLETOWN AVE NORTHFORD, CT 06472	Active	10/2/2013	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump..	8	REILLY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141842&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141842&amp;type=ENFORCEMENT_ACTION</a>
Montville	RENALDI'S ONE STOP	1588 HARTFORD NEW LONDON TPKE Montville, CT 06353	Closed	10/31/2013	A review of DEP records indicates that we do not have a registration form with current information.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. This NOV was clsd by Kelly McShea on 12/3/13 as part of the NOV followup project.	7	RENALDI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143378&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143378&amp;type=ENFORCEMENT_ACTION</a>

Plainfield	Best Way Citgo	2 PROSPECT ST Plainfield, CT 06374	Active	11/29/2013	A review of DEP records indicates that we do not have a registration form with current information.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. No Notice of Financial Responsibility on site.. Suction piping without continuous monitoring with a check valve at the tank is required to be tightness tested every three years. Safe suction piping is required to be tested annually the last three (3) years of its life expectancy.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained	12	REPUBLIC OIL COMPANY, INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144708&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144708&amp;type=ENFORCEMENT_ACTION</a>
RIVERSIDE	RIVERSIDE YACHT CLUB	102 CLUB RD RIVERSIDE, CT 06878	Closed	5/27/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. Crum & foster Specialty Insurance Co, STP-1-2912, exp. 6/2/16; performed spill bucket maintenance	3	RIVERSIDE YACHT CLUB, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159030&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159030&amp;type=ENFORCEMENT_ACTION</a>
CANAAN	GEER NURSING & REHABILITATION CENTER	99 S CANAAN RD CANAAN, CT 06018	Active	4/29/2014	Failure to have required financial responsibility in the required amount(s).. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	6	ROBERT C. GEER HOSPITAL, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156518&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156518&amp;type=ENFORCEMENT_ACTION</a>



EAST HADDAM	ROB'S AUTO SERVICE INC.	21 TOWN ST EAST HADDAM, CT 06423	Closed	11/25/2013	Fittings were not cathodically protected.. No Notice of Financial Responsibility on site.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. There is one or more underground storage tank piping system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.. UST owners or operators have failed to demonstrate ...	15	ROB'S AUTO SERVICE, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144517&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144517&amp;type=ENFORCEMENT_ACTION</a>
CANTON	TALCOTT VIEW DEVELOPMENT COMPANY, INC.	3 ALBANY TPKE CANTON, CT 06019	Active	6/11/2014	A closure report has not been maintained for this system permanently closed at this facility.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information..	3	Rose	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160943&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160943&amp;type=ENFORCEMENT_ACTION</a>
HIGGANUM	FORMER ROSSI LUMBER COMPANY	300 SAYBROOK RD HIGGANUM, CT 06441	Closed	9/30/2014	Subject tanks removed on 6/13/14 by Enviroshield. Registration form and closure report recd and forwarded to steu and sasu on 10/3/14	10	ROSSI CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167637&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2167637&amp;type=ENFORCEMENT_ACTION</a>
WETHERSFIELD	CROSS AUTOMOTIVE	708 SILAS DEANE HWY WETHERSFIELD, CT 06109	Closed	10/17/2013	The release detection documentation was not available.. Site submitted passing line tightness and LLD testing performed 4/11/13	3	Rossitto	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142515&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142515&amp;type=ENFORCEMENT_ACTION</a>
GREENWICH	ROUND HILL SERVICE STATION	369 ROUND HILL RD GREENWICH, CT 06831	Closed	11/14/2013	The tanks cathodic protection was not operational, therefore, corrosion protection must be repaired or system permanently closed.. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project	1	ROUND HILL SERVICE STATION, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144042&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144042&amp;type=ENFORCEMENT_ACTION</a>
MERIDEN	ROUSSEAU'S GARAGE	369 COOK AVE MERIDEN, CT 06451	Closed	11/6/2013	per Inspector Bellmar A. Rousseau is deceased. New owner is Sticky's Meriden Gas LLC, nov being closed due to ownership change	19	ROUSSEAU	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143602&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143602&amp;type=ENFORCEMENT_ACTION</a>

WALLINGFORD	SUNOCO	2 RIVER RD WALLINGFORD, CT 06492	Closed	5/19/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The gasket/O'rings for inner lids of sump wells have been reseated/repared. The liquid (rain water) was pumped out by Tradebe Environmental Services from both the sump wells.	1	ROUSSEAU	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158479&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158479&amp;type=ENFORCEMENT_ACTION</a>
SOUTHURY	S & S ASPHALT PAVING, INC.	680 MAIN ST S SOUTHURY, CT 06488	Active	10/10/2013	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. The release detection documentation was not available..	3	S & S ASPHALT PAVING, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142371&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142371&amp;type=ENFORCEMENT_ACTION</a>
NORTH HAVEN	SAINT THERESE CHURCH	555 MIDDLETOWN AVE NORTH HAVEN, CT 06473	Active	10/15/2013	A review of DEP records indicates that we do not have a registration form with current information.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The three (3) year test documentation was not available for the suction piping.. UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. .	5	SAINT THERESE CHURCH	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142406&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142406&amp;type=ENFORCEMENT_ACTION</a>
NEW HAVEN	BUDGET RENT-A-CAR	323 GEORGE ST NEW HAVEN, CT 06511	Active	6/26/2014	A review of DEP records indicates that we do not have a registration form with current information.. Failure to have required financial responsibility in the required amount(s).. No Notice of Financial Responsibility on site.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The release detection documentation was not available.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	8	SALATTO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162106&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162106&amp;type=ENFORCEMENT_ACTION</a>

TORRINGTON	SHEERAZI MINI MART	454 N ELM ST TORRINGTON, CT 06790	Active	3/5/2014	Annual Tightness Test for Pressurized Piping was not performed.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual test documentation was not available for the piping leak monitoring equipment and devices. . The annual tightness test documentation was not available for the piping. . The owner or operator failed to immediately respond to a sump sensor alarm.. The passing annual line leak detector test had not been performed.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. The tanks cathodic protection was not tested within six (...)	14	SALIMUDDI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151281&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151281&amp;type=ENFORCEMENT_ACTION</a>
GUILFORD	Citgo Guilford/ Quick Mart	455 BOSTON POST RD GUILFORD, CT 06437	Active	3/4/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. UST owner...	19	SANATAN, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151213&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151213&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	CITY GAS	10 WHITE ST HARTFORD, CT 06114	Closed	3/13/2014	Recd test documentation from NE Tank Services: 3/22/14 line tightness test passed and LLD passed, passing 0.2 for both tanks, passing CP for tanks AND lines	6	SANDR, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151854&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151854&amp;type=ENFORCEMENT_ACTION</a>

Orange	BEN'S SERVICE CENTER	115 Boston Post Rd Orange, CT 06477	Active	3/28/2014	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The passing annual line leak detector test documentation was not maintained.. The passing annual line leak detector test had not been performed.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	14	SANTAMAURO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153249&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153249&amp;type=ENFORCEMENT_ACTION</a>
ANSONIA	SARDO'S AUTOMOTIVE	522 MAIN ST ANSONIA, CT 06401	Closed	10/18/2013	The passing annual line leak detector test had not been performed.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd on 11/21/13 by Kelly McShea as part of the NOV followup project.	4	SARDO'S AUTOMOTIVE, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142528&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142528&amp;type=ENFORCEMENT_ACTION</a>
MIDDLETOWN	MIDDLETOWN GULF	339 S MAIN ST MIDDLETOWN, CT 06457	Active	3/12/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Fittings were not cathodically protected.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. .	12	SARKIS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151786&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151786&amp;type=ENFORCEMENT_ACTION</a>
BROOKLYN	SAVEWAY PETROLEUM INC., BROOKLYN TEXACO	49 S MAIN ST BROOKLYN, CT 06234	Closed	5/8/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Inspection on 05/09/2014 by inspector Mike Cosker .The inspection status was passed.	4	SAVEWAY PETROLEUM, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157291&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157291&amp;type=ENFORCEMENT_ACTION</a>

Norwich	EAST GREAT PLAINS MOBIL	489 New London Tpke Norwich, CT 06360	Closed	4/17/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. Submitted Aldin Assoc LP Monthly UST Inspection checklists from 8/28/12-11/29/13	1	SAVIN GASOLINE PROPERTIES II, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155211&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155211&amp;type=ENFORCEMENT_ACTION</a>
PRESTON	PRESTON MOBIL	124 ROUTE 12 PRESTON, CT 06365	Closed	3/18/2014	Site is in operation, per Inspector Bellmar site is only open Fridays 6-10am & 3-6pm, Recd Passing Cathodic Protection test results for piping and tanks, Monthly inspection checklist, Gasoline variance report ok's by Inspector Wilde on 9/18/14. Site submitted photos showing spill containment has been pumped out. Recd A/B Operator Training and Certification of Financial Responsibility on 9/18/14	16	SAVIN GASOLINE PROPERTIES II, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152464&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152464&amp;type=ENFORCEMENT_ACTION</a>
MONTVILLE	MIDWAY MOBIL	568 NORWICH MONTVILLE, CT 06353	Closed	11/29/2013	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. On 12/2/13 ted Ayers of the Aldin Maintenance Dept. removed the water from the spill containment	3	SAVIN GASOLINE PROPERTIES II, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144721&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144721&amp;type=ENFORCEMENT_ACTION</a>
NORWALK	C QUALITY PETROLEUM	180 CONNECTICUT AVE NORWALK, CT 06854	Closed	7/14/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Fittings were not cathodically protected.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. NOV issued to incorrect owner. NOV to be closed per Phil Wilde 1/30/15. Inspector Bellmar notified 1/30/15.	7	SCHIANO	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163044&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163044&amp;type=ENFORCEMENT_ACTION</a>
NEW BRITAIN	Schiavone Enterprises LLC	345 COLUMBUS BLVD NEW BRITAIN, CT 06051	Active	11/20/2013	Monthly records of interstitial monitoring records were not available.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The dispenser sump contains liquid.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. UST owners and/or operators are required to report to the implementing agency, at (860) 424-3338 and within twenty-four (24)hours, actual or suspected releases from UST systems..	11	SCHIAVONE ENTERPRISES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144331&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144331&amp;type=ENFORCEMENT_ACTION</a>

BOZRAH	MAIN'S COUNTRY STORE	318 FITCHVILLE RD BOZRAH, CT 06334	Active	11/8/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. The tanks cathodic protection was not operational, therefore, corrosion protection must be repaired or system permanently closed.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	4	SCHIAVONE ENTERPRISES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143830&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143830&amp;type=ENFORCEMENT_ACTION</a>
Mansfield	SHERRAZ LLC GULF	607 MIDDLE TURNPIKE Mansfield, CT 06250	Closed	10/23/2013	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The annual tightness test documentation was not available for the piping. . The fill cover was broken or missing and must be repaired or replaced.. The passing annual line leak detector test documentation was not maintained.. Came into office and discussed nov on 11/14/13. Passing LLD & tank tightness testing submitted. Sumps were pumped out and new spill bucket purchased, Ok to close NOv per Inspector Purple.	10	SCRANTON ASSOCIATES LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142915&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142915&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	SELECT FOOD MART, LLC	181 FRANKLIN AVE HARTFORD, CT 06114	Active	4/10/2014	A review of DEP records indicates that we do not have a registration form with current information.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. The dispenser sump contains liquid.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s)..	9	SELECT FOOD MART, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154651&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154651&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	DELTA	250 S COLONY RD WALLINGFORD, CT 06492	Active	5/19/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	9	SELINAS FAMILY, LLC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158478&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158478&amp;type=ENFORCEMENT_ACTION</a>

WILTON	SERVCO OIL, INC.	384R DANBURY RD WILTON, CT 06897	Closed	4/16/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. Site submitted email on 5/14/14 . Circuit board replaced. Site submitted passing 0.2 test results, passing status for all sensors, and photos of sump- water removed and lid and seal replaced.	9	SERVCO OIL, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155110&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155110&amp;type=ENFORCEMENT_ACTION</a>
GLASTONBURY	SHELL SERVICE STATION	2088 HEBRON AVE GLASTONBURY, CT 06033	Closed	3/3/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The fill cover was broken or missing and must be repaired or replaced.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. Fuller Installation on site. 4/01/14. Water in sumps do to broken fill cap lids. Fuller pumped out sumps, removed debris, replaced super and regular grade lids on fill manholes and replaced super grade snap cap. Retested, all passing.	6	SHAH PROPERTIES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151053&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151053&amp;type=ENFORCEMENT_ACTION</a>
Sharon	Sharon Fire House	36 W Main St Sharon, CT 06069	Active	10/28/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. Could not verify that the overfill protection device was installed at the required 90% alert or 95% shut off level. . Spill containment device was not present.. The division inspector has determined that release detection was not installed at this facility.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	7	SHARON	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143688&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143688&amp;type=ENFORCEMENT_ACTION</a>



SHARON	SHARON HEALTH CARE CENTER	27 HOSPITAL HILL RD SHARON, CT 06069	Closed	6/6/2014	Site submitted the following information: notification form (forwarded to steu 8/28/14)including fiscal information( Crum & Foster Specialty Ins. Co. STP-103546, \$1,000,000 7/18/14-7/18/16), monthly & daily checklists for DF emergency generator, Brian Reynolds A/B Operator retrained 7/28/14, Aaron Environmental passing CP Test performed 6/11/14 on DF UST,	6 SHARON SNF CT, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160592&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160592&amp;type=ENFORCEMENT_ACTION</a>
SUFFIELD	FLEMING'S TRANSPORTATION INC.	720 THOMPSONVILLE RD SUFFIELD, CT 06078	Active	12/12/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. Monthly records of interstitial monitoring records were not available.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The annual test documentation was not available for the piping leak monitoring equipment and devices. . The overfill audible alarm was not visible or clearly marked.. The owner or operator of an UST system has failed to designate Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. The release detection documentation was not available..	9 SHAUN FLEMING & SONS, INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145471&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145471&amp;type=ENFORCEMENT_ACTION</a>
SOUTH WINDSOR	NEW ENGLAND TRANSPORTATION INC	500 SULLIVAN AVE PO BOX 775 SOUTH WINDSOR, CT 06074	Closed	11/6/2013	Fittings were not cathodically protected.. Feedline & vent pipe excavated & exposed and the replaced with APT flexible Piping & Fiberglass vent pipe. In addition, a sump containment was installed.	1 SHEA	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143639&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143639&amp;type=ENFORCEMENT_ACTION</a>
OLD LYME	SHORLINE CHEVRON	214 SHORE RD OLD LYME, CT 06371	Active	10/7/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	18 Shoreline Service Center, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142083&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142083&amp;type=ENFORCEMENT_ACTION</a>

HARTFORD	AIRPORT ROAD AUTO BODY INC	80 AIRPORT RD HARTFORD, CT 06114	Active	3/13/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The passing annual line leak detector test documentation was not maintained..	10	SHORT STOP, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151855&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151855&amp;type=ENFORCEMENT_ACTION</a>
BETHANY	OLD BETHANY DEPOT	119 AMITY RD BETHANY, CT 06524	Active	12/5/2013	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator of an UST system has failed to designate Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. The release detection documentation was not available.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	10	SICKINGER	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145108&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145108&amp;type=ENFORCEMENT_ACTION</a>
BURLINGTON	Sikorski Bus Company	227 SPIELMAN HWY BURLINGTON, CT 06013	Closed	3/12/2014	A review of DEP records indicates that we do not have a registration form with current information.. An out-of-service UST system remains installed at the site, and it has not been properly permanently closed through either removal or NFPA-30 compliant in-place abandonment. Registration form in ICM dated 5/14/12 states tank has been permanently closed	2	Sikorski Bus Company	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151817&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151817&amp;type=ENFORCEMENT_ACTION</a>
NAUGATUCK	MEYERS SUPPLY, INC.	191 SHERIDAN DR NAUGATUCK, CT 06770	Closed	10/28/2013	The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd by Kelly McShea on 12/2/13 as part of the NOV followup project.	2	SLOAT	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143097&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143097&amp;type=ENFORCEMENT_ACTION</a>
ORANGE	ORANGE HILLS COUNTRY CLUB	389 RACEBROOK RD ORANGE, CT 06477	Closed	6/24/2014	Failure to have required financial responsibility in the required amount(s).. ACE American Insurance Company G24769070-001 Commercial Insurance 1000000.00 10/1/2013	1	SMITH	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161954&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161954&amp;type=ENFORCEMENT_ACTION</a>

PORTLAND	SAB FUEL, INC.	691 PORTLAND COBALT RD PORTLAND, CT 06480	Active	11/8/2013	A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. There is one or more underground storage tank piping system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location..	11	SOBOLESKI	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143801&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143801&amp;type=ENFORCEMENT_ACTION</a>
South Kent	SOUTH KENT SCHOOL	40 Bulls Bridge Rd South Kent, CT 06785	Closed	6/20/2014	Notification form in ICM dated 7/7/14,, Recd Certificate of Financial Responsibility 9/18/14, Fred C Church Inc, PLC8087915 7/1/14-7/1/16, Compliance Statement states the operator is now performing and recording visual inspections, ok to close this violation per Lori Saliby 1/30/14	3	SOUTH KENT SCHOOL CORPORATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161758&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161758&amp;type=ENFORCEMENT_ACTION</a>
SOUTHINGTON	SOUTHINGTON FIRE DEPARTMENT HEADQUARTERS	310 N MAIN ST SOUTHINGTON, CT 06489	Closed	5/6/2014	A spill containment device was not installed. . Service Station Equipment removed and replaced two spill buckets on 5/29/14	2	SOUTHINGTON	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157101&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157101&amp;type=ENFORCEMENT_ACTION</a>
STAMFORD	SHIPPAN SHELL	179 SHIPPAN AVE STAMFORD, CT 06902	Closed	12/11/2013	N E Tank Services cleaned spill containment device, submitted annual testing of two discharge lines, passing CP & LLD test results, veeder root certification, and Stage 2 testing. Submersibles are in total containment sumps and were cleaned & pumped free of water by EGC Environmental 1/8/14, site replaced two fill caps	6	STANDARD PETROLEUM COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145414&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145414&amp;type=ENFORCEMENT_ACTION</a>
Griswold	Pachaug VALERO	832 Voluntown Rd. (Rt. 138) Griswold, CT 06351	Closed	10/31/2013	Fittings were not cathodically protected.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. This NOV was clsd by Kelly McShea on 12/9/13 as part of the NOV followup project.	6	STANDARD PETROLEUM COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143377&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143377&amp;type=ENFORCEMENT_ACTION</a>

CLINTON	CLINTON SUNOCO	31 W MAIN ST CLINTON, CT 06413	Active	8/4/2014	Monthly records of interstitial monitoring records were not available.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The release detection documentation was not available.. The release detection for this tank indicates a possible release. The owner shall perform an investigation into the cause of the failure to determine if a release has occurred. If a release of a regulated substance from the system has occurred, the owner shall comply with all the requirements of Section 105.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). .	12	STANDARD REALTY, L.L.C.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164349&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164349&amp;type=ENFORCEMENT_ACTION</a>
DARIEN	NOROTON CITGO (valero's)	1927 POST RD DARIEN, CT 06820	Active	6/13/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities..	8	STANDARD REALTY, L.L.C.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161145&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161145&amp;type=ENFORCEMENT_ACTION</a>

DARIEN	Post Road Shell d/b/a Premiere Auto Sport	805 POST RD DARIEN, CT 06820	Active	6/10/2014	Fittings were not cathodically protected.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained..	23	STANDARD REALTY, L.L.C.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160709&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2160709&amp;type=ENFORCEMENT_ACTION</a>
NORTH HAVEN	MOBIL STATE STREET CAR CARE	384 STATE ST NORTH HAVEN, CT 06473	Active	8/25/2014	The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities	1	STATE STREET ASSOCIATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165599&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165599&amp;type=ENFORCEMENT_ACTION</a>
WEST HARTFORD	STEBEN'S SERVICE	293 PARK RD WEST HARTFORD, CT 06119	Active	3/6/2014	A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. Equipment is not capable of one-eighth of an inch measurement.. No Notice of Financial Responsibility on site.. The annual tightness test documentation was not available for the piping. . The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The passing annual line leak detector test documentation was not maintained.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	13	STEBEN'S MOTORS AUTO BODY, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151429&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151429&amp;type=ENFORCEMENT_ACTION</a>

BETHEL	STEINER, INC.	02 PARK LAWN DR BETHEL, CT 06801	Active	11/13/2013	22a-449(d)-108(a)Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. A review of DEP records indicates that we do not have a registration form with current information.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Release detection had not been performed.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. Suction piping without continuous monitoring with a check valve at the tank is required to be tightness tested every three years. Safe suction piping is requi..	14	STEINER, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143962&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143962&amp;type=ENFORCEMENT_ACTION</a>
NORTHFORD	NORTHFORD SUNOCO SERVICE	847 FOREST RD NORTHFORD, CT 06472	Active	10/2/2013	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	19	STEROCO INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141841&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2141841&amp;type=ENFORCEMENT_ACTION</a>

MIDDLETOWN	STEVES REPAIRS UNLIMITED, LLC	649 MAIN ST MIDDLETOWN, CT 06457	Closed	10/30/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. No Notice of Financial Responsibility on site.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met.. NOV being closed, issued to incorrect owner. NOVUST-GB13-0125 issued to City of Middletown (current owner)	11	STEVES REPAIRS UNLIMITED, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143304&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143304&amp;type=ENFORCEMENT_ACTION</a>
THOMASTON	STEWART EFI CONNECTICUT, LLC	45 OLD WATERBURY RD THOMASTON, CT 06787	Active	4/28/2014	Monthly records of interstitial monitoring records were not available.. Secondary Containment is not designed for interstitial monitoring.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). . There was no release detection provided for tanks..	6	STEWART EFI, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156193&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2156193&amp;type=ENFORCEMENT_ACTION</a>
Stonington	PAWCATUCK MIDDLE SCHOOL	MAYFLOWER AVE Stonington, CT 06378	Closed	3/18/2014	Failure to meet tightness test requirements for repaired UST system compnents.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Site submitted passing CP test results for tanks on 4/8/14	2	STONINGTON	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152409&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152409&amp;type=ENFORCEMENT_ACTION</a>



BRANFORD	STONY CREEK AUTO SERVICE	417 LEETES ISLAND RD BRANFORD, CT 06405	Active	9/11/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The monthly release detection test documentation from the automatic tank gauging device was not available. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. The UST system owner or operator has failed to perform compliant release detection on UST system compon...	9	STONY CREEK AUTO SERVICE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166639&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166639&amp;type=ENFORCEMENT_ACTION</a>
NAUGATUCK	M & I RUBBER AVE CITGO	711 RUBBER AVE NAUGATUCK, CT 06770	Closed	6/30/2014	Inspection on 07/01/2014 by inspector Latroy Franklin.The inspection status was passed.	9	STOP N SAVE, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162297&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162297&amp;type=ENFORCEMENT_ACTION</a>
CHESHIRE	CHESHIRE AUTO BODY INC.	532 W MAIN ST CHESHIRE, CT 06410	Closed	10/16/2013	No Notice of Financial Responsibility on site.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. This NOV was clsd by Kelly McShea on 12/2/13 as part of the NOV followup project.	4	Strollo	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142466&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142466&amp;type=ENFORCEMENT_ACTION</a>
MYSTIC	SULLIVAN'S	48 STONINGTON RD MYSTIC, CT 06355	Closed	3/13/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Sump pumped and cleaned by Western Oil on 3/14/14.	1	SULLIVAN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151948&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2151948&amp;type=ENFORCEMENT_ACTION</a>
ESSEX	SUNOCO (R & M) / BESTWAY	1 SAYBROOK RD ESSEX, CT 06426	Closed	8/6/2014	Recd notification form, certification of financial responsibility both forwarded to steu on 9/8/14, recd closure report stating on 5/14/13 four 8000 gal usts and 66.39 tons soil removed. Report forwarded to sasu on 9/8/14.	7	SUNOCO, INC. (R&M)	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164499&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164499&amp;type=ENFORCEMENT_ACTION</a>

MOOSUP	T & S OIL	200 WARD AVE MOOSUP, CT 06354	Active	11/8/2013	Metallic piping in the STP sump is in contact with the ground and/or the ground water or surface run off water and is therefore subject to corrosion.. The annual tightness test documentation was not available for the piping. . The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	15	T & S OIL COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143762&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143762&amp;type=ENFORCEMENT_ACTION</a>
MANCHESTER	SHELL	252 SPENCER ST MANCHESTER, CT 06040	Closed	11/22/2013	The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. CMI tested product lines and electronic LLD on 12/17/13, passed	6	THAPAN GROUP LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144470&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144470&amp;type=ENFORCEMENT_ACTION</a>
NEW MILFORD	JAMES THOMPSON JR.	80 CONNELLY RD NEW MILFORD, CT 06776	Active	3/18/2014	A review of DEP records indicates that we do not have a registration form with current information.. UST system components have not been permanently closed, through removal or proper in-place abandonment, prior to the last day of their thirty (30) year life expectancy. .	3	THOMPSON	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152332&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2152332&amp;type=ENFORCEMENT_ACTION</a>
THOMPSON	TOWN GARAGE	255 BUCKLEY HILL RD THOMPSON, CT 06277	Closed	12/4/2013	The three (3) year test documentation was not available for the suction piping.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. Inspection on 04/01/2014 by inspector George Purple.The inspection status was passed. Site took A/B operator course from Atlas March 5, 2014. Had Crompco in for testing on 12-26-13, everything passed	3	THOMPSON PUBLIC SCHOOLS	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144955&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144955&amp;type=ENFORCEMENT_ACTION</a>
EAST HARTFORD	CHUCKS AUTOMOTIVE LLC	653 BURNSIDE AVE EAST HARTFORD, CT 06108	Closed	6/2/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The annual tightness test documentation was not available for the piping. . The dispenser sump contains liquid.. The passing annual line leak detector test documentation was not maintained.. Amor Pump Service LLC performed line & leak detector testing on all three lines and all passed 6/10/14, Site pumped out and cleaned sumps	10	TISCHOFER	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159723&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159723&amp;type=ENFORCEMENT_ACTION</a>

Washington Depot	TITUS PARK GARAGE	TITUS ROAD Washington Depot, CT 06794	Active	10/17/2013	A review of DEP records indicates that we do not have a registration form with current information.. No Notice of Financial Responsibility on site.. The division inspector has identified that an overfill device was not installed on this system..	5	TITUS PARK GARAGE, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142581&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142581&amp;type=ENFORCEMENT_ACTION</a>
Torrington	Torrington Gas	37 Migeon Ave Torrington, CT 06790	Active	7/22/2014	Documentation of an annual passing cathodic protection test for piping was not available.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Proof of installation was not available; provide the piping corrosion protection testing results to prove installation or system must be permanently closed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has determined that the monthly ATG test documentation from the automatic tank gauging device was not available.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The piping cathodic protection was not tested..	38	TORRINGTON FUEL OIL, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163519&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163519&amp;type=ENFORCEMENT_ACTION</a>
Trumbull	Town Convenience Citgo	5891 Main St Trumbull, CT 06611	Closed	4/2/2014	A release may have occurred resulting in an unusual operating condition.. A review of DEP records indicates that we do not have a registration form with current information.. Monthly records of interstitial monitoring records were not available.. Release detection had not been performed.. Sensor is not properly placed.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The division inspector has identified that an overfill device was not installed on this system.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or o...	21	TOWN CONVENIENCE, INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153928&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153928&amp;type=ENFORCEMENT_ACTION</a>

MIDDLETOWN	STEVES REPAIRS UNLIMITED, LLC	649 MAIN ST MIDDLETOWN, CT 06457	Active	10/30/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form with current information.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. No Notice of Financial Responsibility on site.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	11	TOWN OF MIDDLETOWN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144577&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144577&amp;type=ENFORCEMENT_ACTION</a>
TRUMBULL	J & J Service Center	5771 MAIN ST TRUMBULL, 06611	Active	4/1/2014	A review of DEP records indicates that we do not have a registration form with current information.. A spill containment device was not installed. . A tank and/or integral piping installed on or after October 1, 2003 is not double-walled, or, the tank is double-walled but is not monitored interstitially.. Annual Tightness Test for Pressurized Piping was not performed.. ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. Could not determine the material of the piping. . CT DEP requires Swivel adaptors to be installed on all fill riser pipes. Swivel adapters were not installed on some or all fill pipes.. Documentation of an annual passing cathodic protection test for piping was not available.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. Proof of installation was not available; provide the piping co...	64	TRANGALI, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153635&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2153635&amp;type=ENFORCEMENT_ACTION</a>
Darien	DARIEN MAINTENANCE & REPAIR FACILITY	65 Brookside Dr Darien, CT 06820	Closed	8/26/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The owner or operator failed to immediately respond to a sump sensor alarm.. The owner or operator has rendered inoperable a sensor in a new under-dispenser containment sump and/or a new piping containment sump. Inspection on 09/11/2014 by inspector George Purple. The inspection status was passed.	3	TRANSPORTATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165650&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165650&amp;type=ENFORCEMENT_ACTION</a>

DARIEN	ALLIANCE ENERGY LLC# 839	I-95 SOUTHBOUND EXIT 10-9, DARIEN TPKE DARIEN, CT 06820	Closed	8/26/2014	Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. Fuller Installations inspected, sealed & secured the manholes on 8/27/14, replaced super grade vapor cap, tested ok, A/B Operators have been retrained.	2	TRANSPORTATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165651&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165651&amp;type=ENFORCEMENT_ACTION</a>
BRANFORD	ALLIANCE ENERGY LLC #836	I-95 NORTH EXIT 54-53 BRANFORD, CT 06405	Closed	8/14/2014	Overfill is bypassed by coaxial drop tube or by object opening valve. 8/18/14 Removed stick from special fill, stick not broken, driver dropped in on delivery.	1	TRANSPORTATION	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164942&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164942&amp;type=ENFORCEMENT_ACTION</a>
WINDSOR LOCKS	DOLLAR RENT A CAR	593 ELM ST WINDSOR LOCKS, CT 06096	Active	9/10/2014	Monthly records of interstitial monitoring records were not available.. The annual test documentation was not available for the piping leak monitoring equipment and devices. . The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The release detection documentation was not available.. UST owners or operators have failed to demonstrate that financial responsibility requirements are being met..	6	TRAVELERS RENTAL CO., INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166451&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166451&amp;type=ENFORCEMENT_ACTION</a>
HARTFORD	AUTO PARTS DEPOT, INC.	741 WINDSOR ST HARTFORD, CT 06120	Active	5/7/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Equipment is not capable of one-eighth of an inch measurement.. Failure to have required financial responsibility in the required amount(s).. Inventory control and weekly reconciliation records were not available during the inspection.. Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. No Notice of Financial Responsibility on site.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . Tank tightness test is...	18	TRIEBER	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157129&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157129&amp;type=ENFORCEMENT_ACTION</a>

TRUMBULL	Trumbull Foodmart LLC	648 WHITE PLAINS RD TRUMBULL, CT 06611	Active	4/8/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. Documentation showing that the monitors for tanks impressed current systems have been inspected every 30 days was not available.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator has failed to perform, or has performed inadequately, the requisite monthly visual inspections at their UST facility or facilities.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The tanks cathodic protection was not operational, therefore, corrosion protection must be repaired or system permanently closed..	12	Trumbull Foodmart, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154409&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2154409&amp;type=ENFORCEMENT_ACTION</a>
Greenwich	BMW of Greenwich	361 W Putnam Ave Greenwich, CT 06830	Active	5/16/2014	Proof of corrosion protection installation on tank was not available.. Suction piping without continuous monitoring with a check valve at the tank is required to be tightness tested every three years. Safe suction piping is required to be tested annually the last three (3) years of its life expectancy.. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The three (3) year test documentation was not available for the suction piping.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). . There is one or more underground storage tank piping system(s) that d...	9	Tunick DH Family LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158260&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158260&amp;type=ENFORCEMENT_ACTION</a>

Greenwich	BMW of Greenwich	361 W Putnam Ave Greenwich, CT 06830	Closed	5/15/2014	A review of DEP records indicates that we do not have a registration form with current information.. Proof of corrosion protection installation on tank was not available.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system owner or operator has failed to perform compliant release detection on UST system components (tank and/or integral piping). . There is one or more underground storage tank piping system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily closed for more than 12 months at this location.. There is one or more underground storage tank system(s) that does not meet new UST system standards or upgrade requirements and release detection requirements which has been temporarily...	7	Tunick DH Family LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158201&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158201&amp;type=ENFORCEMENT_ACTION</a>
SHELTON	THE UNITED ILLUMINATING COMPANY	801 BRIDGEPORT AVE SHELTON, CT 06484	Active	12/5/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. A review of DEP records indicates that we do not have a registration form with current information.. The owner or operator failed to submit to the Commissioner a statement signed by the installation contractor, certifying that the installation has been carried out in accordance with the UST Regulations. .	5	UNITED ILLUMINATING COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145106&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2145106&amp;type=ENFORCEMENT_ACTION</a>
BRISTOL	UNITED STATES POSTAL SERVICE:BRISTOL POST OFFICE	151 N MAIN ST BRISTOL, CT 06010	Active	8/19/2014	A review of DEP records indicates that we do not have a registration form with current information..	1	UNITED STATES POSTAL SERVICE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165192&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2165192&amp;type=ENFORCEMENT_ACTION</a>
WEST HARTFORD	UNIVERSITY OF HARTFORD	200 BLOOMFIELD AVE WEST HARTFORD, CT 06117	Closed	4/17/2014	A review of DEP records indicates that we do not have a registration form with current information.. Recd registration form dated 4/22/14; Inspection on 04/24/2014 by inspector Mike Cosker .The inspection status was passed.	1	UNIVERSITY OF HARTFORD	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155224&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2155224&amp;type=ENFORCEMENT_ACTION</a>



PLAINVILLE	FOODMART,LLC	147 N WASHINGTON ST PLAINVILLE, CT 06062	Closed	7/7/2014	The passing annual line leak detector test had not been performed.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Recd passing line leak detector and line tightness test results performed by Aaron Environmental on 7/21/14, and passing CP test results for tanks and lines dated 7/2/14 from PTS Corrosion Engineering	6	USMAN JALIL LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162591&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162591&amp;type=ENFORCEMENT_ACTION</a>
Groton	PUMP N MUNCH 3	81 Poquonnock Rd Groton, CT 06340	Active	12/3/2013	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. No Notice of Financial Responsibility on site.. Spill containment device was not maintained in good working order. The spill containment device shall be replaced, repaired or cleaned to enable the device to collect and hold a minimum 5-gallon spill during a product delivery.. The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C O...	18	USMAN, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144871&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144871&amp;type=ENFORCEMENT_ACTION</a>
TORRINGTON	JOHNSON GAS	294 S MAIN ST TORRINGTON, CT 06790	Closed	7/29/2014	NOV being closed as site ownership has changed. Inspector Hirschfeld notified 1/20/15. New Owner Mir Ahmed. Site submitted updated registration form, updated operator training (Mir Ahmed 10/16/14) and updated fiscal info (Colony Insurance Co. 0025571)	14	V JOHNSON INVESTMENTS LLCV	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163996&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163996&amp;type=ENFORCEMENT_ACTION</a>

SALISBURY	LIME ROCK AUTO SVC	US RTE 7 & 112 SALISBURY, CT 06068	Active	10/8/2013	22a-449(d)-108(a) Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. No Notice of Financial Responsibility on site.. Release detection had not been performed.. The piping cathodic protection was not tested within six (6) months of installation or within the last year.. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	14	VAKASSIAN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142144&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142144&amp;type=ENFORCEMENT_ACTION</a>
NAUGATUCK	NAUGATUCK SUNOCO	704 RUBBER AVE NAUGATUCK, CT 06770	Active	8/12/2014	A review of DEP records indicates that we do not have a registration form for the current owner and/or UST system as noted.. A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. A review of DEP records indicates that we do not have a registration form with current information.. Failure to have required financial responsibility in the required amount(s).. No Notice of Financial Responsibility on site.. Significant operational compliance (SOC) violations have resulted in the issuance of an NOV. Accordingly, Class A, Class B or Class C trained operators must be retrained and recertified in accordance with a Connecticut specific approved training program. . The owner or operator failed to submit to the Commissioner a statement signed by the installation contractor, certifying that the installation has been carried out in accordance with the UST Regulations. . The owner or operator has ...	24	VIGE	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164747&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2164747&amp;type=ENFORCEMENT_ACTION</a>
MIDDLETOWN	W. F. SHUCK PETROLEUM COMPANY	302 E MAIN ST MIDDLETOWN, CT 06457	Closed	10/22/2013	The monthly release detection test documentation from the automatic tank gauging device was not available. . Recd passing o 2 test results on 9/15/14	1	W. F. SHUCK PETROLEUM CO.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142791&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142791&amp;type=ENFORCEMENT_ACTION</a>
WALLINGFORD	THE W.I. CLARK COMPANY	30 BARNES INDUSTRIAL PARK RD SOUTH WALLINGFORD, CT 06492	Closed	11/7/2013	22a-449(d)-108(a) Own or operate a UST or UST system without designating Class A, B, and C Operators who have been trained and certified in accordance with an approved training program.. This NOV was clsd by Kelly McShea on 12/10/13 as part of the NOV followup project.	1	W. I. CLARK COMPANY	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143727&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143727&amp;type=ENFORCEMENT_ACTION</a>

WALLINGFORD	SHEEHAN HIGH SCHOOL	142 HOPE HILL RD WALLINGFORD, CT 06492	Closed	7/7/2014	The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program.. Wallingford Board of Ed has retained Environsheid as their A/B operator, they will assist in training the C operators. The site also replaced the overflow protection device on this tank (flapper valve) and installed a file box in the gas pump house that will contain the necessary records for	1	WALLINGFORD	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162719&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2162719&amp;type=ENFORCEMENT_ACTION</a>
WATERTOWN	9 Trades Lane	9 Trades Lane WATERTOWN, CT 06795	Closed	7/17/2014	A review of DEP records indicates that we do not have a registration form for the UST system noted. An unregistered tank was found on the property.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. Site is newtown school but registered in watertown, requested extension due to vacation & our database error causing him to have problem getting check cut, 8/25/14 awaiting check & will be in htfd - see emails, 8/29/14 REGISTRATION HAND DELIVERED TO FIRST FLOOR, PAID, TANKS REMOVED	2	WATERTOWN	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163246&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163246&amp;type=ENFORCEMENT_ACTION</a>
FAIRFIELD	GREENFIELD HILL SERVICE	1865 BRONSON RD FAIRFIELD, CT 06824	Closed	5/9/2014	A review of DEP records indicates that we do not have a registration form with current information.. NOV archived by Lori Saliby on 6/9/14	1	WELLNER	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157303&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157303&amp;type=ENFORCEMENT_ACTION</a>
CHESTER	WEST MAIN STREET SERVICES INC.	100 W MAIN ST CHESTER, CT 06412	Closed	10/9/2013	The monthly release detection test documentation from the automatic tank gauging device was not available. . This NOV was clsd by Kelly McShea on 10/24/13 as part of the NOV followup project.	2	WEST MAIN STREET SERVICES INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142271&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142271&amp;type=ENFORCEMENT_ACTION</a>
NORWALK	SHELL SERVICE STATION	94 WEST AVE NORWALK, CT 06854	Closed	2/26/2014	The Department's inspector has determined that there is liquid or evidence of liquid accumulating in sump.. Per CMI UST Monitoring Certification 6/9/14, liquid was not found in any secondary containment system designed as a dry system, all equipment/alarm/sensors working properly, product lines tested tight, lld test passed, and in-tank monitor inspection operational,	3	WHOLESALE FUEL DISTRIBUTORS CT, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150680&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150680&amp;type=ENFORCEMENT_ACTION</a>
GREENWICH	SOUTH GREENWICH CONVENIENCE MART, INC.	623 W PUTNAM AVE GREENWICH, CT 06830	Closed	11/14/2013	The annual tightness test documentation was not available for the piping. . The passing annual line leak detector test documentation was not maintained.. This NOV was clsd by Kelly McShea on 12/2/13 as part of the NOV followup project	6	WHOLESALE FUEL DISTRIBUTORS, INC.	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144043&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2144043&amp;type=ENFORCEMENT_ACTION</a>

PORTLAND	37 Indian Hill Avenue	37 INDIAN HILL AVE PORTLAND, CT 06480	Closed	10/8/2013	ATG is not checking portion of the tank that routinely contains product (for most models, tank level must be at least 50%).. The monthly release detection test documentation from the automatic tank gauging device was not available. . This NOV was clsd by Kelly McShea on 10/10/13 as part of the NOV followup project	2	WILLIAM J. PETZOLD, INCORPORATED	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142167&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2142167&amp;type=ENFORCEMENT_ACTION</a>
WILTON	SCHOOL BUS STORAGE GARAGE	130 SCHOOL RD WILTON, CT 06897	Closed	10/24/2013	Recd registration form 11/18/13 stating UST F2R1 was removed 8/23/10, forwarded to steu, The alarm condition was caused by an accumulation of rain water in the interstitial space of the convault, not a release of DF. The rain water leaked in through access ports where monitoring cables enter the interstitial space of the convault. Town staff removed the water from the interstitial space which terminated the alarm condition. They sealed the monitoring access points to prevent leakage of water into internal space. This is a convault tank not ust, Note: Official response from legette Brashears Environsheild CP testing was performed on 12/11/14 and that the tanks passed. They will forward report after completion. Per Lori Saliby this violation can be closed.	5	WILTON	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143003&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2143003&amp;type=ENFORCEMENT_ACTION</a>
WINDSOR	WINDSOR AVE CITGO LLC.	595 WINDSOR AVE WINDSOR, CT 06095	Closed	9/15/2014	Failure to have required financial responsibility in the required amount(s).. 10/10/14-10/10/15 PP4005275 Colony Insurance Co	1	WINDSOR AVE CITGO LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166719&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2166719&amp;type=ENFORCEMENT_ACTION</a>
Windsor	Windsor Sunoco	446 Bloomfield Ave Windsor, CT 06095	Closed	5/9/2014	Recd notification form with financial mechanism and operator training information, forwarded to steu on 9/30/14, tanks are single walled and do not have interstitial monitoring sensors. Notification form has been amended to show release detection as ATG CSLD with inventory reconciliation. Windsor LLC has retained ECS Eclipse to manage release detection and inventory reconciliation. Site submitted 12 months of ATG passing results, passing LLD and passing line tightness test results. This violation did not appear on the NOV. Voiding violation. Discussed this w Inspector Hirschfeld on 10/30/14, Windsor Ventures LLC has designated new class a & B operators for the facility. They have retained ECS Eclipse to act as their designated class a/b operators, all employees of the facility have accomplished class c training through Eclipse.	9	WINDSOR VENTURES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157692&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2157692&amp;type=ENFORCEMENT_ACTION</a>

NEW HAVEN	YALE MOTOR FREIGHT, INC.	1215 STATE ST NEW HAVEN, CT 06511	Active	6/24/2014	Failure to have required financial responsibility in the required amount(s).. The owner or operator has failed maintain the requisite testing records and has failed to provide those records the Commissioner upon request.. The release detection documentation was not available.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. The UST system is in operation or is temporarily out-of-service without the requisite designated Class A, B, and/or C Operators who have been trained and certified in accordance with an approved training program..	11	YALE MOTOR FREIGHT INC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161955&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2161955&amp;type=ENFORCEMENT_ACTION</a>
MADISON	NORTH MADISON SUNOCO	1276 DURHAM RD MADISON, CT 06443	Active	6/2/2014	Inventory volume measurements for inputs, withdrawals, and remaining amounts are not recorded each operating day and reconciled weekly as required.. The annual tightness test documentation was not available for the piping. . The monthly release detection test documentation from the automatic tank gauging device was not available. . The passing annual line leak detector test documentation was not maintained.. The tanks cathodic protection was not tested within six (6) months of installation or within the last year..	10	YELLOWDOG ENTERPRISES, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159753&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2159753&amp;type=ENFORCEMENT_ACTION</a>
NEWTOWN	EDMOND TOWN HALL	45 MAIN ST NEWTOWN, CT 06470	Closed	7/17/2014	Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Tank is no longer used, site is on gas. Needed to do a cathodic test, received passing CP for tanks dated 9/12/14	1	ZELNICK	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163247&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2163247&amp;type=ENFORCEMENT_ACTION</a>

WALLINGFORD	ZOZ 1ST LLC	68 N TURNPIKE RD WALLINGFORD, CT 06492	Closed	5/20/2014	A tank(s) was temporarily closed for 3 months or more and fill cap is not locked to prevent filling.. Cathodic protection systems require annual testing to ensure that a structure to soil test voltage reading of at least minus 0.85 volts is maintained.. Fittings were not cathodically protected.. The inspector has determined that a tank was temporarily closed and contains more than 1" of liquid and did not meet release detection requirements.. The owner or operator has failed to notify the Commissioner within thirty (30) days of changes in UST notification information.. The owner or operator has failed to submit the requisite annual UST facility notification and/or the requisite annual UST facility fee(s).. The release detection documentation was not available.. The UST system is in operation or is temporarily ... This nov issued to incorrect owner, new Nov (novust-gb14-0062) issued to correct owner (Cicillia Johnson)	18	ZOZ 1ST LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158690&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2158690&amp;type=ENFORCEMENT_ACTION</a>
AVON	FORMERLY NINO'S FOREIGN CAR SERVICE	213 W MAIN ST AVON, CT 06001	Closed	2/28/2014	Monthly records of interstitial monitoring records were not available.. The annual test documentation was not available for the piping leak monitoring equipment and devices. . The tanks cathodic protection was not tested within six (6) months of installation or within the last year.. Recd Liquid status report, all sensors normal. Recd passing 0.2 test results and passing CP test results for tanks. Recd passing line tightness test and passing LLD test results for tanks	6	ZZ Management, LLC	<a href="http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150973&amp;type=ENFORCEMENT_ACTION">http://depwebs100/pe/EaEnforcementAction.aspx?ID=2150973&amp;type=ENFORCEMENT_ACTION</a>