LIVE SYSTEM

Incident Report

Incident Number:

Number of Alarms:

Date: 2/19/2013

Time: 18:04

3013812

Shift: A

District: 19157

Exposure: 000

Station: S19

Alarm Time: 2/19/2013 18:04

Arrival Time: 2/19/2013 Controlled Time: 18:08

Cleared Time:

2/20/2013 15:53

Incident Address

Dispatch Address:

Actual Address:

W 48th ST

910 W 48TH ST

Address Type: 1 - Street address

cafeteria

Property Use: 161 - Restaurant or Insurance Carrier: Owner: Haake Common Name:

Insurance

Latitude:

Longitude:

Phone:

Incident Classification

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN,

THOMAS

Incident Type as Dispatched:

Actual Incident Type:

Mutual Aid:

11 - Structure Fire

111 - Building fire

N.- None

FDID:

State:

Incident Number:

Hazardous Materials Release:

Actions Taken:

11 - Extinguish

12 - Salvage & overhaul

81 - Incident command 82 - Notify other agencies.

21 - Search

86 - Investigate

24 - Recover body

Value - Property: Contents:

Loss - Property: 0 Contents: 0

Authorities

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN,

THOMAS

Member Making Report: TH0333

Other Authorities:

Officer In Charge: JB2149 Report Completed: Yes

Member Name:

Role:

THOMAS KIEVLAN

Incident Persons Involved

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN,

THOMAS

Person involved:		
Name: MR James W Frantze		
Address:	•	-
906 W Red Bridge RD	,	
Date Of Birth: 6/28/1940	Gender: 1 - Male	
Race: 1 - White	Ethneity:	
Involvement: 0 - Owner	Business: JJ's Restaurant	
Person Involved:		
Name: MS Megan Cramer		
Address:		•
Date Of Birth:	Gender: 2 - Female	
Race: 1 - White	Ethncity:	
Involvement:	Business:	
Person involved:		
Name: Patient 3		-
Address:	•	
Date Of Birth:	Gender:	
Race:	Ethncity:	
involvement:	Business:	
Person Involved:		
Name: Patient 4		
Address:		
Date Of Birth:	Gender:	
Race:	Ethncity:	
Involvement:	Business:	
Person Involved:		
Name: Patient 5		
Address:		
Date Of Birth:	Gender:	
Race:	Ethncity:	
nvolvement:	Business:	
Person Involved:		
Name: Patient 6	•	
Address:		
Date Of Birth:	Gender:	
Race:	Ethncity:	
nvolvement:	Business:	
Person Involved:	- 44110001	
Name: Patient 7		
Address:	•	
Date Of Birth:	Cand	
Race:	Gender:	
1	Ethncity:	



Involvement:	Business:	
Person involved:		
Name: Patient 8		
Address:		
Date Of Birth:	Gender:	
Race:	Ethncity:	
Involvement:	Business:	
Person involved:		
Name: Patient 9		
Address:		
Date Of Birth:	Gender:	
Race:	Ethncity:	
Involvement:	Business:	
Person Involved:		
Name: Patient 10		
Address:		
Date Of Birth:	Gender:	
Race:	Ethncity:	ı
Involvement:	Business:	•
Person Involved:		
Name: Patient 11		
Address:		
Date Of Birth:	Gender:	•
Race:	Ethncity:	
Involvement:	Business:	
Person involved:		
Name: Patient 12		
Address:		
Date Of Birth:	Gender:	i
Race:	Ethncity:	ļ
Involvement:	Business:	
Person Involved:		
Name: Patient 13		
Address:		
Date Of Birth:	Gender:	
Race:	Ethncity:	
involvement:	Business:	
Person Involved:		
Name: Patient 14		
Address:	•	
Date Of Birth:	Gender:	
Race:	Ethneity:	
	-	í

Involvement: Business: Person involved: Name: Patient 15 Address: Date Of Birth: Gender: Race: Ethncity: involvement: **Business:** Person involved: Name: Patient 16 Address: Date Of Birth: Gender:

Race: **Involvement:**

Ethncity:

Business:

Person Involved: Name: Patient 17 Address: Date Of Birth:

Gender: Ethncity:

Race: involvement:

Business:

Incident Property

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN,

THOMAS

Area Of Origin: 24 - Cooking area, kitchen

Heat Source: 60 - Heat from other open flame or

smoking materials

Item First Ignited: 65 - Flammable liquid/gas -

uncontained

Material First Ignited: 11 - Natural gas

Cause of Ignition: 2 - Unintentional

Buildings: 6

Residential Units:

Acres Burned:

On Site Materials:

Human Factors	Factors Contributing to	Fire Suppression Factors
N - None	Ignition	
Age:	23 - Leak or break	
Gender:		

Incident Structure

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN,

THOMAS

Structure Type: 1 - Enclosed building

Status: 2 - In normal use

Item Contributing to Flame Spread:

Material Contributing to Flame Spread:

Fire Spread: 5 - Beyond building of origin

Main Floor -

Length: 0

Width: 0

Area: 5000

Story of Origin: 1

Floors Below Grade:

Floors Above Grade: 1

Floors Damaged -

Minor:

Significant:

Heavy:

Extreme: 1

Total:

Incident Personnel

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN, THOMAS

Personnel ID	Last Name	First Name	Rank / Position
TK1178	KIEVLAN	THOMAS	FINV
TK1178	KIEVLAN	THOMAS	FINV
FP0976	PEOPLES	FLOYD	BCA
FP0976	PEOPLES	FLOYD	BCA
PB1370	BERARDI	PAUL	DCA

Personnel Actions Taken

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN, THOMAS

Action	
81 - Incident command	
86 - Investigate	

Incident Apparatus and Resources

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN,

Unit ID	Dispatched	En- route	Arrival	Cleared Scene	Arrive Facility	Cleared Facility	in Service	in Qtrs
P32	02/19 18:05	02/19 18:07	02/19 18:09			02/19 23:25		
T07	02/19 18:05	02/19 18:07	02/19 18:09			02/19 21:07		 - -
P19	02/19 18:05	02/19 18:07	02/19 18:12			02/19 23:26		
R31	02/19 18:05	02/19 18:08	02/19 18:23			02/20 00:49		
M36	02/19 18:05	02/19 18:10	02/19 18:24			02/19 23:30		
C106	02/19 18:05	02/19 18:07	02/19 18:08			02/20 00:59		
P17	02/19 18:05	02/19 18:07	02/19 18:13			02/19 21:24		
R09	107/14 IX116 I	02/19 18:07	02/19 18:57			02/20 00:55		
C211	31) // IO I 2:II6	02/19 18:10	02/19 18:45			02/20 00:23		
A 01	02/19 18:06	02/19 18:09	02/19 18:33			02/19 21:51		
M35	BIZZIO IXIONI I	02/19 18:06	02/19 18:15	02/19 18:35	02/19 19:15	02/19 19:32		
C530	11 1 / / I G + 1 X * I 15	02/19 18:08	02/19 19:15			02/20 01:17		
M05	BIZZER STOCK	02/19 18:07	02/19 18:14	02/19 21:54	02/19 22:09	02/19 22:26		
IM71	02/19 18:07	02/19	02/19			02/19 21:18		

-		18:10	20:37		1	1 .	1	1
P09	02/19 18:0	9 02/19 18:11	02/19 18:26			02/19 21:06		
C10:	5 02/19 18:0	00/10	02/19		- 	02/17/21:00		
C10.	02/19 18:0	18:14	18:26		[02/19 21:07	ł	
T06	02/19 18:0	9 02/19 18:10	02/19 18:15			02/19 21:05		_
T02	02/19 18:09		02/19					_
P35	02/19 18:09	02/19	18:12 02/19			02/19 21:25	<u> </u>	
 	 -	18:10	18:24 02/19			02/19 21:03		
M40	02/19 18:12	18:13	18:21	02/19 18:33	02/19 18:37	02/19 18:45		,
M37	02/19 18:15	02/19 18:16	02/19 18:25	02/19 18:45	02/19 18:59	02/19 19:01		+-
M24	02/19 18:15	02/19 18:15	02/19 18:43	02/19 18:43	02/19 18:48	02/19 19:04		- -
M33	02/19 18:15	02/19	02/19	02/19 18:57	02/19 19:12	 	 	 -
M30	02/19 18:17	18:15 02/19	18:24 02/19	-		02/19 19:27	<u> </u>	
-	 	18:17	18:48 02/19	02/19 18:48	02/19 19:02	02/19 19:22	<u> </u>	
C101A	02/19 18:28	<u> </u>	18:28			02/20 00:39		
C120	02/19 18:40		02/19 18:40			02/19 23:29		†
/119	02/19 18:29		02/19 18:29			02/20 01:02		
101C	02/19 18:46	†	02/19		 	02/20 00:33		
29	02/19 18:47	02/19	18:46 02/19		 	 	<u> </u>	
 37	02/19 18:47	18:47 02/19	20:30 02/19		<u> </u>	02/19 20:50		<u> </u>
		18:48 02/19	20:30 02/19		<u> </u>	02/19 21:19		
102	02/19 18:47	18:48	20:27			02/19 21:05		
33	02/19 18:47	02/19 18:49	02/19 20:30			02/19 21:19		
11	02/19 18:47	02/19 18:48	02/19 20:28			02/19 20:50	.	
300	02/19 19:01	10.10	02/19		 			
)1	02/19 19:49	02/19	19:01 02/19			02/20 01:19		ļ
-+		19:54 02/19	20:09 02/19			02/20 15:52		
201	02/19 19:58	19:58	19:58			02/20 01:17	,	
1	02/19 20:01	02/19 20:03	02/19 20:40			02/20 00:55		<u> </u>
2	02/19 20:03		02/19 20:15			02/19 23:58		
12 (02/19 20:24	02/19	02/19			02/19 20:30		
	20/10 == ::		20:24 02/19			02/17 20:50		-
8 ()2/19 22:49		02/19 23:01			02/20 00:49		
) (12 IY / 2 44 I	02/19	02/19 23:08			02/20 00:42	-	

C212	02/19 23:56		02/19 23:56	02/20 01:16
C910	02/20 01:06		02/20 01:06	02/20 01:33
P47	02/20 03:33	02/20 03:39	02/20 04:05	02/20 06:57
T08	02/20 03:33		02/20 03:34	02/20 06:57
C100	02/20 04:31		02/20 04:31	02/20 06:34
C201	02/20 05:30	02/20 05:30	02/20 05:50	02/20 15:53
C106	02/20 06:52	02/20 06:56	02/20 06:56	02/20 07:39
T07	02/20 06:52	02/20 06:54	02/20 06:58	02/20 08:04
219	02/20 06:52	02/20 06:54	02/20 06:58	02/20 09:19
C101B	02/20 07:04	02/20 07:13	02/20 07:35	02/20 12:18
211	02/20 07:18		02/20 07:18	02/20 15:51
109	02/20 08:28	02/20 08:28	02/20 08:39	02/20 12:22
06	02/20 09:09	02/20 09:10	02/20 09:21	02/20 10:13
304	02/20 09:28	02/20 09:28	02/20 09:28	02/20 12:24
32	02/20 10:01	02/20 10:01	02/20 10:09	02/20 11:09

Apparatus Actions Taken
Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN,
THOMAS

A - 42	
Action	·
11 - Extinguish	
12 - Salvage & overhaul	
21 - Search	
32 - Provide basic life support (BLS)	
33 - Provide advanced life support (ALS)	
56 - Provide air supply	
76 - Provide water	
81 - Incident command	
86 - Investigate	
92 - Standby	

Incident Civilian Casualty
Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN,
THOMAS

Civilian Casualty: Name: MS Megan Cramer



Address:

Date Of Birth:

Gender: 2 - Female

Race: 1 - White

Ethncity:

Date and Time of Injury:

2/19/2013 18:04

Affiliation: I - Civilian

Disposition:

Cause of Injury: 5 - Caught or trapped

Severity: 5 - Death

Primary Apparent Symptom: 00 -

Primary Part of Body Injured:

Activity When

Other symptom

Injured:

1 - Escaping

Location at Time of Incident: 3 - Not in area of origin, but involved

General Location at Time of Injury: 2 - In building, but not in area of

origin

Specific Location at

Time of Injury: 10 - Assembly or sales

Story at Start: 1

Story Where Injured: 1

area, other

Factors Contributing To Injury:

41 - Roof collapse

Human Factors:

Incident Narrative

Incident: 2013-3013812-000 Version 3 of 3 Saved On: 2/28/2013 2:13:22 PM by KIEVLAN, THOMAS

Title: CAD Narrative

Type: 0 - CAD

Author:

Narrative Text:

P32

Title:

Type: 1 - Incident

Author: TREVOR HOUGHTON

Narrative Text:

Companies were dispatched to a structure fire and observed an extremely large column of smoke from the station. On arrival there was evidence of an apparent explosion, a large body of fire and very little of the original fire building (JJ's Restaurant) standing. The fire extended upwards more than 100 feet from the roofline of the fire building and was impinging on a 5 story building to the North/C exposure. The East/B exposure was a 2 story doctor's office/spa. It sustained structural damage from the blast and eventually had fire on 2 floors. Occaisionally blue flames were visible eminating from the ground on the West side of the building, indicating natural gas leaking from the ground. Companies found victims of the blast in front of the restaurant lying on the ground or in the process of self-extricating. Witnesses told crews of more victims inside the restaurant, but none were found using a quck search of the collapsing structure. Victims were moved across the street where a medical sector was set up. M36 had responded from their post at Station 19 and was Medical Sector. BC Baker assumed command, ordered a working fire response and filled out the first alarm, ordered police for traffic and ordered C120 as Medical Sector officer followed by a request for a PD for traffic, and a second alarm. Comapanies immediately caught a hydrant and set up for handline and flypipe operations to the original fire building, while M36 and P32 provided medical assistance to victims. Companies entered the C-side exposure and found sprinklers operating and fire inside the structure, those companies had no standpipe and stretched a handline from the pumper to knock fires in the building and later, using a vantage point inside the C-exposure, the original fire building. A third and eventually fourth alarm was struck. DC Grote assumed command and BC Baker was named Operations Chief. Fire was observed in the B-side exposure and P17 and R31 entered to complete a primary and secondary search and extinguish fires on two floors. P19 used used handlines to extinguish fires in the restaurant and cool off a nearby truck containing flammables that construction company reps told crews was being used on the high rise building under construction across the street. Command staff consulted restaurant employees to ascertain number and location of the missing. MGE opened the pavement in 2 locations to close a gas line that was feding the fires and hindering extinguishment. After knockdown and overhaul, companies, assisted by dogs, searched for a missing victim. Much time was spent looking for a victim without success, in deteriorating conditions. There were waist-deep holes full of water and frigid conditions, and



crews had been operating for several hours. At approximately 0200, command was terminated and all fire crews were in service, leaving police guarding the perimeter, P47 and T8 were later dispatched to oversee the site and were relieved at shift change by C106, P32 and T7. Recovery operations resumed after daylight and a victim was found

Title: Fire Investigator

Type: 1 - Incident

Author: THOMAS KIEVLAN

Narrative Text:

Upon my arrival on-scene of this incident was at a Second Alarm level having heavy fire out of the involved structure and in the middle of the street on 48th Street east of Belleview. I made contact with Deputy Chief Grote and assisted with man power status and emergency transportation of injured. This incident was upgraded to a Forth Alarm Level. This fire incident was a joint investigation to include Kansas City Police Bomb and Arson Unit; Bureau of Alcohol, Tobacco, Firearms and Explosives (ATFE) and the Kansas City Fire Department's Fire Prevention Division. EMS reported they transported 7 injured to area hospitals where some were treated and moved to other hospital do to injuries. While check hospitals it was found that 7 patients were self-transported for care to

I observed the involved structure front faced towards the south with the entire roof collapsed down into the building. I observed the west side wall was still standing and the south wall collapsed and lying on the sidewalk and on 48th Street. I observed the east wall had collapsed and the north wall was attached to the north building which received heavy fire damage above the roof line. I observed the north structure was a five-story building with heavy fire damage to the upper exterior wall with the windows out with moderate fire spread inside south side rooms. I was advised that Pumper-19 had responded prior with report of a gas leak on 48th Street and made a request to have the candles and pilot lights on the stove and hot water heater to be shut off for safety of the people inside JJ's

I observed the structure to the east with the west exterior wall façade fallen off the interior wall studs approximately over 25 feet from the south end to the north end of the structure with both the first and second floor levels damaged. I observed the large 12 story building that was under construction located on the south side and across the street had both large and small glass windows broken out or cracked to over 30 windows. I was further advised that fire debris from the explosion had landed on the top of the roof of the building. I observed the structure located to the southwest side across the street had various broken out window panes and that fire crews made force entry by breaking out the doors glass panes to make entry to ensure there was no gas inside the structure. Additional structures may have

The area fire scene was controlled by KCPD over night to allow the investigation the following morning. The investigation team returned the following morning to the scene and make contact with the owner for his information. I received information along with other information as to the located where the missing female could have been located prior to the collapse of the structure. Information lead to the bar area of the restaurant and fire crews with KCPD began to removed large fire debris and to remove other debris located the remains of a body on the center south section near the bar. A complete interior check using the cadaver dogs was completed finding no other handless of possible more individuals under the fire debris.

A contractor crew was hired to assist our investigation and fire debris along the south side of the exterior wall material was removed from the site. I made contact with the restaurant manager and when I asked him if the fire department advised him to put the flames out on the candles, stove and hot water heater? He stated that they did tell flames out and he said they only put the candles out and turn the stove off but did not turn out the pilot lights for the stove or hot water heater.

A joint determination cause from the three investigating agency's determined this was an accidental incident caused by an underground gas line being damage that produced a natural gas release outside of JJ's Restaurant with ATFE completing the written report of the incidents investigation. The scene was turned over to Missouri Public Service Regulator Gas Pipeline Safety and OSHA for fully understand of the events that led up to the explosion. Detective Luster of Police Bomb and Arson took a Dead Body report #13012160 for this incident.

Thomas F. Kievlan
Fire Investigator, 211
Fire Prevention Division

Reviewed:

Fire Version 2.11.1

LIVE SYSTEM

Incident Report

Incident Number:

Number of Alarms: 3013795

Date: 2/19/2013

Time: 16:54

Shift: A

District: 19157

Exposure: 000

Station: S19

Alarm Time: 2/19/2013 16:54

17:04

Arrival Time: 2/19/2013 Controlled Time:

Cleared Time:

2/19/2013 17:17

Incident Address

Dispatch Address:

Actual Address:

Address Type: 1 - Street address

W 48th ST Apt. e of

W 48th ST Apt. e of

Property Use: 161 - Restaurant or Insurance Carrier:

Common Name:

cafeteria

Phone:

Latitude:

Longitude:

Incident Classification Incident: 2013-3013795-000 Version 3 of 3 Saved On: 2/22/2013 11:58:25 AM by DOWNING, RONALD

Incident Type as Dispatched:

Actual incident Type:

412 - Gas leak (natural gas or LPG)

Mutual Aid:

N - None FDID: State:

Incident Number:

Hazardous Materials Release:

Actions Taken:

86 - Investigate 92 - Standby

00 - Action taken, other

Value - Property: Contents:

Loss - Property: Contents:

Authorities .

Incident: 2013-3013795-000 Version 3 of 3 Saved On: 2/22/2013 11:58:25 AM by DOWNING,

RONALD

Member Making Report: dt0200

Other Authorities:

Officer In Charge: pj9597

Report Completed: Yes

Member Name: Role:

Incident Personnel

Incident: 2013-3013795-000 Version 3 of 3 Saved On: 2/22/2013 11:58:25 AM by DOWNING, RONALD

Personnel ID Last Name First Name Rank / Position

CAMPBELL	JAMES	lee .
JONES	PAUL	CAPT
FOSTER	WAYNE	FF
TOZIER	DONOVAN	FF
	JONES FOSTER	JONES PAUL FOSTER WAYNE

Incident Apparatus and Resources

Incident: 2013-3013795-000 Version 3 of 3 Saved On: 2/22/2013 11:58:25 AM by DOWNING, **BUNNID**

Unit ID	Dispatched	En- route	Arrival	Cleared Scene	Arrive Facility	Cleared Facility	In Service	In Qtrs
P19		02/19	02/19	 			Service	GUS
	32/13 10:54	16:58	17:04			02/19 17:17		

Incident Narrative

Incident: 2013-3013795-000 Version 3 of 3 Saved On: 2/22/2013 11:58:25 AM by DOWNING, **RONALD**

Title: CAD Narrative Type: 0 - CAD Author: **Narrative Text:** P19

Title:

Type: 1 - Incident

Author: DONOVAN TOZIER

Narrative Text:

On Tuesday, 19 February 2013 at 16:54:09, units P19 responded to an unreported incident type at W 48th ST #e of, Kansas City, MO 64112. Upon arrival a 412 - Gas leak (natural gas or LPG) incident was found.

The primary property use is 161 - Restaurant or cafeteria.

Unit P19, the first arriving unit, arrived at 17:04:37. The last unit on scene, P19, cleared the scene at 17:17:00.

Actions taken by the primary responding units were: 86 - Investigate; 92 - Standby and 00 - Action taken, other.

A total of 1 apparatus and 4 personnel responded to this call.

Upon arrival we were met by construction workers who informed us that they punctured a gas line causing a steady leak. We asked if MGE was notified and they confirmed that they were. We then entered JJ's restaurant to warn managment of the situation with the gas leak. Upon entrance of restaurant we could smell gas and told managment to put out all ignition sources in the kitchen and throughout the establishment. Staff started to extinguish all candles on tables and the manager informed us that they were shutting down the kitchen and all ignition sources. Mge arrived on the scene and they inspected the gas leak and informed us that equipment was on the way. We asked MGE what he needed us to do, and he stated that the equipment was coming from Raymore and that he had the situation under control. He then advised us that we could leave the scene with him. We then entered JJ's again to notify them that gas service had equipment on the way but it may be a little while before the leak would be fixed. We stressed again that JJ's management should keep all ingition sources off, and should wait for MGE to notify them of an all clear. We then cleared the scene leaving it with MGE.

LIVE SYSTEM

Incident Report

Incident Number:

3013800

Number of Alarms:

Date: 2/19/2013

Time: 17:08

Shift: A

District: 19190

Exposure: 000

Station: S19

Alarm Time: 2/19/2013 17:08

17:14

Arrival Time: 2/19/2013 Controlled Time:

Cleared Time: 2/19/2013 17:17

Incident Address

Dispatch Address:

Actual Address:

Address Type: 1 - Street address

400 W 51st ST

400 W 51st ST

Property Use: 000 - Property Use, Insurance Carrier:

Common Name:

Latitude:

Longitude:

Phone:

Incident Classification

Incident: 2013-3013800-000 Version 2 of 2 Saved On: 2/28/2013 2:17:55 PM by KIEVLAN, **THOMAS**

Incident Type as Dispatched:

Actual incident Type:

500 - Service Call, other

Mutual Aid:

N - None FDID:

State:

Incident Number:

Hazardous Materials Release:

Actions Taken:

86 - Investigate

Value - Property: Contents:

Loss - Property: Contents:

Authorities

Incident: 2013-3013800-000 Version 2 of 2 Saved On: 2/28/2013 2:17:55 PM by KIEVLAN, **THOMAS**

Member Making Report: mi8850

Other Authorities:

Officer in Charge: RK7371 **Report Completed:** Yes

Member Name: Role:

Incident Apparatus and Resources

Incident: 2013-3013800-000 Version 2 of 2 Saved On: 2/28/2013 2:17:55 PM by KIEVLAN, **THOMAS**

Unit ID	Dispatched	En- route	12-3 C K A 37 2-41	_	Arrive	—	in Service	in Qtrs
•	•		l į	I				

P32	02/19 17:09	02/19	02/19	1	I	,	1	ì
		17:11	17:14		02/19 17:17			-

Apparatus Actions Taken

Incident: 2013-3013800-000 Version 2 of 2 Saved On: 2/28/2013 2:17:55 PM by KIEVLAN, **THOMAS**

Action 86 - Investigate

Incident Narrative Incident: 2013-3013800-000 Version 2 of 2 Saved On: 2/28/2013 2:17:55 PM by KIEVLAN, **THOMAS**

Title: CAD Narrative

Type: 0 - CAD

Author:

Narrative Text:

P32

Title:

Type: 1 - Incident

Author: Matthew Lanio

Narrative Text:

On Tuesday, 19 February 2013 at 17:08:32, units P32 responded to an unreported incident type at 400 W 51st ST, Kansas City, MO 64112. Upon arrival a 500 - Service Call, other incident was found.

The primary property use is 000 - Property Use, other.

Unit P32, the first arriving unit, arrived at 17:14:18. The last unit on scene, P32, cleared the scene at 17:17:44.

Actions taken by the primary responding units were: 86 - Investigate.

A total of 1 apparatus and 4 personnel responded to this call.

Fire Version 2.11.1

Tom Kievlan

From:

Kim Gunn

Sent:

Wednesday, February 20, 2013 5:02 AM

To:

Jeff Grote; Paul Berardi

Cc:

Mitchell Mauer; Jerry Harrington; Christa Harris; Joseph Robinette; Tom Kievlan

Subject:

Nite II feb. 19/20, 2013

ADC Gunn & ADC Robinette in Comm Center

16:54 Nat gas

48th / Belleview

In Service- 17:17

P19 was sent to scene of a construction crew that struck a gas line and MGE was ordered. P19 left the scene with MGE

17:09

400 W. 51st (Pembrooke school grounds)

In service- 17:17

P32 was sent to strong odor of gas near buildings facing Loose Park, determined was from construction accident P19 was handling

1st alarm + Hazmat 18:04

910 W 48 St

on-going at shift change

Calls started on building fire and possible explosions about 48th St & Belleview

Tac 5 was assigned for fire attack

Tac 6 was assigned for EMS sector

Tac 7 was assigned for staging & evacuation of structures in vicinity

Tac 2 was not assigned but used abundantly for addition scene related communications

Tac 10 is currently assigned for continuation of search & overhaul procedures

As of this email KCFD had the presence of over 50 vehicles on this scene including 11 Pumpers, 3 Rescues, 5 Trucks, Hazmat71, Support 75 (rescue division), 2 command vans, air1 & various other chief and support vehicles.

ATF will have this exact report.

Kimberly Gunn Assistant Division Chief **KCFD Emergency Communications** 6750 Eastwood Trfwy KCMO 64129 816-922-6219