

Facility Name: Lafayette Academy-V. Keeler (Demo-Reno Contractor)  
City: New Orleans Parish: Orleans  
Date: 3/22/2017 Reason: Inspection

AI: 99938, 8555  
Photographer: L. Maloan  
Other ID #:




Photo #: 4 of 5

Description: A bag pulled from inside containment. According to the on-site supervisor, the generator labels inside the bags were crumpled and unreadable at the time of inspection due to the water inside the bags.



Facility Name: Lafayette Academy-V. Keeler (Demo-Reno Contractor)  
City: New Orleans Parish: Orleans  
Date: 3/22/2017 Reason: Inspection


AI: 99938, 8555  
Photographer: L. Maloan  
Other ID #:



Photo #: 5 of 5

Description: Negative pressure units were not fully functional.





Google Earth

